



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 4394U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,449.95	-
2	REAR BUMPER BRACKETS (CONSISTENT)	SERVICEABLE	124.20	-
2	REAR BUMPER RETAINERS (CONSISTENT)	SERVICEABLE	220.70	-
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	98.40	-
1	REAR BUMPER REVERSE SENSOR WIRING (CONSISTENT)	SERVICEABLE	455.90	-
1	SET REAR BUMPER CLIPS (CONSISTENT)	NOT NECESSARY	40.00	-
1	SIDE BUMPER RH (CONSISTENT)	TO REPAIR SEE LABOUR	201.35	-
1	SIDE BUMPER RETAINER RH (CONSISTENT)	SERVICEABLE	116.10	-
			2,706.60	-
LABOUR				
	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND SIDE BUMPER RH.		800.00	180.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		600.00	300.00
	TO REMOVE, REPLACE REAR TAILGATE FITTINGS TO FACILITATE REPAIR.	NOT NECESSARY	300.00	-
	TO REMOVE, REPLACE REVERSE SENSOR.	NOT NECESSARY	150.00	-
	TO CHECK WIRING AND LIGHTINGS.		80.00	15.00
			1,930.00	495.00
GRAND TOTAL			4,636.60	495.00
RECOMMENDED COST OF REPAIRS				495.00

Report Ref No. CS/ASM21001990/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.