

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21001991/ATF3E2

Date: 15/07/2021

REFERENCE

Insured/Claimant: GIAM KAH HEAN, EDWIN

Policy No:

Date of Loss: 05/02/2021

Nature of Claim: OD Claim No: 2805842396SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SE2222L

Make & Model: AUDI A6, 1.8 TFSI S-tronic (A)

Engine No: CYG022730

Reg. Date: 03/04/2018 (Man. Year: 2017)

Chassis No: WAUZZZ4G3JN030135

Colour: Black

Odometer: 58925 km

Engine Capacity: 1798 cc

Market Value/New Car Price: S\$130,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40 R19

Rear Tyre Size: 255/40 R19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|-----------------|------------------|--------------|
| Parts | 10,213.00 | 4,013.68 | 6,199.32 | 60.70 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,952.00 | 1,602.00 | 4,350.00 | 73.08 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 16,165.00 | 5,615.68 | 10,549.32 | 65.26 |
| + GST 7.00/7.00% (S\$) | 1,131.55 | 393.10 | 738.45 | 65.26 |
| Nett Amount (S\$) | 17,296.55 | 6,008.78 | 11,287.77 | 65.26 |

INSPECTION

Date of Assignment: 10/02/2021

Date Inspected: 10/02/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 3,268.00 FS | *2,614.40 FS |
| 2 | 1 | | *REAR BUMPER FIXING PARTS | Not Necessary | 273.00 FS | *- FS |
| 3 | 1 | | *REAR BUMPER SPOILER | Deformed | 480.00 FS | *383.20 FS |
| 4 | 1 | | *REAR BUMPER SECURING STRIP | Not Necessary | 223.00 FS | *- FS |
| 5 | 2 | | *REAR BUMPER CLOSING ELEMENT - LH / RH | Not Necessary | 162.00 FS | *- FS |
| 6 | 1 | | *REAR BUMPER REINFORCEMENT | Not Necessary | 1,012.00 FS | *- FS |
| 7 | 3 | | *HEX COLLARED BOLT | Not Necessary | 24.00 FS | *- FS |
| 8 | 2 | | *REAR BUMPER REINFORCEMENT GASKET - LH / RH | Not Necessary | 28.00 FS | *- FS |
| 9 | 2 | | *REAR BUMPER TOP GUIDE SECTION - LH / RH | Not Necessary | 66.00 FS | *- FS |
| 10 | 2 | | *REAR BUMPER TOP GUIDE SECTION PIN | Not Necessary | 25.00 FS | *- FS |
| 11 | 2 | | *REAR BUMPER GUIDE PROFILE - LH / RH | Not Necessary | 134.00 FS | *- FS |
| 12 | 1 | | *REAR BUMPER CENTRE GUIDE SECTION | Not Necessary | 106.00 FS | *- FS |
| 13 | 2 | | *REAR BUMPER HOLDING STRAP - LH / RH | Not Necessary | 126.00 FS | *- FS |
| 14 | 2 | | *REVERSE SENSOR (NPA) | Not Necessary | 0.00 FS | *- FS |
| 15 | 4 | | *REVERSE SENSOR O RING | Not Necessary | 24.00 FS | *- FS |
| 16 | 1 | | *REAR LID CHROME TRIM | Not Necessary | 366.00 FS | *- FS |
| 17 | 1 | | *REAR LID ADHESIVE | Not Necessary | 19.00 FS | *- FS |
| 18 | 1 | | *AUDI EMBLEM | Not Necessary | 138.00 FS | *- FS |
| 19 | 1 | | *A6 EMBLEM | Not Necessary | 99.00 FS | *- FS |
| 20 | 1 | | *TFSI EMBLEM | Not Necessary | 99.00 FS | *- FS |
| 21 | 1 | | *REAR LID LOCK COVER | Not Necessary | 8.00 FS | *- FS |
| 22 | 1 | | *REAR LID LOCK | Not Necessary | 189.00 FS | *- FS |
| 23 | 1 | | *LED TAIL LIGHT - OUTER LH | Not Necessary | 1,258.00 FS | *- FS |
| 24 | 1 | | *LED TAIL LIGHT TRIM - OUTER LH | Not Necessary | 30.00 FS | *- FS |
| 25 | 2 | | *LED TAIL LIGHT - INNER LH | Cut | 1,258.00 FS | *1,006.40 FS |
| 26 | 1 | | *LED TAIL LIGHT TRIM - INNER LH | Not Necessary | 30.00 FS | *- FS |
| 27 | 1 | | *EXHAUST CHROME TRIM - LH | Not Necessary | 568.00 FS | *- FS |
| 28 | 1 | | *SUNDRIES | Necessary | 200.00 FS | *9.68 FS |

F=Franchise part. S=SpcNett.

Total Parts (S\$) 10,213.00 4,013.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE | New | 360.00 | 360.00 |
| 2 | TO DISMANTLE AND RENEW REAR LID AND LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 2,400.00 | 500.00 |
| 3 | TO RESPRAY REAR BUMPER, REAR LID AND LHS REAR FENDER | New | 3,000.00 | 550.00 |
| 4 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| Gross Labour Cost (\$\$) | | | 5,952.00 | 1,602.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >