

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002003/AGS3Q2
Date: 31/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900250927
Claimant Vehicle No :	SKU6240T	Insured Vehicle No :	SMQ4728P
Date of Loss:	08/02/2021	Nature of Claim:	TP
		Claim No:	1369099069SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU6240T		
Make & Model:	NISSAN ALMERA, 1.5 (A)	Engine No:	HR15973055C
Reg. Date:	05/08/2015 (Man. Year: 2014)	Chassis No:	MNTBBAN17Z0003902
Colour:	Grey	Odometer:	106466 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,457.22	4,714.02	4,743.20	50.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,570.00	1,530.00	37.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,557.22	7,284.02	6,273.20	46.27
Approved Total (Overridden) (S\$)		5,800.00		

Nett Amount (S\$)	13,557.22	5,800.00	7,757.22	57.22
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
Nett Liability (S\$)		6,600.00		

INSPECTION

Date of Assignment: 09/02/2021

Date Inspected: 09/02/2021

Estimated Period of Repair: 9.0 days

Inspected At:

Automobile Hub Enterprise
 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	864.00 FL	*864.00 FL
2	1		*REAR BOOT EMBLEM NISSAN	Necessary	62.40 FL	*62.40 FL
3	1		*REAR BOOT EMBLEM ALMERA	Necessary	68.60 FL	*68.60 FL
4	2		*REAR BOOT OUTER GARNISH	Not Necessary	257.10 FL	*- FL
5	1		*REAR BOOT INNER LOCK	Damaged	174.50 FL	*174.50 FL
6	1		*REAR BOOT INNER TRIM	Not Necessary	211.50 FL	*- FL
7	10		*REAR BOOT INNER TRIM CLIPS	Not Necessary	45.00 FL	*- FL
8	2		*REAR BOOT HINGES -L/R	Not Necessary	270.00 FL	*- FL
9	2		*REAR BOOT STOPPERS	Not Necessary	24.40 FL	*- FL
10	1		*REAR BUMPER	Distorted	570.00 FL	*570.00 FL
11	2		*REAR BUMPER PDC SENSORS	Damaged	760.05 FS	*200.00 FS
12	1		*REAR BUMPER SPONGE	Cracked	130.20 FL	*130.20 FL
13	2		*REAR BUMPER BRACKETS-L/R	Not Necessary	183.40 FL	*- FL
14	2		*REAR BUMPER SIDE BRACKETS-L/R	Not Necessary	97.80 FL	*- FL
15	2		*REAR BUMPER SIDE RETAINERS -L/R	Necessary	117.20 FL	*117.20 FL
16	1		*REAR END PANEL	Dented	498.30 FL	*498.30 FL
17	1		*REAR END PANEL GARNISH	Deformed	160.20 FL	*160.20 FL
18	1		*REAR EXHAUST SILENCER	Not Necessary	586.00 FL	*- FL
19	2		*REAR EXHAUST MOUNTINGS	Not Necessary	42.40 FL	*- FL
20	1		*REAR FLOOR BOARD	Torn	427.60 FL	*275.80 FL
21	1		*REAR FLOOR PANEL	Repair	861.90 FL	*- FL
22	1		*REAR FENDER -LH	Buckled	909.70 FL	*909.70 FL
23	2		*REAR FENDER INNER TRIMS -L/R	Not Necessary	623.00 FL	*- FL
24	10		*REAR FENDER INNER TRIM CLIPS	Not Necessary	45.00 FL	*- FL
25	2		*REAR FENDER INNER SHIELDS	Not Necessary	163.00 FL	*- FL
26	2		*REAR TAILLAMPS -L/R	Cracked	813.40 FL	*584.80 FL
27	1		*REAR TAILLAMP PANELS -L/R	N/S Dented	425.20 FL	*212.60 FL
28	1		*REAR WINDSCREEN MOULDING	Necessary	89.90 FL	*89.90 FL
29	1		*REAR SMART KEYLESS ANTENNA	Cracked	169.60 FL	*169.60 FL
30	1		*SET REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
31	1		*SET REAR NO.PLATE WITH HOLDER	Not Necessary	60.00 FS	*- FS
32	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
33	2		*SET REAR TAILLAMP CLIPS -L/R	Necessary	70.00 FS	*20.00 FS
34	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	10,346.35	5,202.80
					- List Item Discount on L Items 10.00/10.00% (\$)	889.13	488.78
					Total Parts (\$)	9,457.22	4,714.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE ,REFIX REAR SEATS ,INTERIOR TRIM TO ASSIST REPAIR	New	120.00	60.00
3	TO REMOVE ,REFIX REAR WINDSCREEN	New	180.00	120.00
4	TO REMOVE,REFIX REAR EXHAUST SYSTEMS	New	100.00	0.00
5	TO RESPRAY UNDERCOATING	New	150.00	60.00
6	TO RESPRAY PAINTING AND ETC	New	1,500.00	1,100.00
7	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	2,000.00	1,200.00
Gross Labour Cost (S\$)			4,100.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >