

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21002006/ETF3E2

Date: 12/05/2021

REFERENCE

Insured/Claimant:	DAVID FOO HEE CHEW	Policy No:	1900003272		
Date of Loss:	04/02/2021	Nature of Claim:	OD	Claim No:	7870647580SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW972E	Engine No:	G4FGJH712637
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5022784
Reg. Date:	11/01/2019 (Man. Year: 2018)	Odometer:	30855 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$71,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,658.00	19,511.20	8,146.80	29.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,510.00	11,030.00	480.00	4.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,168.00	30,541.20	8,626.80	22.03
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	38,868.00	30,241.20	8,626.80	22.20
+ GST 7.00/7.00% (S\$)	2,720.76	2,116.88	603.88	22.20
Nett Amount (S\$)	41,588.76	32,358.08	9,230.68	22.20

INSPECTION

Date of Assignment:	10/02/2021	
Date Inspected:	10/02/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	20.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*COVER-FR BUMPER	Broken	633.00 F	*633.00 FL
3	1		*CAP-FRONT HOOK	Crushed	9.00 F	*9.00 FL
4	1		*GRILLE-FRONT BUMPER	Broken	485.00 F	*485.00 FL
5	1		*COVER-FR BUMPER FOG LAMP, RH	Cut	15.00 F	*15.00 FL
6	1		*COVER-FR BUMPER FOG LAMP, LH	Not Necessary	15.00 F	*- FL
7	1		*LAMP ASSY-FRONT FOG, RH	Not Necessary	303.00 F	*- FL
8	1		*LAMP ASSY-FRONT FOG, LH	Not Necessary	303.00 F	*- FL
9	1		*LAMP ASSY-SIDE REPEATER, RH	Cut	143.00 F	*143.00 FL
10	1		*LAMP ASSY-SIDE REPEATER, LH	Not Necessary	143.00 F	*- FL
11	1		*GRILLE ASSY-RADIATOR	Broken	328.00 F	*328.00 FL
12	1		*GARNISH-RADIATOR GRILLE	Broken	38.00 F	*38.00 FL
13	1		*AIR DUCT-FR BUMPER, RH	Broken	14.00 F	*14.00 FL
14	1		*AIR DUCT-FR BUMPER, LH	Broken	14.00 F	*14.00 FL
15	1		*BRACKET-FR BUMPER UPR SIDE MTG	Broken	22.00 F	*22.00 FL
16	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 F	*- FL
17	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 F	*84.00 FL
18	1		*WIRING ASSY-BUMPER EXTENSION	Broken	207.00 F	*207.00 FL
19	4		*ULTRASONIC SENSOR ASSY - P.A.S	Not Necessary	652.00 F	*- FL
20	1		*PANEL ASSY-HOOD	Dented	1,502.00 F	*1,502.00 FL
21	1		*HINGE ASSY-HOOD, RH	Bent	43.00 F	*43.00 FL
22	1		*HINGE ASSY-HOOD, LH	Bent	43.00 F	*43.00 FL
23	1		*PANEL-FENDER, RH	Dented	430.00 F	*430.00 FL
24	1		*PANEL-FENDER, LH	Repair	430.00 F	*- FL
25	1		*BEAM COMPLETE-FR BUMPER	Dented	497.00 F	*497.00 FL
26	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 F	*675.00 FL
27	1		*BRACKET ASSY-FENDER & BUMPER, R	Broken	9.00 F	*9.00 FL
28	1		*BRACKET ASSY-FENDER & BUMPER, L	Broken	9.00 F	*9.00 FL
29	1		*BRACKET ASSY-FENDER & BPR MTG	Not Necessary	14.00 F	*- FL
30	1		*PANEL ASSY-FNDR APRON, RH	Dented	538.00 F	*538.00 FL
31	1		*PNL-FENDER APRON UPR OTR, RH	Bent	30.00 F	*30.00 FL
32	1		*PAD-HOOD INSULATING	Crushed	156.00 F	*156.00 FL
33	1		*LATCH ASSY-HOOD	Bent	103.00 F	*103.00 FL
34	1		*COVER-AFTER SERVICE, RH	Missing	11.00 F	*11.00 FL
35	1		*COVER-AFTER SERVICE, LH	Missing	11.00 F	*11.00 FL
36	1		*MOULDING-WINDSHIELD GLASS	Necessary	56.00 F	*56.00 FL
37	1		*COVER ASSY-COWL TOP	Cut	247.00 F	*247.00 FL
38	1		*GLASS-WINDSHIELD	Broken	821.00 F	*821.00 FL
39	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 F	*- FL
40	1		*GUARD ASSY-FRONT WHEEL, LH	Not Necessary	95.00 F	*- FL
41	1		*LAMP ASSY-HEAD, RH	Broken	2,210.00 F	*2,210.00 FL
42	1		*LAMP ASSY-HEAD, LH	Broken	2,210.00 F	*2,210.00 FL
43	1		*RESERVOIR & PUMP ASSY-WASHER	Crushed	146.00 F	*146.00 FL
44	1		*HORN ASSY-LOW PITCH	Broken	74.00 F	*74.00 FL
45	1		*CRASH PAD ASSY-MAIN	Broken	1,279.00 F	*1,279.00 FL
46	1		*ADJUSTER ASSY-HEIGHT	Not Necessary	37.00 F	*- FL
47	1		*S/BELT ASSY-FR RH	Jammed	317.00 F	*317.00 FL
48	1		*ADJUSTER ASSY-HEIGHT	Not Necessary	37.00 F	*- FL
49	1		*S/BELT ASSY-FR LH	Jammed	315.00 F	*315.00 FL
50	1		*MODULE ASSY-STRG WHEEL AIR BAG	Broken	922.00 F	*922.00 FL
51	1		*AIR BAG ASSY-PASSENGER	Broken	1,275.00 F	*1,275.00 FL
52	1		*MODULE ASSY-AIR BAG CONTROL	Necessary	1,025.00 F	*1,025.00 FL
53	2		*SENSOR ASSY-A TYPE CRASH	Necessary	108.00 F	*108.00 FL
54	2		*SENSOR ASSY-A TYRE CRASH	Not Necessary	108.00 F	*- FL
55	1		*TUBE ASSY-SUCTION & LIQUID	Not Necessary	668.00 F	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*HOSE-DISCHARGE	Not Necessary	122.00 F	*- FL
57	1		*CONDENSER ASSY-COOLER	Bent	687.00 F	*687.00 FL
58	1		*GUARD-AIR, RH	Broken	28.00 F	*28.00 FL
59	1		*GUARD-AIR, LH	Broken	28.00 F	*28.00 FL
60	1		*RADIATOR ASSY	Broken	646.00 F	*646.00 FL
61	1		*BLOWER ASSY	Broken	656.00 F	*656.00 FL
62	1		*FILLER NECK ASSY-RADIATOR	Broken	28.00 F	*28.00 FL
63	1		*HOSE ASSY-RADIATOR, UPR	Crushed	27.00 F	*27.00 FL
64	1		*HOSE ASSY, RADIATOR, LWR	Not Necessary	40.00 F	*- FL
65	1		*WIRING ASSY-CONTROL	Torn	966.00 F	*966.00 FL
66	1		*HOSE ASSY-OIL COOLING	Not Necessary	70.00 F	*- FL
67	1		*HOSE ASSY-OIL COOLING	Not Necessary	35.00 F	*- FL
68	1		*PIPE-DELIVERY	Bent	164.00 F	*164.00 FL
69	1		*CLEANER ASSY-AIR	Broken	174.00 F	*174.00 FL
70	1		*HOSE ASSY-AIR INTAKE	Crushed	83.00 F	*83.00 FL
71	1		*DUCT ASSY-AIR	Broken	55.00 F	*55.00 FL
72	1		*SHIELD-AIR INTAKE	Missing	9.00 F	*9.00 FL
73	1		*DUCT-EXTENSION	Missing	5.00 F	*5.00 FL
74	1		*DUCT ASSY-EXTENSION	Not Necessary	115.00 F	*- FL
75	1		*COVER ASSY-ENGINE	Cut	212.00 F	*212.00 FL
76	1		*MANIFOLD ASSY-INTAKE	Broken	906.00 F	*906.00 FL
77	1		*BODY ASSY-THROTTLE	Broken	636.00 F	*636.00 FL
78	1		*PIPE ASSY-VACUUM	Crushed	50.00 F	*50.00 FL
79	1		*HOSE ASSY-WATER A	Not Necessary	23.00 F	*- FL
80	1		*HOSE ASSY-WATER B	Crushed	23.00 F	*23.00 FL
81	1		*TUBE-FUEL FEED	Crushed	142.00 F	*142.00 FL
82	1		*CONTACT ASSY-CLOCK SPRING	Necessary	253.00 F	*253.00 FL
83	1		*HOSE ASSY-BREATHER	Not Necessary	28.00 F	*- FL
84	1		*CONTROL ASSY-COLLANT TEMPERATURE (Supplementary)	Broken	199.00 F	*199.00 FL
85	1		*PIPE-HEATER (Supplementary)	Torn	119.00 F	*119.00 FL
86	1		*SENSOR ASSY-MAP (Supplementary)	Broken	170.00 F	*170.00 FL
87	1		*SENSOR-CAMSHAFT POSITION (Supplementary)	Broken	119.00 F	*119.00 FL
88	1		*SENSOR ASSY-KNOCK (Supplementary)	Broken	108.00 F	*108.00 FL
89	1		*HOSE ASSY-VAPOR (Supplementary)	Torn	42.00 F	*42.00 FL
90	1		*CABLE ASSY-HOOD LATCH RELEASE (Supplementary)	Torn	24.00 F	*24.00 FL
91	1		*MOULDING-FRONT BUMPER,RH (Supplementary)	Broken	216.00 F	*216.00 FL
92	1		*REINF ASSY-FR BUMPER, LH (Supplementary)	Bent	15.00 F	*15.00 FL
93	1		*CLIPS (X10) (Supplementary)	Necessary	20.00 F	*20.00 FL
94	1		*RETAINER (X10) (Supplementary)	Necessary	20.00 F	*20.00 FL
95	1		*REINF ASSY-FR BUMPER RH (Supplementary)	Bent	15.00 F	*15.00 FL
96	1		*ORNAMENT-KIA NO. 115 (Supplementary)	Necessary	32.00 F	*32.00 FL
97	1		*HOSE ASSY-PCV (Supplementary)	Torn	28.00 F	*28.00 FL
98	1		*BRACKET, IU ADHESIVE (Supplementary)	Necessary	26.00 FS	*26.00 FS
99	1		*ROCKET BATTERY L2-AGN (60AH 640CCA) (Supplementary)	Broken	298.00 FS	*298.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	27,658.00	24,303.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	4,791.80
Total Parts (\$)	27,658.00	19,511.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT SUPPORT PANEL, FRT WHEELHOUSING RH. REPAIR FRT DOOR RH & LH, A-PILLAR RH & LH, FRT CHASSIS RH	New	3,200.00	3,200.00
2	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
3	TOP UP AIRCON GAS	New	80.00	80.00
4	FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	RENEW FUEL PIPE, LINK TO REAR	New	400.00	400.00
8	REMOVE & INSTALL FRT CROSSMEMBER TO FACILITATE RENEW FUEL PIPE	New	400.00	400.00
9	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
10	RENEW FRT WINDSCREEN	New	240.00	240.00
11	APPLY SEALANT FOR FRT WINDSCREEN	New	80.00	80.00
12	APPLY FRONT WINDSCREEN SOLAR FILM	New	220.00	220.00
13	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	80.00
14	RENEW INTAKE MANIFOLD & THROTTLE BODY	New	400.00	400.00
15	RENEW AIRBAGS AND SEAT BELTS	New	400.00	400.00
16	RENEW DASHBOARD & AIRBAG SENSOR	New	400.00	400.00
17	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH, FRONT DOOR RH & LH. A-PILLAR RH & LH, FRT CHASSIS RH & LH FRT WHEEL ALIGNMENT RH	New	4,800.00	4,320.00
18	REPAIR FRONT CHASSIS (Supplementary)	New	450.00	450.00
Gross Labour Cost (\$\$)			11,510.00	11,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >