



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

o Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
DAVID FOO HEE CHEW  37 HOUGANG AVE 7 #12-06 SINGAPORE 538803  Contact No Mobile: 97897757	Cust No/Name	/DAVID FOO HEE CHEW
	Reg No/Reg Date	SJW972E / 11/01/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5022784
	Engine No	G4FGJH712637
	Make/Model	KIA/CERATO 1.6 A SR SX G335
		Colour/Trim
		CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	10/02/2021/ 12:05	Bod	442 / CocoLu	28804		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M SUNDRY							20.00
Sundry							
M SUNDRY							
WIRE ASSY MAIN -----91150M6490							3200.00
E PNT88000							
RENEW FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT SUPPORT PANEL				8 X 400			
FRT WHEELHOUSING RH							
REPAIR FRT DOOR RH & LH, A-PILLAR RH & LH, FRT CHASSIS RH							100.00
E PNT88000							
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR							80.00
M SUNDRY							
TOP UP AIRCON GAS							50.00
M SUNDRY							
FRT NUMBER PLATE WITH FRAME							3500.00
E PNT98000							
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH,				9 X 350			
FRT DOOR RH & LH, A-PILLAR RH & LH, FRT CHASSIS RH & LH							
FRT WHEELALIGNMENT RH							30.00
A 90000001							
CHECK WIRING & ELECTRICAL SYSTEM							120.00
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							400.00
A 90000001							
RENEW FUEL PIPE , LINK TO REAR							400.00
A 90000001							
REMOVE & INSTALL FRT CROSSMEMBER TO FACILITATE RENEW FUEL PIPE							60.00
E PNT88000							
REMOVE & INSTALL PARKING SENSOR							240.00
E PNT88000							
RENEW FRT WINDSCREEN							80.00
M SUNDRY							
APPLY SEALANT FOR FRT WINDSCREEN							

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

GST Reg No : MR-8500111-X

o Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
DAVID FOO HEE CHEW	Cust No/Name /DAVID FOO HEE CHEW
37 HOUGANG AVE 7	Reg No/Reg Date SJW972E / 11/01/201
#12-06	Date In/Mileage / 0
SINGAPORE 538803	Chassis No KNAF3416MK5022784
Contact No Mobile: 97897757	Engine No G4FGJH712637
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	10/02/2021/ 12:05	Bod	442 / CocoLu	28804			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								220.00
APPLY FRONT WINDSCREEN SOLAR FILM								80.00
M SUNDRY								400.00
APPLY SEALANT FOR ACCIDENT PORTION								400.00
A 90000001								400.00
RENEW INTAKE MANIFOLD & THROTTLE BODY								400.00
A 90000001								400.00
RENEW AIRBAGS AND SEAT BELTS								
A 90000001								
RENEW DASHBOARD & AIRBAG SENSOR					1.00	633.00	00.00	633.00
M COVER-FR BUMPER	BR				1.00	9.00	00.00	9.00
M CAP-FRONT HOOK	CRU				1.00	485.00	00.00	485.00
M GRILLE-FRONT BUMPER	BR (Back)				1.00	15.00	00.00	15.00
M COVER-FR BUMPER FOG LAMP,RH	CUT				1.00	15.00	00.00	15.00
M COVER-FR BUMPER FOG LAMP,LH	X				1.00	303.00	00.00	303.00
M LAMP ASSY-FRONT FOG,RH	X				1.00	303.00	00.00	303.00
M LAMP ASSY-FRONT FOG,LH	X				1.00	143.00	00.00	143.00
M LAMP ASSY-SIDE REPEATER,RH	CUT				1.00	143.00	00.00	143.00
M LAMP ASSY-SIDE REPEATER,LH	X				1.00	328.00	00.00	328.00
M GRILLE ASSY-RADIATOR	BR				1.00	38.00	00.00	38.00
M GARNISH-RADIATOR GRILLE	BR (Top cover)				1.00	14.00	00.00	14.00
M AIR DUCT-FR BUMPER,RH	BR				1.00	14.00	00.00	14.00
M AIR DUCT-FR BUMPER,LH	X				1.00	22.00	00.00	22.00
M BRACKET-FR BUMPER UPR SIDE MTG	BR (RH)				1.00	22.00	00.00	22.00
M BRACKET-FR BUMPER UPR SIDE MTG	X				1.00	84.00	00.00	84.00
M ABSORBER-FRONT BUMPER ENERGY	BR?				1.00	207.00	00.00	207.00
M WIRING ASSY-BUMPER EXTENSION	?				4.00	163.00	00.00	652.00
M ULTRASONIC SENSOR ASSY-P.A.S	?				1.00	1502.00	00.00	1502.00
M PANEL ASSY-HOOD	DD				1.00	43.00	00.00	43.00
M HINGE ASSY-HOOD,RH	BT				1.00	43.00	00.00	43.00
M HINGE ASSY-HOOD,LH	BT				1.00	430.00	00.00	430.00
P PANEL-FENDER,RH	DD				1.00	430.00	00.00	430.00
P PANEL-FENDER,LH	X R				1.00	430.00	00.00	430.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

GST Reg No : MR-8500111-X

o Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
DAVID FOO HEE CHEW	Cust No/Name /DAVID FOO HEE CHEW
37 HOUGANG AVE 7	Reg No/Reg Date SJW972E / 11/01/201
#12-06	Date In/Mileage / 0
SINGAPORE 538803	Chassis No KNAF3416MK5022784
Contact No Mobile: 97897757	Engine No G4FGJH712637
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	10/02/2021/ 12:05	Bod	442 / CocoLu	28804			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BEAM COMPLETE-FR BUMPER	DD			1.00	497.00	00.00	497.00
M	CARRIER ASSY-FRONT END MODULE	BR			1.00	675.00	00.00	675.00
M	BRACKET ASSY-FENDER & BUMPER,R	BR			1.00	9.00	00.00	9.00
M	BRACKET ASSY-FENDER & BUMPER,L	X			1.00	9.00	00.00	9.00
M	BRACKET ASSY-FENDER & BPR MTG,	?			1.00	14.00	00.00	14.00
M	PANEL ASSY-FNDR APRON,RH	DD			1.00	538.00	00.00	538.00
M	PNL-FENDER APRON UPR OTR,RH	BT			1.00	30.00	00.00	30.00
P	PAD-HOOD INSULATING	CRU			1.00	156.00	00.00	156.00
M	LATCH ASSY-HOOD	BT			1.00	103.00	00.00	103.00
M	COVER-AFTER SERVICE,RH	MIS			1.00	11.00	00.00	11.00
M	COVER-AFTER SERVICE,LH	MIS			1.00	11.00	00.00	11.00
M	MOULDING-WINDSHIELD GLASS	MIS			1.00	56.00	00.00	56.00
M	COVER ASSY-COWL TOP	CUT			1.00	247.00	00.00	247.00
M	GLASS-WINDSHIELD	BR			1.00	821.00	00.00	821.00
M	GUARD ASSY-FRONT WHEEL,RH	?			1.00	95.00	00.00	95.00
M	GUARD ASSY-FRONT WHEEL,LH	X			1.00	95.00	00.00	95.00
M	LAMP ASSY-HEAD,RH	BR			1.00	2210.00	00.00	2210.00
M	LAMP ASSY-HEAD,LH	BR			1.00	2210.00	00.00	2210.00
M	RESERVOIR & PUMP ASSY-WASHER	CRU			1.00	146.00	00.00	146.00
M	HORN ASSY-LOW PITCH	BR			1.00	74.00	00.00	74.00
M	CRASH PAD ASSY-MAIN	BR			1.00	1279.00	00.00	1279.00
M	ADJUSTER ASSY-HEIGHT	?			1.00	37.00	00.00	37.00
M	S/BELT ASSY-FR RH	Jammed			1.00	317.00	00.00	317.00
M	ADJUSTER ASSY-HEIGHT	?			1.00	37.00	00.00	37.00
M	S/BELT ASSY-FR LH	Jammed			1.00	315.00	00.00	315.00
M	MODULE ASSY-STRG WHEEL AIR BAG	BR			1.00	922.00	00.00	922.00
M	AIR BAG ASSY-PASSENGER	BR			1.00	1275.00	00.00	1275.00
M	MODULE ASSY-AIR BAG CONTROL	BR			1.00	1025.00	00.00	1025.00
P	SENSOR ASSY-A TYPE CRASH	hec			2.00	54.00	00.00	108.00
M	SENSOR ASSY-A TYPE CRASH	X			2.00	54.00	00.00	108.00
M	TUBE ASSY-SUCTION & LIQUID	?			1.00	668.00	00.00	668.00
M	HOSE-DISCHARGE	?			1.00	122.00	00.00	122.00
M	CONDENSER ASSY-COOLER	BT			1.00	687.00	00.00	687.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

o Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
DAVID FOO HEE CHEW	Cust No/Name /DAVID FOO HEE CHEW
37 HOUGANG AVE 7	Reg No/Reg Date SJW972E / 11/01/201
#12-06	Date In/Mileage / 0
SINGAPORE 538803	Chassis No KNAF3416MK5022784
Contact No Mobile: 97897757	Engine No G4FGJH712637
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	10/02/2021/ 12:05	Bod	442 / CocoLu	28804		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	GUARD-AIR,RH	BR		1.00	28.00	00.00	28.00
M	GUARD-AIR,LH	?		1.00	28.00	00.00	28.00
M	RADIATOR ASSY	BR		1.00	646.00	00.00	646.00
M	BLOWER ASSY	BR		1.00	656.00	00.00	656.00
M	FILLER NECK ASSY-RADIATOR			1.00	28.00	00.00	28.00
M	HOSE ASSY-RADIATOR,UPR	CRU		1.00	27.00	00.00	27.00
M	HOSE ASSY-RADAATOR,LWR	X		1.00	40.00	00.00	40.00
M	WIRING ASSY-CONTROL	TAI		1.00	966.00	00.00	966.00
M	HOSE ASSY-OIL COOLING			1.00	70.00	00.00	70.00
M	HOSE ASSY-OIL COOLING	?		1.00	35.00	00.00	35.00
M	PIPE-DELIVERY	BR		1.00	164.00	00.00	164.00
M	CLEANER ASSY-AIR	BR		1.00	174.00	00.00	174.00
M	HOSE ASSY-AIR INTAKE	CRU		1.00	83.00	00.00	83.00
M	HOSE ASSY-BREATH	?		1.00	28.00	00.00	28.00
M	DUCT ASSY-AIR	BR		1.00	55.00	00.00	55.00
M	SHIELD-AIR INTAKE	MIS		1.00	9.00	00.00	9.00
M	DUCT-EXTENSION	MIS		1.00	5.00	00.00	5.00
M	DUCT ASSY-EXTENSION			1.00	115.00	00.00	115.00
M	COVER ASSY-ENGINE	CUT		1.00	212.00	00.00	212.00
M	MANIFOLD ASSY-INTAKE	BR		1.00	906.00	00.00	906.00
M	BODY ASSY-THROTTLE	BR		1.00	636.00	00.00	636.00
M	PIPE ASSY-VACUUM	?		1.00	50.00	00.00	50.00
M	HOSE ASSY-WATER A	?		1.00	23.00	00.00	23.00
M	HOSE ASSY-WATER B	?		1.00	23.00	00.00	23.00
M	TUBE-FUEL FEED	?		1.00	142.00	00.00	142.00
M	CONTACT ASSY-CLOCK SPRING	REC		1.00	253.00	00.00	253.00

Estimate

Steve (CLKK)

00-AM AL

EXCROSS - ?

10/2/21, 12:00pm

P/P

Estimate

Steve (LKK)  
 00-AM AL  
 Excess - ?  
 10/2/21, 12.00pm  
 P/P

Confirm &amp; accepted by

By [Signature]  
 20 days

Nett

35,967.00

35967.00

2517.69

Total Payable

38,484.69

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.