

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002015/KGS3Q2
Date: 15/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100339505-17
Claimant Vehicle No :	SLQ5603X	Insured Vehicle No :	GW5374J
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	0422031288SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ5603X	Engine No:	3ZRB906298
Make & Model:	TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)	Chassis No:	ZSU600091583
Reg. Date:	14/07/2017 (Man. Year: 2016)	Odometer:	92631 km
Colour:	Metallic Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Maxxis 9 mm	Rear Left Side:	Maxxis 9 mm
Front Right Side:	Maxxis 9 mm	Rear Right Side:	Maxxis 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,924.21	100.00	3,824.21	97.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	330.00	370.00	52.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,624.21	430.00	4,194.21	90.70
+ GST 7.00/7.00% (S\$)	323.69	30.10	293.59	90.70

Nett Amount (S\$)	4,947.90	460.10	4,487.80	90.70
+ Loss of Use (1.0 x S\$100.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		562.10		

INSPECTION

Date of Assignment: 10/02/2021

Date Inspected: 17/02/2021

Estimated Period of Repair: 1.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Serviceable	3,478.10 FL	*- FL
2	1		*HEADLAMP LOWER BRACKET RH	Serviceable	98.00 FL	*- FL
3	1		*FRONT BUMPER	Repair	627.20 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINER LH & RH	Serviceable	230.40 FL	*- FL
5	12		*FRONT BUMPER CLIPS	Not Necessary	50.40 FL	*- FL
6	1		*FRONT FENDER COWLING RH	Serviceable	522.50 FL	*- FL
7	8		*FRONT FENDER COWLING CLIPS	Not Necessary	25.68 FL	*- FL
8	1		*TO DO CERAMIC COATING	Necessary	150.00 FS	*100.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	5,182.28 100.00
					- List Item Discount on L Items 25.00/25.00% (\$)	1,258.07 0.00
					Total Parts (\$)	3,924.21 100.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	10.00
2	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD .TO KNOCK & REAIR FRONT INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	300.00	100.00
4	TO SPRAY FRONT BUMPER	New	300.00	220.00
Gross Labour Cost (S\$)			700.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >