

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBE7595D210128

Estimate

Customer		Date:	09-02-21
Name:	Lonpac Insurance Berhad	Vehicle No:	GBE7595D
Address	Motor Claims Department	Model/Make:	Toyota Hiace
	300 Beach Road #17-04 / 07		Van Turbo 5 DR Manual
	The Concourse		Singapore 199555

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper	\$ 599.50	X
2	Bumper Clips 1 set	\$ 65.00	SN X
3	Rear Rh Bumper Bracket	\$ 202.00	X
4	Tail Lamp	\$ 365.10	X
5	Tail Lamp Panel	\$ 258.00	X
6	"Corporate" Advertisement & Artwork	\$ 450.00	400 s. Net
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	500
	To putty & spray painting & including touch up paint on accident affected ar	\$ 600.00	400
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 60.00	111x

Total Parts & Labour of estimate for damaged vehicle

\$ 3,199.60

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not authorized
nku
P/PB 1571.57
3275.

P-362.10
252
P-271.57
SN-400
L-900
P 1571.57

L/Kh - Hsiao Long

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: