

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002017/UPS3Q2**Date:** 10/05/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100032675
Claimant Vehicle No :	SJJ1996Z	Insured Vehicle No :	SGY6811Y
Date of Loss:	08/02/2021	Nature of Claim:	TP
		Claim No:	9949439801SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ1996Z	Engine No:	2AZF183881
Make & Model:	TOYOTA ESTIMA, 2.4 Aeras G (A)	Chassis No:	ACR500075218
Reg. Date:	04/09/2008 (Man. Year: 2008)	Odometer:	195396 km
Colour:	Silver		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	915.10	200.00	715.10	78.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	940.00	300.00	640.00	68.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,855.10	500.00	1,355.10	73.05
+ GST 7.00/7.00% (S\$)	129.86	35.00	94.86	73.05

Nett Amount (S\$)	1,984.96	535.00	1,449.96	73.05
+ Loss of Use (1.0 x S\$100.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		642.45		
Global Sum Settlement (S\$)		640.00		

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021

Estimated Period of Repair: 1.0 days

Inspected At:

Synergy Motor Pte Ltd (HQ)
 53 UBI AVENUE 1, #01-45 PAYA UBI INDUSTRIAL ESTATE
 Singapore 408934

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Repair	585.10 F	*- FL	
2	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 F	*- FL	
3	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS	
					Sub Total (\$\$)	915.10	200.00
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	0.00
					Total Parts (\$\$)	915.10	200.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	0.00
2	LABOUR FOR PANEL BEATING & REPLACED PARTS }	New	350.00	100.00
3	TO DISMANTLE & REPLACED REVERSE SENSOR }	New	60.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	80.00	0.00
5	TO PUTTY & SPRAY PAINTING	New	400.00	200.00
			Gross Labour Cost (S\$)	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >