

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21002021/ETD3Q2

Date: 19/03/2021

REFERENCE

Insured/Claimant:	KOH JIA HUI, VICTOR	Policy No:	7210005257	
Date of Loss:	10/02/2021	Nature of Claim:	OD	Claim No: 0640951932SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ4313B		
Make & Model:	KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)	Engine No:	G4LEKS605743
Reg. Date:	21/01/2021 (Man. Year: 2019)	Chassis No:	KNACC81CVL5365873
Colour:	White	Odometer:	775 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,626.80	4,112.80	514.00	11.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,340.00	4,470.00	870.00	16.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,966.80	8,582.80	1,384.00	13.89
+ GST 7.00/7.00% (S\$)	697.68	600.80	96.88	13.89
Nett Amount (S\$)	10,664.48	9,183.60	1,480.88	13.89

INSPECTION

Date of Assignment:	10/02/2021	
Date Inspected:	10/02/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	9.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-REAR DOOR,LH	Dented	1,542.00 FL	*1,542.00 FL
2	1		*FILM-ANTI CHIPPG LH	Necessary	15.00 FL	*15.00 FL
3	1		*TAPE-RR DR BLACK FRAME FR,LH	Necessary	11.00 FL	*11.00 FL
4	1		*TAPE-RR DR BLACK RR,LH	Necessary	9.00 FL	*9.00 FL
5	1		*MOULDING ASSY-RR DR FRAME,LH	Necessary	33.00 FL	*33.00 FL
6	1		*W/STRIP ASSY-RR DR BELT O/S LH	Not Necessary	50.00 FL	*- FL
7	1		*MOULDING ASSY-SIDE SILL,LH	Not Necessary	201.00 FL	*- FL
8	1		*MOULDING ASSY-RR DR W/LINE,LH	Not Necessary	113.00 FL	*- FL
9	1		*GARNISH ASSY-QTR SIDE,LH	Cut	144.00 FL	*144.00 FL
10	1		*MOULDING ASSY-RR BUMPER SIDE,L	Cut	15.00 FL	*15.00 FL
11	1		*BRACKET ASSY-RR BUMPER SIDE,LH	Broken	25.00 FL	*25.00 FL
12	1		*BRACKET ASSY-RR BUMPER SIDE,RH	Not Necessary	25.00 FL	*- FL
13	1		*COVER-RR BUMPER,UPR	Broken	486.00 FL	*486.00 FL
14	1		*COVER-RR BUMPER LWR	Broken	392.00 FL	*392.00 FL
15	1		*PANEL ASSY-QUARTER OUTER,LH	Dented	1,207.00 FL	*1,207.00 FL
16	1		*GLASS & MOULDING ASSY-QUARTER	Necessary	368.00 FL	*368.00 FL
17	1		*CAP ASSY-WHEEL HUB	Not Necessary	216.00 FL	*- FL
18	1		*WHEEL ASSY-ALUMINIUM	Cut	629.00 FL	*629.00 FL
19	1		*HANDLE ASSY-DOOR OUTSIDE	Cut	42.00 FL	*42.00 FL
20	1		*COVER-FR DR O/S HDL,PASSENGER	Cut	24.00 FL	*24.00 FL
21	1		*GUARD ASSY-REAR WHEEL,LH	Torn	158.00 FL	*158.00 FL
22	1		*GUARD ASSY-REAR MUD,LH	Cut	16.00 FL	*16.00 FL
23	1		*SUNDIRES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,771.00	5,136.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,144.20	1,023.20
Total Parts (\$)	4,626.80	4,112.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON LH REAR DOOR,REAR BUMPER FACE,CUT/WELD LH REAR FENDER PANEL	New	2,400.00	2,000.00
2	REMOVE AND INSTALL REAR PARKING ASSIST	New	60.00	60.00
3	REMOVE AND TRANSFER LH REAR DOOR GLASS,TRIM,MECHANISM AND OTHERS TO NEW DOOR PANEL	New	120.00	120.00
4	REMOVE AND REPLACE GLASS & MOULDING ASSY-QUARTER	New	120.00	120.00
5	APPLY GLASS & MOULDING ASSY-QUARTER SEALANT	New	60.00	60.00
6	PAINT WORK SPRAY LH REAR DOOR,LH REAR FENDER,REAR BUMPER AND AFFECTED PORTION	New	1,400.00	1,050.00
7	APPLY BODY SEALANT	New	80.00	40.00
8	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
9	PERFORM RUST PREVENTION	New	80.00	0.00
10	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
11	RENEW LH REAR WHEEL INCLUDING BALANCING	New	30.00	30.00
12	REMOVE AND INSTALL FUEL TANK ASSY	New	400.00	400.00
13	CONDUCT DIAGNOSTIC CHECK USING HI-SAN PRO TEST AND CLEAR TROUBLE CODE SUPPLEMENTARY	New	120.00	120.00
14	CONDUCT COLABRATION ON REAR RADAR SUPPLEMENTARY	New	120.00	120.00
15	REMOVE & REINSTALL REAR SEAR ASSY, REAR FLOOR BOARD, LH REAR FENDER TRIMS, & ALL OTHER ATTACHMENTS TO FACILIATE REPAIR SUPPLEMENTARY	New	120.00	120.00
16	SUPPLY & INSTALL LH REAR QUARTER GLASS SOLAR FILM - RIKECOOL SUPPLEMENTARY	New	80.00	80.00
Gross Labour Cost (\$\$)			5,340.00	4,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >