

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21002023/KPA3Q2**Date:** 20/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993661
<b>Claimant Vehicle No :</b>	SML1629M	<b>Insured Vehicle No :</b>	SMU387U
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	5691123090SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SML1629M</b>	Engine No:	4J11AD2932
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0600836
Reg. Date:	08/05/2019 (Man. Year: 2018)	Odometer:	15696 km
Colour:	Metallic Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R19	Rear Tyre Size:	225/55 R19
Front Left Side:	Toyo 9 mm	Rear Left Side:	Toyo 9 mm
Front Right Side:	Toyo 9 mm	Rear Right Side:	Toyo 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,854.00	2,987.00	2,867.00	48.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,430.00	940.00	39.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,224.00</b>	<b>4,417.00</b>	<b>3,807.00</b>	<b>46.29</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,224.00</b>	<b>3,500.00</b>	<b>4,724.00</b>	<b>57.44</b>
<b>+ Loss of Use (5.0 x S\$40.00/day) (S\$)</b>		200.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		21.40		
<b>Nett Liability (S\$)</b>		<b>3,728.85</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,700.00</b>		

INSPECTION

Date of Assignment:	10/02/2021		
Date Inspected:	16/02/2021	Inspected At:	A T Auto Consultant (HQ) B/113 Teck Whye Lane, #05-650 Singapore 680113
Estimated Period of Repair:	4.0 days		

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,098.00 F	*989.00 F
2	1		*TAILGATE LOCK	Dented	238.00 F	*238.00 F
3	1		*TAILGATE STRIKER	Repair	85.00 F	*- F
4	1		*TAILGATE INNER TRIM	Serviceable	299.00 F	*- F
5	1		*TAILGATE WINDSCREEN MOULDING	Necessary	85.00 F	*85.00 F
6	1		*TAILGATE WEATHERSTRIP	Serviceable	286.00 F	*- F
7	1		*TAILGATE EMBLEM MISUBISHI	Necessary	86.00 F	*86.00 F
8	1		*TAILGATE EMBLEM OUTLANDER	Necessary	85.00 F	*85.00 F
9	1		*TAILGATE EMBLEM MIVEC	Necessary	56.00 F	*56.00 F
10	1		*REAR BUMPER	Buckled	1,108.00 F	*873.00 F
11	1		*REAR BUMPER SIDE RETAINER LH/RH	N/S Distorted	96.00 F	*48.00 F
12	1		*REAR BUMPER LOWER LID	Dented	389.00 F	*389.00 F
13	1		*REAR BUMPER REFLECTOR LH	Serviceable	151.00 F	*- F
14	1		*REAR END PANEL	Repair	588.00 F	*- F
15	1		*REAR END PANEL TOP GARNISH	Serviceable	252.00 F	*- F
16	2		*REAR IMPACT BRACKET	Repair	126.00 F	*- F
17	1		*REMOTE KEY BUZZER	Cracked	88.00 F	*88.00 F
18	1		*REMOTE KEY BUZZER BRACKET	Repair	18.00 F	*- F
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
20	1		*SET REVERSE SENSOR	Serviceable	320.00 FS	*- FS
21	1		*SET REVERSE CAMERA	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **5,854.00**      **2,987.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	800.00	500.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	800.00	600.00
3	WIRING CHARGES	New	100.00	20.00
4	REMOVE/REFIX REVERSE SENSOR	New	100.00	50.00
5	REMOVE/REFIX REVERSE CAMERA	New	100.00	50.00
6	TRANSFER TAILGATE GLASS	New	200.00	120.00
7	TRANSFER TAILGATE COMPONENT	New	150.00	60.00
8	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	120.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>2,370.00</b>	<b>1,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >