

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG21002028/APA3Q2

Date:

05/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SMG9879G

Date of Loss: 09/02/2021

Policy No:

1900258756

Insured Vehicle No :

SMR232Z

Nature of Claim:

TP

Claim No:

8991707748SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG9879G

Make & Model: TOYOTA SIENTA, 1.5 (A)

Reg. Date: 08/01/2019 (Man. Year: 2016)

Colour: Black

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No:

2NR8638938

Chassis No:

NSP1707040637

Odometer:

120407 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Front Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Tyre Size:

205/50 R16

Rear Left Side:

Tourador 6 mm

Rear Right Side:

Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	18,854.05	6,709.62	12,144.43	64.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,320.00	3,740.00	2,580.00	40.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,174.05	10,449.62	14,724.43	58.49
Approved Total (Overridden) (S\$)		8,300.00		

Nett Amount (S\$)	25,174.05	8,300.00	16,874.05	67.03
+ Car Rental (14.0 x S\$100.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,707.45		
Global Sum Settlement (S\$)		9,700.00		

INSPECTION

Date of Assignment: 10/02/2021

Date Inspected: 10/02/2021

Estimated Period of Repair: 10.0 days

Inspected At:

Profi Automotive (KB)
 10 KAKI BUKIT ROAD 2, #01-05 FIRST EAST CENTRE
 Singapore 417868

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	647.70 FL	*647.70 FL
2	1		*REAR BUMPER RETAINER LH	Serviceable	52.30 FL	*- FL
3	1		*REAR BUMPER RETAINER RH	Necessary	52.30 FL	*52.30 FL
4	1		*REAR BUMPER OUTER BRACKET LH	Not Necessary	155.00 FL	*- FL
5	1		*REAR BUMPER OUTER BRACKET RH	Not Necessary	155.00 FL	*- FL
6	1		*REAR BUMPER INNER BRACKET LH	Not Necessary	179.00 FL	*- FL
7	1		*REAR BUMPER INNER BRACKET RH	Not Necessary	179.00 FL	*- FL
8	1		*REAR BUMPER CENTRE GARNISH	Cut	230.00 FL	*230.00 FL
9	1		*REAR BUMPER SIDE GARNISH LH	Cut	159.10 FL	*159.10 FL
10	1		*REAR BUMPER SIDE GARNISH RH	Not Necessary	159.10 FL	*- FL
11	1		*REAR BUMPER REFLECTOR LH	Cracked	87.70 FL	*87.70 FL
12	1		*REAR BUMPER REFLECTOR RH	Not Necessary	87.80 FL	*- FL
13	1		*REAR TAILGATE	Dented	1,631.10 FL	*1,288.00 FL
14	1		*REAR TAILGATE HINGE LH	Not Necessary	132.00 FL	*- FL
15	1		*REAR TAILGATE HINGE RH	Not Necessary	132.00 FL	*- FL
16	1		*REAR TAILGATE LOCK	Not Necessary	401.00 FL	*- FL
17	1		*REAR TAILGATE LOCK CATCH	Not Necessary	52.00 FL	*- FL
18	1		*REAR TAILGATE WEATHERSTRIP	Cut	465.30 FL	*329.00 FL
19	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	198.00 FL	*- FL
20	1		*REAR TAILGATE EMBLEM LOGO	Necessary	65.60 FL	*65.60 FL
21	1		*REAR TAILGATE LAMP LH	Cracked	321.40 FL	*321.40 FL
22	1		*REAR TAILGATE ABSORBER LH	Not Necessary	282.50 FL	*- FL
23	1		*REAR TAILGATE ABSORBER RH	Not Necessary	282.50 FL	*- FL
24	1		*REAR TAILGATE SWITCH OPENER	Not Necessary	265.00 FL	*- FL
25	1		*REAR TAILGATE OPENING PANEL LH LOGO	Not Necessary	277.00 FL	*- FL
26	1		*REAR TAILGATE OPENING PANEL LH BOTTOM	Not Necessary	297.00 FL	*- FL
27	1		*REAR WINDSCREEN MOULDING TOP	Necessary	64.00 FL	*64.00 FL
28	1		*REAR WINDSCREEN MOULDING BOTTOM	Necessary	64.00 FL	*64.00 FL
29	1		*REAR WINDSCREEN MOULDING LH	Necessary	57.00 FL	*57.00 FL
30	1		*REAR WINDSCREEN MOULDING RH	Necessary	57.00 FL	*57.00 FL
31	1		*REAR FENDER INNER GARNISH LH BOTTOM	Not Necessary	783.00 FL	*- FL
32	1		*REAR FENDER INNER GARNISH LH TOP	Not Necessary	265.00 FL	*- FL
33	1		*REAR FENDER INNER GARNISH LH BOTTOM POCKET	Not Necessary	208.00 FL	*- FL
34	1		*REAR END PANEL INNER	Repair	471.00 FL	*- FL
35	1		*REAR END PANEL OUTER	Dented	531.00 FL	*531.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR END PANEL TOP GARNISH	Cracked	184.50 FL	*184.50 FL
37	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	558.70 FL	*- FL
38	1		*REAR SPARE TYRE PANEL BOARD INNER COVE	Not Necessary	349.00 FL	*- FL
39	1		*FUEK TANK COVER	Repair	198.00 FL	*- FL
40	1		*REAR AXLE	Not Necessary	3,174.10 FL	*- FL
41	1		*REAR SHOCK ABSORBER LH	Not Necessary	272.20 FL	*- FL
42	1		*REAR HUB BEARING LH	Damaged	937.80 FL	*571.00 FL
43	1		*REAR SLIDING DOOR PANEL	Repair	1,518.20 FL	*- FL
44	1		*REAR SLIDING RUN CHANNEL LH	Not Necessary	465.00 FL	*- FL
45	1		*REAR DOOR LOCK LH	Not Necessary	321.00 FL	*- FL
46	1		*REAR AUTO DOOR MOTOR MODULE ASSEMBLY LH	Not Necessary	698.00 FL	*- FL
47	1		*REAR FENDER LH	Distorted	1,697.30 FL	*1,205.00 FL
48	1		*REAR FENDER AIR VENT LH	Deformed	45.00 FL	*45.00 FL
49	1		*REAR FENDER INNER TRIM LH	Not Necessary	721.00 FL	*- FL
50	1		*REAR FENDER INNER SHIELD LH	Torn	265.00 FL	*265.00 FL
51	1		*REAR TAIL LAMP LH	Cracked	457.20 FL	*457.20 FL
52	1		*REAR FENDER QUARTER GLASS MOULDING LH	Necessary	201.00 FL	*201.00 FL
53	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
54	1		*SET REAR TAILGATE INNER TRIM CLIP	Not Necessary	40.00 FS	*- FS
55	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	40.00 FS	*30.00 FS
56	1		*SET REAR REVERSE SENSOR	Not Necessary	400.00 FS	*- FS
57	1		*RIM	Cut	700.00 FS	*500.00 FS
58	1		*BTL BRAKE FLUID	Necessary	60.00 FS	*40.00 FS
59	1		*JOINT SEALANT	Necessary	120.00 FS	*80.00 FS
60	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
61	1		*REAR SLIDE RAIL COVER LH	Cracked	420.00 FL	*420.00 FL
62	1		*REAR FENDER OUTER TRIM LH	Deformed	756.00 FL	*657.00 FL
63	1		*REAR NUMBER PLATE HOLDER	Not Necessary	20.00 FS	*- FS
64	1		*REVERSE CAMERA	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	24,525.40	8,699.50
- List Item Discount on L Items 25.00/25.00% (S\$)	5,671.35	1,989.88
Total Parts (S\$)	18,854.05	6,709.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	120.00	30.00
2	REMOVE AND RENEW REVERSE SENSORS	New	120.00	50.00
3	REMOVE ,REFIT REAR LINING ,TRIM AND GARNISH	New	250.00	80.00
4	REMOVE AND REFIT FUEL TANK	New	150.00	80.00
5	REMOVE AND REFIT TAILGATE GLASS	New	150.00	120.00
6	REMOVE AND REFIT REAR QUARTER GLASS LH	New	130.00	60.00
7	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT	New	150.00	80.00
8	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS	New	300.00	80.00
9	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	80.00
10	TRANSFER PARTS ,ATTACHMENT FROM OLD SLIDING DOOR LH TO NEW	New	200.00	0.00
11	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	2,600.00	1,500.00
12	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	1,500.00
13	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	80.00
Gross Labour Cost (S\$)			6,320.00	3,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >