

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002033/GPA3Q2

Date: 20/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700090984

Claimant
Vehicle No : SHB8065E **Insured Vehicle No :** SLV197H

Date of Loss: 08/02/2021 **Nature of Claim:** TP **Claim No:** 6453092537SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8065E	Engine No:	D4FDFH314189
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5642482
Reg. Date:	13/11/2015 (Man. Year: 2015)	Odometer:	381026 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	290.40	0.00	290.40	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	660.00	390.00	37.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,340.40	660.00	680.40	50.76
+ GST 7.00/7.00% (S\$)	93.83	46.20	47.63	50.76
Nett Amount (S\$)	1,434.23	706.20	728.03	50.76
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 10/02/2021

Date Inspected: 22/02/2021 Inspected At: Premier Automotive Services Pte Ltd (HQ)
23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S FENDER INNER SHIELD	Repair	120.00 FL	*- FL
2	1		*WHEEL COVER	Repair	116.00 FL	*- FL
3	1		*SET FRONT O/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
4	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
					Sub Total (S\$)	314.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	23.60
					Total Parts (S\$)	290.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME	New	450.00	200.00
3	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER	New	400.00	400.00
4	TO APPLY RUSTPROOFING ON REPAIRED PANELS	New	80.00	0.00
Gross Labour Cost (\$\$)			1,050.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >