

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21002039/GTD3E2

Date: 19/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900003272
Claimant Vehicle No : GBF4313R **Insured Vehicle No :** SJW972E
Date of Loss: 04/02/2021 Nature of Claim: TP Claim No: 7870647580SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF4313R**
Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2659008
Reg. Date: 01/11/2016 (Man. Year: 2016) Chassis No: JTFAT35Y00K207074
Colour: White Odometer: 132864 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/02/2021
Date Inspected: 11/02/2021 Inspected At: H.S.L. Auto Service (HQ)
1 Kaki Bukit Avenue 6 #01-02 Autobay, S417883
Singapore 417883
Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Bent	0.00 F	*- F
3	1		*FRT BUMPER	Bent	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*FRT GRILLE	Distorted	0.00 F	*- F
6	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
7	1		*FRT PANEL	Buckled	0.00 F	*- F
8	1		*FRT PANEL EMBLEM	Necessary	0.00 F	*- F
9	1		*FRT PANEL GARNISH	Distorted	0.00 F	*- F
10	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
11	1		*RADIATOR FAN ASSY	Cracked	0.00 F	*- F
12	1		*FRT LH DOOR	Repair	0.00 F	*- F
13	1		*FRT DOOR FRT PILLAR	Repair	0.00 F	*- F
14	1		*STICKER	Necessary	0.00 F	*- F
15	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
16	1		*REAR NUMBER PLATE BRACKET	Distorted	0.00 F	*- F
17	1		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F
18	1		*REAR END PANEL	Repair	0.00 F	*- F
19	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
20	1		*REAR LH TAILLAMP BRACKET	Bent	0.00 F	*- F
21	1		*REAR LH DOOR	Repair	0.00 F	*- F
22	1		*REAR RH DOOR	Repair	0.00 F	*- F
23	1		*SPARE TYRE LOCKING CHAIN	Distorted	0.00 F	*- F
24	1		*SPARE TYRE BRACKET	Distorted	0.00 F	*- F
25	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
26	1		*REAR EXHAUST MOUNTING	Distorted	0.00 F	*- F
27	1		*REAR LH CHASSIS MEMBER	Repair	0.00 F	*- F
28	1		*REAR RH CHASSIS MEMBER	Repair	0.00 F	*- F
29	1		*REAR NUMBER PLATE LAMP BRACKET	Bent	0.00 F	*- F
30	1		*REAR LH MUDGUARD	Dented	0.00 F	*- F
31	1		*STICKER	Necessary	0.00 F	*- F
32	1		*REAR LH SHOCK ABSORBER	Dented	0.00 F	*- F
33	1		*REAR LH LEAF SPRING	Repair	0.00 F	*- F
34	1		*REAR RH LEAF SPRING	Repair	0.00 F	*- F
35	1		*COOL BOX REAR LOWER FRAME	Dented	0.00 F	*- F
36	1		*REAR LH CHASSISWOODEN	Cracked	0.00 F	*- F
37	1		*REAR RH CHASSISWOODEN	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >