

ANNEX

REPAIR DETAILS (XD 4475 G)

Recommended Parts

No	Qty	Particulars	Condition	Repairer's Amount	Adjuster's Amount
1	1	Headlamp Assembly - N/s	Casing Broken	971.00	971.00
2	1	Front Side & Signal Lamp - N/s	Cracked/Broken	674.00	674.00
3	1	Headlamp Top Garnish - N/s	Grazed - To Re-paint NN	1,120.00	0.00
4	1	Front Side Bumper - N/s	Dented/Cracked	1,719.00	1,719.00
5	1	2 nd Step Board - N/s	Grazed - To Re-paint NN	2,025.00	0.00
6	1	2 nd Step Board Garnish - N/s	Holder Broken	1,184.00	1,184.00
7	1	2 nd Step Board Garnish Reflector - N/s	Grazed	32.00	32.00
8	1	1 st Step Plate Panel - N/s	Cracked/Broken	356.00	356.00
9	1	Front Wheel Front Mudguard - N/s	Grazed - To Re-paint NN	679.70	0.00
Sub-Total				8,760.70	4,936.00
Less 0%				0.00	0.00
Total Parts (S\$)				8,760.70	4,936.00

Recommended Labours

No	Particulars	Repairer's Amount	Adjuster's Amount
1	To repair left headlamp top garnish, left 2 nd step board and left front wheel front mudguard including replacement of the left front accident damaged parts.	900.00	600.00
2	To check front lightings and electrical wiring system include focusing both headlights and adjust if necessary.	80.00	50.00
3	To putty and re-spray painting on left headlamp top garnish, left front side bumper, left 2 nd step board, left 2 nd step board garnish and left front wheel front mudguard.	1,155.00	1,050.00
Total Labour (S\$)		2,135.00	1,700.00
Total Repair Cost (S\$)		10,895.70	6,636.00

Adjusted Repair Cost (Part by Part basis)	S\$6,636.00
--	--------------------

4 repair days

ANNEX

REPAIR DETAILS (XD 4475 G)

Recommended Parts

No	Qty	Particulars	Condition	Repairer's Amount	Adjuster's Amount
1	1	Headlamp Assembly - W/ signal	Casing Broken	971.00	506.80
2	1	Front Side & Signal Lamp - N/s	Cracked/Broken	674.00	
3	1	Headlamp Top Garnish - N/s	Grazed - To Re-paint	1,120.00	
4	1	Front Side Bumper - N/s	Dented/Cracked	1,719.00	652.50
5	1	2 nd Step Board - N/s	Grazed - To Re-paint	2,025.00	
6	1	2 nd Step Board Garnish - N/s	Holder Broken	1,184.00	161.60
7	1	2 nd Step Board Garnish Reflector - N/s	Grazed	32.00	32.00
8	1	1 st Step Plate Panel - N/s	Cracked/Broken	356.00	356.00
9	1	Front Wheel Front Mudguard - N/s	Grazed - To Re-paint	679.70	
Sub-Total				8,760.70	
Less 0%				0.00	
Total Parts (S\$)				8,760.70	

Recommended Labours

No	Particulars	Repairer's Amount	Adjuster's Amount
1	To repair left headlamp top garnish, left 2 nd step board and left front wheel front mudguard including replacement of the left front accident damaged parts.	900.00	400.00
2	To check front lightings and electrical wiring system include focusing both headlights and adjust if necessary.	80.00	30.00
3	To putty and re-spray painting on left headlamp top garnish, left front side bumper, left 2 nd step board, left 2 nd step board garnish and left front wheel front mudguard.	1,155.00	600.00
Total Labour (S\$)		2,135.00	

Total Repair Cost (S\$) 10,895.70

Adjusted Repair Cost (Part by Part basis)

Further review, repairer quoted the wrong model.

alex.ng@scania.com

Scania Singapore - Agent
Sin Kien Wah 6741162622

Shiau Chan (LKKAUTO)

From: Goh, Jeremy <Jeremy.Goh@aig.com>
Sent: Wednesday, 10 March 2021 12:56 PM
To: Reports (LKKAUTO)
Cc: SUR; Huey Yon (LKKAUTO)
Subject: RE: <Evaluation Report> Your Ref : 0538307605SG *Our Ref: CS3/AIG20011996/Eqd3e2-1

XLEP4X20005237724

580 w/Signal

Hi Elaine,

Thanks for the report. Can I check with you on the survey report parts.

I make reference to this below.

Mr
Scanin Singapore.

1 HEADLAMP ASSEMBLY-N/S	429.20	CASING BROKEN	971.00	971.00	429.20 each	165
1 FRONT SIDE & SIGNAL LAMP-N/S	151.70	CRACKED / BROKEN	674.00	574.00	151.70	75

5m kiam
wah

I checked with my In house surveyor. They shared that this item is supposed to be 1 item instead of 2. And also it has been inflated by the TPWS. Can confirm?

Hope to hear from you soon.

Regards

Jeremy Goh

Complex Claims Examiner – Auto Property Damage Claims
AIG Asia Pacific Insurance Pte. Ltd.

AIG Building
78 Shenton Way, Level 10
Singapore 079120
Tel +(65) 6419 1767
Jeremy.goh@aig.com | www.AIG.com.sg

97302017

Mr Chong.

Woon Meng.

If you have received this message outside of your usual work hours, I do not expect that you will read, respond to or action it until appropriate for you.

From: Elaine (LKK Auto) <report@lkkauto.com>
Sent: Thursday, March 4, 2021 5:02 PM
To: Goh, Jeremy <Jeremy.Goh@aig.com>
Cc: 'SUR' <sur@lkkauto.com>; 'Huey Yon (LKKAUTO)' <hueyyon@lkkauto.com>
Subject: [EXTERNAL] <Evaluation Report> Your Ref : 0538307605SG *Our Ref: CS3/AIG20011996/Eqd3e2-1

68619181 enquiry parts.

This message is from an external sender; be cautious with links and attachments.

Your Ref : 0538307605SG
Our Ref : CS3/AIG20011996/Eqd3e2-1

Dear Jeremy,

We refer to the above matter.

Enclosed herewith the evaluation report and our note of charge for your necessary action.

Shiau Chan (LKKAUTO)

From: Ng Alex <Alex.Ng@scania.com>
Sent: Monday, 22 March 2021 2:16 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: KINDLY ASSIST TO CHECK THE PARTS PRICES OF SCANIA P380CA4X2MSZ

Hi Shiau Chan,

Please find the Prices.

Kindly assist to check the parts prices of SCANIA P380CA4X2MSZ, chassis no.: XLEP4X20005237724

1. FRONT SIDE BUMPER – N/S - \$ 741.00
2. 2ND STEP BOARD GARNISH – N/S - \$ 1299.50
3. 1ST STEP PLATE PANEL – N/S - \$ 509.79

Best Regards.

Alex Ng

Parts | Scania Singapore
Phone: +65 68619181 ext 205 ; Fax: +65 6861 1650
Address: 40, Senoko Road, Singapore 758112 alex.ng@scania.com
www.scania.com.sg | www.facebook.com/scaniagroup

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Monday, 22 March 2021 2:10 PM
To: Ng Alex <Alex.Ng@scania.com>
Subject: KINDLY ASSIST TO CHECK THE PARTS PRICES OF SCANIA P380CA4X2MSZ

Dear Alex,

As spoken with you.

Kindly assist to check the parts prices of SCANIA P380CA4X2MSZ, chassis no.: XLEP4X20005237724

1. FRONT SIDE BUMPER – N/S
2. 2ND STEP BOARD GARNISH – N/S
3. 1ST STEP PLATE PANEL – N/S

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)