

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21002040/KGA3Q2  
**Date:** 17/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800133454
<b>Claimant Vehicle No :</b>	SHD232G	<b>Insured Vehicle No :</b>	SME9634G
Date of Loss:	06/02/2021	Nature of Claim:	TP
		Claim No:	4705876366SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD232G</b>	Engine No:	M9R8839C002808
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC282171
Reg. Date:	16/10/2015 (Man. Year: 2015)	Odometer:	725758 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,623.76	571.53	2,052.23	78.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	810.00	3,260.00	80.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,693.76</b>	<b>1,381.53</b>	<b>5,312.23</b>	<b>79.36</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,100.00</b>		

## Adjuster Report

	(S\$)	6,693.76	1,100.00	5,593.76	83.57
<b>+ GST 7.00/7.00% (S\$)</b>		468.56	77.00	391.56	83.57
<b>Nett Amount (S\$)</b>		<b>7,162.32</b>	<b>1,177.00</b>	<b>5,985.32</b>	<b>83.57</b>
	<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 09/02/2021

Date Inspected: 09/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd  
 No 2 Ang Mo Kio Street 63  
 Singapore 569111

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL	
2	1		*BUMPER LOWER REAR	Serviceable	411.90 FL	*- FL	
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL	
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL	
5	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL	
6	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL	
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL	
8	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL	
9	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS	
10	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS	
11	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS	
12	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Serviceable	10.00 FS	*- FS	
13	1		*SET BUMPER RETAINER RH CLIP RR	Serviceable	20.00 FS	*- FS	
14	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS	
15	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS	
					<b>Sub Total (\$)</b>	<b>2,813.40</b>	<b>627.70</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	189.64	56.17
					<b>Total Parts (\$)</b>	<b>2,623.76</b>	<b>571.53</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,500.00	440.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,500.00	300.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
			<b>Gross Labour Cost (\$\$)</b>	<b>4,070.00</b>
				<b>810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >