



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 7647R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT O/S FOOTREST BRACKET }	DAMAGED	65.00	78.00
1	FRONT O/S FOOTREST RUBBER }	NECESSARY	35.00	-
1	BRAKE PEDAL	SERVICEABLE	42.00	-
1	REAR O/S FOOTREST	INTACT	40.00	-
1	EXHAUST ASSY	SERVICEABLE	585.00	-
1	EXHAUST PROTECTOR	DAMAGED	80.00	80.00
1	REAR O/S TAILBOARD	DAMAGED	155.00	155.00
1	CHAIN COVER	SERVICEABLE	48.00	-
1	REAR O/S ORIGINAL	SERVICEABLE	65.00	-
1	REAR TAILLAMP	CRACKED	155.00	155.00
1	REAR BRAKE DISC	SERVICEABLE	175.00	-
1	REAR FENDER	DAMAGED	120.00	120.00
1	REAR RIM SHAFT	SERVICEABLE	60.00	-
1	REAR RIM HUB WITH BEARING	SERVICEABLE	238.00	-
1	SWING-ARM	SERVICEABLE	590.00	-
	LESS 10% DISCOUNT		-245.30	-58.80
			2,207.70	529.20
1	REAR RIM (SN)	DAMAGED	350.00	180.00
	LESS 10% DISCOUNT		-35.00	-
			315.00	180.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	DAMAGED	18.00	10.00
1	REAR BOX (SN)	DAMAGED	280.00	200.00
1	REAR BOX BRACKET (SN)	DAMAGED	100.00	70.00
1	SWING-ARM RUBBER (SN)	NECESSARY	75.00	75.00
1	SET STICKER (SN)	SERVICEABLE	95.00	-
			568.00	355.00

Report Ref No. CS3/LPC20002428/Gqd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	30.00
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.		380.00	200.00
	TO CHECK, REPAIR AND STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.	NOT NECESSARY	350.00	-
			860.00	260.00
	GRAND TOTAL		3,950.70	1,324.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,050.00

Report Ref No. CS3/LPC20002428/Gqd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.