

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 334B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,264.00	-
1	WING MIRROR RH	NOT NECESSARY	1,390.10	-
1	W/MIRROR OUTER COVER RH	TO REPAIR SEE LABOUR	141.90	-
	LESS 25% DISCOUNT		-699.00	-
			2,097.00	-
	NETT ITEMS			
1	FRT DOOR COMFORTDELGRO RH (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS RH (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
	SPECIAL NETT ITEMS			
1	FRT DOOR ADV.STICKER RH (SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADV.STICKER RH (SN)	NECESSARY	100.00	100.00
			200.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH AND W/MIRROR OUTER COVER RH.		400.00	350.00
	SPRAYPAINT CHARGE.		750.00	500.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	60.00	-
	TRANSFER OF DOOR.		120.00	60.00
	CHECK WIRING.	NOT NECESSARY	40.00	-
			1,370.00	910.00
	GRAND TOTAL		3,806.50	1,249.50





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,000.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC21002049/Gtf3e2

XING GUO QIANG

Automotive Assessor

M.MATAI, AMSAE-A

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.