

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21002050/TIQD3N2

Date: 18/03/2021

REFERENCE

Insured/Claimant:	LIM CHYE GUAN	Policy No:	2070043686		
Date of Loss:	09/02/2021	Nature of Claim:	OD	Claim No:	4725673914SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS8305P	Engine No:	G4FGKH751165
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416ML5058233
Reg. Date:	17/03/2020 (Man. Year: 2019)	Odometer:	8498 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,746.00	3,223.20	522.80	13.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	3,000.00	1,430.00	32.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,176.00	6,223.20	1,952.80	23.88
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	7,876.00	5,923.20	1,952.80	24.79
+ GST 7.00/7.00% (S\$)	551.32	414.62	136.70	24.80
Nett Amount (S\$)	8,427.32	6,337.82	2,089.50	24.79

INSPECTION

Date of Assignment:	11/02/2021	
Date Inspected:	17/02/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL-SIDE SILL OUTRER,RH	Bent	1,208.00 FL	*1,208.00 FL
2	1		*PANEL ASSY-FRONT DOOR,RH	Bent	1,277.00 FL	*1,277.00 FL
3	1		*BLACK TAPE-FR DR RR,RH	Necessary	13.00 FL	*13.00 FL
4	1		*BLACK TAPE-RR DR FR,RH	Necessary	13.00 FL	*13.00 FL
5	1		*BLACK TAPE-RR DR FRAME RR OTR	Necessary	8.00 FL	*8.00 FL
6	1		*PANEL ASSY-REAR DOOR,RH	Bent	1,377.00 FL	*1,377.00 FL
7	1		*HANDLE ASSY-DOOR OUTSIDE,RH	Repair	164.00 FL	*- FL
8	1		*LATCH ASSY-FRONT DOOR,RH	Not Necessary	400.00 FL	*- FL
9	1		*BASE ASSY-FR DR O/S HANDLE RH	Not Necessary	52.00 FL	*- FL
10	1		*FILM-ANTI CHIPPG RH	Necessary	27.00 FL	*27.00 FL
11	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
12	1		*MOULDING ASSY-FRT DR FRAME,RH (Supplementary)	Deformed	37.00 FL	*37.00 FL
13	1		*MOULDING ASSY-RR DR FRAME,RH (Supplementary)	Deformed	44.00 FL	*44.00 FL
					Sub Total (\$)	4,670.00 4,024.00
					- List Item Discount on L Items 20.00/20.00% (\$)	924.00 800.80
					Total Parts (\$)	3,746.00 3,223.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON RH FRONT DOOR,RH REAR DOOR,CUT/WELD RH SIDE SILL PANEL	New	2,000.00	1,400.00
2	REMOVE AND TRANSFER RH FRONT DOOR GLASS,DOOR TRIM,MECHANISM TO NEW DOOR PANEL	New	120.00	120.00
3	REMOVE AND TRANSFER RH REAR DOOR GLASS,DOOR TRIM,MECHANISM TO NEW DOOR PANEL	New	120.00	120.00
4	REMOVE AND INSTALL FLOOR CABIN CARPET,SEAT AND OTHERS ATTACHMENT TO FACILITATE REPAIR WORK	New	400.00	0.00
5	PAINT WORK SPRAY RH FRONT DOOR,RH REAR DOOR,RH SIDE SILL PANEL AND AFFECTED PORTION	New	1,400.00	1,050.00
6	APPLY BODY SEALANT ON AFFECTED PORTION	New	120.00	80.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	PERFORM RUST PREVENTION	New	120.00	80.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			4,430.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >