

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21002064/R1BS3Q2
Date: 17/05/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLA3200Y	Insured Vehicle No :	SLS9289H
Date of Loss:	06/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000611

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA3200Y		
Make & Model:	BMW 216I, 1.5 D GT LED (A)	Engine No:	35745246B38A15A
Reg. Date:	29/06/2018 (Man. Year: 2018)	Chassis No:	WBA2D920605K81056
Colour:	Black	Odometer:	64149 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,192.80	3,128.30	3,064.50	49.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,710.00	4,709.00	2,001.00	29.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,902.80	7,837.30	5,065.50	39.26
+ GST 7.00/7.00% (S\$)	903.20	548.61	354.59	39.26

Nett Amount (S\$)	13,806.00	8,385.91	5,420.09	39.26
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,821.36		

INSPECTION

Date of Assignment: 11/02/2021

Date Inspected: 23/02/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance Centre
 Singapore 159941

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2021)
Parts:	M1-MPV	BMW 216I 1.5 D GT LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA3200Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	531.00 FS	*- FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	1		*BOOTLID	Bent	1,216.40 FS	*1,216.40 FS
4	1		*REAR BUMPER CARRIER	Bent	460.40 FS	*460.40 FS
5	1		*SUPPORT	Serviceable	45.75 FS	*- FS
6	1		*RR BUMPER LH INNER SIDE GUIDE	Serviceable	61.65 FS	*- FS
7	1		*RR BUMPER RH INNER SIDE GUIDE	Serviceable	61.65 FS	*- FS
8	1		*REAR BUMPER TRIM STRIP (CHROM)	Cracked	110.55 FS	*110.55 FS
9	1		*LEFT PROTECT	Not Necessary	11.25 FS	*- FS
10	1		*RIGHT PROTEC	Not Necessary	11.25 FS	*- FS
11	1		*REAR BUMPER PANEL PRIMED (LINES PDC)	Deformed	1,050.65 FS	*1,050.65 FS
12	1		*SET MOUNTS PDC SENSOR REAR	Serviceable	61.00 FS	*- FS
13	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Serviceable	43.25 FS	*- FS
14	1		*LETTERING 216I	Necessary	64.75 FS	*64.75 FS
15	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
16	1		*PLAQUE 74MM	Necessary	71.95 FS	*71.95 FS
17	10		*BUMP STOP	Not Necessary	32.00 FS	*- FS
18	1		*REAR WINDOW (ESG)	Not Necessary	657.60 FS	*- FS
19	10		*HOOK AND LOOP FASTENER	Not Necessary	22.00 FS	*- FS
20	1		*BOOTLID SEALING	Not Necessary	144.55 FS	*- FS
21	1		*REAR LH REFLECTOR	Not Necessary	39.05 FS	*- FS
22	4		*ULTRASONIC SENSOR BLACK	Not Necessary	1,004.80 FS	*- FS
23	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.60 FS	*- FS
24	1		*(DG)CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
25	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS
26	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Not Necessary	27.85 FS	*- FS
27	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					6,192.80	3,128.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REAR BOOT LID REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC	New	2,550.00	1,700.00
2	PAINTING REAR BOOT LID ,REAR BUMPER AND TAIL END PANEL	New	2,666.00	1,730.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIR	New	271.00	230.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
5	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	150.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
7	TO REPLACE REAR WINDSCREEN GLASS	New	676.00	574.00
8	TO CONDUCT WATER LEAK TEST	New	75.00	75.00
Gross Labour Cost (\$\$)			6,710.00	4,709.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >