

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21002066/ETF3E2

Date: 08/03/2021

REFERENCE

Insured/Claimant:	ISMANI BIN KASIMI	Policy No:	1900259586		
Date of Loss:	09/02/2021	Nature of Claim:	OD	Claim No:	6793803153SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR574L		
Make & Model:	MITSUBISHI OUTLANDER, 2.4 CVT (A)	Engine No:	4J11AA2736
Reg. Date:	17/12/2019 (Man. Year: 2018)	Chassis No:	GF7W0600199
Colour:	Grey	Odometer:	33076 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,173.61	3,756.81	1,416.80	27.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	950.00	1,930.00	67.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,053.61	4,706.81	3,346.80	41.56
- Excess (S\$)	3,300.00	3,300.00	0.00	0.00
(S\$)	4,753.61	1,406.81	3,346.80	70.41
+ GST 7.00/7.00% (S\$)	332.75	98.48	234.27	70.40
Nett Amount (S\$)	5,086.36	1,505.29	3,581.07	70.41

INSPECTION

Date of Assignment:	11/02/2021	
Date Inspected:	15/02/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, FR BUMPER	Broken	851.00 FL	*851.00 FL
3	1		*EXTENSION, FR BUMPER	Cut	509.00 FL	*509.00 FL
4	10		*CLIP	Necessary	30.00 FL	*30.00 FL
5	1		*GARNISH, FR BUMPER, RH	Missing	48.00 FL	*48.00 FL
6	1		*BRACKET, FR BUMPER SIDE, RH	Broken	18.00 FL	*18.00 FL
7	1		*COVER, FR BUMPER	Cut	361.00 FL	*361.00 FL
8	1		*GARNISH, FR BUMPER SIDE	Broken	48.00 FL	*48.00 FL
9	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
10	1		*GARNISH, FR BUMPER SIDE	Broken	112.00 FL	*112.00 FL
11	1		*REINFORCEMENT, FR BUMPER	Not Necessary	490.00 FL	*- FL
12	1		*BAR, FR BUMPER GUARD	Not Necessary	130.00 FL	*- FL
13	1		*HEADLAMP ASSY, RH	Cut	1,948.00 FL	*1,948.00 FL
14	1		*LAMP ASSY, FOG, FR RH	Broken	348.00 FL	*348.00 FL
15	1		*SHIELD, FR WHEELHOUSE, RH	Torn	164.00 FL	*164.00 FL
16	1		*MOULDING, FR BUMPER, RH	Necessary	116.00 FL	*116.00 FL
17	1		*MOULDING, FR WHEEL ARCH, RH	Not Necessary	160.00 FL	*- FL
18	1		*TANK, WINDSHIELD WASHER	Not Necessary	86.00 FL	*- FL
19	1		*WHEEL, DISC RHF	Not Necessary	974.00 FL	*- FL
20	1		*CLIP, RR BUMPER (10PCS) (Supplementary)	Necessary	30.00 FL	*30.00 FL
21	1		*CLIP, ENG ROOM COVER (10 PCS) (Supplementary)	Necessary	20.00 FL	*20.00 FL
22	1		*RIVERT, FR BUMPER (6PCS) (Supplementary)	Necessary	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,713.00	4,873.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,539.39	1,116.19
Total Parts (\$\$)	5,173.61	3,756.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER. REPAIR / ALIGN RHF FENDER	New	1,800.00	450.00
2	RESPRAY FRT BUMPER & RHF FENDER	New	700.00	350.00
3	RENEW RHF SPORT RIM & TRANSFER TYRE	New	30.00	0.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	0.00
Gross Labour Cost (\$)			2,880.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >