

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002084/AQD3E2

Date: 20/12/2021

REFERENCE

Insured/Claimant: DEBY SAROJIUY D/O P K KRISHNAN
Date of Loss: 10/02/2021

Policy No:
Nature of Claim: OD Claim No: 5460593954SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKN2975U**
Make & Model: AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A) Engine No: CXS083572
Reg. Date: 29/05/2014 (Man. Year: 2014) Chassis No: WAUZZZ8V1E1032598
Colour: Bronze Odometer: 86089 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$51,800.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,508.00	12,660.08	13,847.92	52.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,934.00	8,782.00	14,152.00	61.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	49,442.00	21,442.08	27,999.92	56.63
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	47,842.00	19,842.08	27,999.92	58.53
+ GST 7.00/7.00% (S\$)	3,348.94	1,388.95	1,959.99	58.53
Nett Amount (S\$)	51,190.94	21,231.03	29,959.91	58.53

INSPECTION

Date of Assignment: 15/02/2021

Date Inspected: 11/02/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,233.00 FS	*1,786.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER COVER TRIM RH	Not Necessary	163.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Not Necessary	163.00 FS	*- FS
5	1		*FRONT BUMPER PULL STRAP LOWER	Not Necessary	206.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION	Damaged	39.00 FS	*30.48 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE RH	Missing	109.00 FS	*87.20 FS
8	1		*RADIATOR GRILLE	Not Necessary	691.00 FS	*- FS
9	1		*FRONT BUMPER TOP COVER	Not Necessary	98.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	795.00 FS	*- FS
11	1		*REINFORCEMENT BEAM FOAM FILLER PIECE	Not Necessary	137.00 FS	*- FS
12	1		*REINFORCEMENT BEAM COVER	Not Necessary	56.00 FS	*- FS
13	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIR COND STICKER	Not Necessary	8.00 FS	*- FS
15	1		*FRONT FENDER RH	Distorted	851.00 FS	*680.40 FS
16	1		*FRONT FENDER ATTACHMENTS PARTS RH	Not Necessary	39.00 FS	*- FS
17	1		*FRONT FENDER BRACKET RH	Distorted	39.00 FS	*30.72 FS
18	1		*FRONT FENDER BRACKET RH	Distorted	28.00 FS	*21.84 FS
19	1		*FRONT FENDER BRACE RH	Distorted	96.00 FS	*76.48 FS
20	1		*FRONT FENDER CLOSING ELEMENT RH	Distorted	33.00 FS	*26.16 FS
21	1		*FRONT FENDER INSULATION RH	Not Necessary	43.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER RH	Distorted	169.00 FS	*134.80 FS
23	1		*WHEEL HOUSING LINER ATTACHMENT PARTS RH	Not Necessary	89.00 FS	*- FS
24	1		*FRONT FENDER CLOSING ELEMENT RH	Not Necessary	74.00 FS	*- FS
25	1		*HEADLIGHT CONTROL UNIT RH	Not Necessary	1,116.00 FS	*- FS
26	1		*HEADLIGHT POWER MODULE RH	Not Necessary	556.00 FS	*- FS
27	1		*HEADLIGHT GAS DISCHARGE RH	Not Necessary	416.00 FS	*- FS
28	1		*HEADLIGHT HOSE RH	Not Necessary	52.00 FS	*- FS
29	1		*HEADLIGHT WASHER LIFT CYLINDER RH	Not Necessary	193.00 FS	*- FS
30	1		*HEADLIGHT WASHER LIFT CYLINDER HOSE RH	Not Necessary	182.00 FS	*- FS
31	1		*LOCK CARRIER	Not Necessary	727.00 FS	*- FS
32	1		*RADIATOR COOLANT	Not Necessary	95.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE RH	Not Necessary	25.00 FS	*- FS
34	1		*RADIATOR RH OUTER SEAL	Not Necessary	8.00 FS	*- FS
35	1		*FRONT DOOR RH	Distorted	3,039.00 FS	*2,431.20 FS
36	1		*FRONT DOOR OUTER SEAL RH	Necessary	161.00 FS	*128.40 FS
37	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
38	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
39	1		*FRONT DOOR ATTACHMENT PARTS RH	Not Necessary	241.00 FS	*- FS
40	1		*FRONT DOOR CATCH RH	Not Necessary	105.00 FS	*- FS
41	1		*FRONT WING MIRROR MOUNTING RH	Not Necessary	1,024.00 FS	*- FS
42	1		*FRONT WING MIRROR CAP RH	Not Necessary	169.00 FS	*- FS
43	1		*FRONT WINDOW SLOT SEAL RH	Not Necessary	309.00 FS	*- FS
44	1		*FRONT WINDOW GUIDE RH	Not Necessary	257.00 FS	*- FS
45	1		*FRONT DOOR HANDLE RH	Repair	374.00 FS	*- FS
46	1		*FRONT DOOR HANDLE CAP RH	Repair	117.00 FS	*- FS
47	1		*FRONT DATA PLATE FOR TYRE PRESSURE	Not Necessary	30.00 FS	*- FS
48	1		*REAR DOOR RH	Distorted	3,039.00 FS	*2,431.20 FS
49	1		*REAR DOOR OUTER SEAL RH	Necessary	161.00 FS	*128.40 FS
50	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
51	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
52	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
53	1		*REAR DOOR ATTACHMENT PARTS RH	Not Necessary	129.00 FS	*- FS
54	1		*REAR DOOR CATCH RH	Not Necessary	94.00 FS	*- FS
55	1		*FRONT ALUMINIUM RIM RH	Cut	1,166.00 FS	*932.80 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT LOWER ARM RH	Bent	373.00 FS	*298.00 FS
57	1		*FRONT WHEEL BEARING HOUSING RH	Damaged	579.00 FS	*462.80 FS
58	1		*FRONT WHEELHUB WITH BEARING RH	Damaged	478.00 FS	*382.40 FS
59	1		*FRONT WHEEL GUIDE JOINT RH	Damaged	124.00 FS	*98.80 FS
60	1		*FRONT COUPLING ROD	Not Necessary	98.00 FS	*- FS
61	1		*FRONT GAS SHOCK ABSORBER RH	Bent	259.00 FS	*206.80 FS
62	1		*ARYCLIX SEALANT	Not Necessary	180.00 FS	*- FS
63	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
64	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
65	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
66	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
67	1		*SUNDRIES	Necessary	400.00 FS	*172.00 FS
68	1		*A-PILLAR CONNECTING PLATE RH	Repair	329.00 FS	*- FS
69	1		*HEADLIGHT RH	Cracked	2,641.00 FS	*2,112.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	26,508.00	12,660.08
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
3	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
4	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY	New	1,800.00	1,800.00
5	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	0.00
6	TO PUT VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	0.00
7	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,700.00	2,000.00
8	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS FRONT FENDER TOP SUPPORT, RHS UPPER A-PILLAR, RHS REAR DOOR, DOOR HANDLES AND RHS REAR FENDER	New	6,800.00	3,700.00
9	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE / POST WHEEL ALIGNMENT TEST	New	520.00	280.00
10	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK	New	384.00	192.00
11	TO REMOVE AND TRANSFER RHS FRONT DOOR AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	700.00	560.00
Gross Labour Cost (\$\$)			22,934.00	8,782.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >