

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21002087/UVF3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBB8348K **Insured Vehicle No :** SMF3077Z
 Date of Loss: 10/02/2021 Nature of Claim: TP Claim No: CDMPG21000289

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB8348K**
 Make & Model: NISSAN URVAN, 3.0 5MT ABS AB 5DR LWB PANEL (A) Engine No: ZD30253507K
 Reg. Date: 18/05/2010 (Man. Year: 2010) Chassis No: JN1MG4E25Z0793722
 Colour: Silver Odometer: 277563 km
 Engine Capacity: 2953 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15 Rear Tyre Size: 195R15
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
 Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,069.70	5,756.72	7,312.98	55.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	2,070.00	1,910.00	47.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,049.70	7,826.72	9,222.98	54.09
Approved Total (Overridden) (S\$)		6,250.00		
(S\$)	17,049.70	6,250.00	10,799.70	63.34
+ GST 7.00/7.00% (S\$)	1,193.48	437.50	755.98	63.34
Nett Amount (S\$)	18,243.18	6,687.50	11,555.68	63.34

INSPECTION

Date of Assignment: 15/02/2021
 Date Inspected: 15/02/2021 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

3/5/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Mar 2021)	
Parts:	N/A	NISSAN URVAN 3.0 5MT ABS AB 5DR LWB PANEL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB8348K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	2,405.00 F	*1,742.00 FL
2	1		*TAILGATE OUTER HANDLE	Cracked	399.00 F	*319.00 FL
3	1		*TAILGATE INNER LOCK	Dented/Jammed	398.20 F	*354.50 FL
4	1		*TAILGATE INNER LOCK COVER	Not Necessary	145.50 F	*- FL
5	1		*TAILGATE INNER TRIM	Torn	366.20 F	*182.40 FL
6	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	35.00 F	*35.00 FL
7	1		*TAILGATE WEATHERSTRIP	Twisted	282.30 F	*180.80 FL
8	1		*TAILGATE REAR LOGO	Necessary	65.00 F	*62.50 FL
9	1		*TAILGATE URVAN STICKER	Necessary	50.00 F	*50.00 FL
10	1		*TAILGATE 3.0DTI STICKER	Necessary	52.00 F	*52.00 FL
11	1		*TAILGATE COMMONRAIL STICKER	Necessary	48.00 F	*48.00 FL
12	1		*REAR BUMPER	Distorted	715.00 F	*660.60 FL
13	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	90.00 F	*- FL
14	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
15	1		*REAR BUMPER STEP PANEL	Bent	255.00 F	*169.00 FL
16	2		*TAILLAMPS	Cracked/Broken	720.00 F	*560.00 FL
17	1		*REAR END PANEL OUTER	Badly Dented	650.20 F	*453.00 FL
18	1		*REAR END PANEL INNER	Badly Dented	899.30 F	*615.00 FL
19	1		*REAR END PANEL TOP STEEL PLATE	Bent	251.80 F	*122.00 FL
20	1		*REAR FENDER O/S	Repair	2,422.20 F	*- FL
21	1		*REAR EXHAUST	Not Necessary	988.20 F	*- FL
22	1		*REAR SPARE TYRE CARRIAGE	Not Necessary	396.80 F	*- FL
23	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
24	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
25	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
26	1		*TAILGATE 70KM/HR STICKER	Necessary	20.00 FS	*10.00 FS
27	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
28	1		*REAR FLOOR PANEL TOP WOODEN	Cracked	950.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,069.70	6,320.80
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	564.08
Total Parts (\$\$)	13,069.70	5,756.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	100.00
4	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	100.00	60.00
5	TO SPRAY RUST PROOFING	New	100.00	60.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	880.00
8	TO PUTTY & SPRAY PAINTING	New	1,600.00	900.00
Gross Labour Cost (S\$)			3,980.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >