

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21002099/Qqf3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 03/03/2021 SINGAPORE 068811 ATTN: LYNN KHONG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SKX 8432C SMH 8446Z Veh. Inspected Policy No. GA424194/1 Coverage (\$) 0.00 Claim No. S1M032MC Excess (\$) 0.00 LYNN KHONG **Assign Date** 15/02/2021 Assign From **Vehicle Particulars & Condition** 2. KIA CERATO 1.6(A) Make & Model 1591 C.C HIDDEN 2019 Engine No. Year of Reg. KNAF1416MK5025177 **GREY** Chassis No. Colour 148932 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/65 R15 YOKOHAMA 6 mm YOKOHAMA L/H Front Tyre 195/65 R15 6 mm 195/65 R15 YOKOHAMA R/H Rear Tyre 6 mm YOKOHAMA L/H Rear Tyre 195/65 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 5. **General Information** 08/02/2021 16/02/2021 (01:41 PM) Inspect Date / Time Accident Date **INFINITY CAPITAL & INSURANCE** Survey held at 38 WOODLAND CLOSE #01-08 MEGA @ WOODLAND SINGAPORE 737856 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/ASM21002099/Qqf3e2

Estimate Days of Repair

Inspected By

OI SUN PIN

5b.

K.K.LAU CPT(RET)

Asst. Automotive Assessor

ESTIMATED NORMAL PERIOD FOR REPAIR:

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days