

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002103/ETF3E2

Date: 01/04/2021

REFERENCE

Insured/Claimant:	YANG SEE JAY,SEAN	Policy No:	1900258756		
Date of Loss:	09/02/2021	Nature of Claim:	OD	Claim No:	8991707748SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR232Z	Engine No:	G4FGKH739365
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF5416ML5060000
Reg. Date:	16/12/2019 (Man. Year: 2019)	Odometer:	26554 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$87,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	NFERA 5 mm	Rear Left Side:	NFERA 5 mm
Front Right Side:	NFERA 5 mm	Rear Right Side:	NFERA 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,357.62	14,187.20	5,170.42	26.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,350.00	9,990.00	4,360.00	30.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	33,707.62	24,177.20	9,530.42	28.27
+ GST 7.00/7.00% (S\$)	2,359.53	1,692.40	667.13	28.27
Nett Amount (S\$)	36,067.15	25,869.60	10,197.55	28.27

INSPECTION

Date of Assignment:	15/02/2021	
Date Inspected:	15/02/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	15.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
3	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
4	1		*COVER-RR BUMPER FOG LAMP, LH	Not Necessary	19.00 FL	*- FL
5	1		*COVER-RR BUMPER FOG LAMP, RH	Cut	19.00 FL	*19.00 FL
6	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Not Necessary	181.00 FL	*- FL
7	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Cut	181.00 FL	*181.00 FL
8	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FL	*- FL
9	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
10	1		*STAY-RR BUMPER LH	Bent	65.00 FL	*65.00 FL
11	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
12	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 FL	*- FL
13	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 FL	*- FL
14	1		*BRACKET-RR BEAM LWR, CTR	Not Necessary	6.00 FL	*- FL
15	1		*BRACKET-RR BEAM LWR MTG	Not Necessary	6.00 FL	*- FL
16	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
17	1		*COVER-RR BUMPER UNDER, RH	Not Necessary	33.00 FL	*- FL
18	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Not Necessary	25.00 FL	*- FL
19	1		*BRACKET-ASSY RR BPR SIDE UPR, R	Broken	31.00 FL	*31.00 FL
20	1		*ULTRASONIC SENSOR ASSY-BWS (4PCS)	Shorted	652.00 FL	*163.00 FL
21	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
22	1		*HINGE ASSY-TRUNK LID, LH	Not Necessary	97.00 FL	*- FL
23	1		*HINGE ASSY-TRUNK LID, RH	Not Necessary	97.00 FL	*- FL
24	1		*TRIM ASSY-TRUNK LID	Not Necessary	202.00 FL	*- FL
25	1		*W/STRIP-TRUNK LID OPNG	Crushed	100.00 FL	*100.00 FL
26	1		*LATCH ASSY-TRUNK LID	Bent	112.00 FL	*112.00 FL
27	1		*STRIKER ASSY-TRUNK LID	Not Necessary	40.00 FL	*- FL
28	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
29	1		*EMBLEM CERATO	Necessary	28.00 FL	*28.00 FL
30	1		*EMBLEM-GT LINE	Necessary	45.00 FL	*45.00 FL
31	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
32	1		*TRIM ASSY-RR TRANSVERSE	Broken	41.00 FL	*41.00 FL
33	1		*LAMP ASSY-CENTER GARNISH	Not Necessary	690.00 FL	*- FL
34	1		*LAMP ASSY-REAR COMB INSIDE, LH	Not Necessary	608.00 FL	*- FL
35	1		*LAMP ASSY, REAR COMB INSIDE, RH	Not Necessary	608.00 FL	*- FL
36	1		*LAMP ASSY-REAR COMB OUTSIDE, LH	Cut	675.00 FL	*675.00 FL
37	1		*LAMP ASSY-REAR COMB OUTSIDE, RH	Broken	675.00 FL	*675.00 FL
38	1		*MUFFLER ASSY-REAR	Bent	757.00 FL	*757.00 FL
39	1		*GASKET-EXHAUST PIPE	Necessary	14.00 FL	*14.00 FL
40	1		*LAMP ASSY-HEAD, RH	Broken	2,210.00 FL	*2,210.00 FL
41	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
42	1		*HINGE ASSY-HOOD, LH	Not Necessary	43.00 FL	*- FL
43	1		*HINGE ASSY-HOOD, RH	Not Necessary	43.00 FL	*- FL
44	13		*CLIP-HOOD INSULATING PAD MTG	Necessary	13.00 FL	*13.00 FL
45	1		*LATCH ASSY-HOOD	Not Necessary	103.00 FL	*- FL
46	1		*PANEL-FENDER, RH	Dented	430.00 FL	*430.00 FL
47	1		*GUARD ASSY-FRONT WHEEL, RH	Crushed	95.00 FL	*95.00 FL
48	1		*RESERVOIR & PUMP ASSY-WASHER	Crushed	146.00 FL	*146.00 FL
49	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
50	1		*GRILLE-FRONT BUMPER	Broken	485.00 FL	*485.00 FL
51	1		*CAP-FRONT HOOK	Not Necessary	9.00 FL	*- FL
52	1		*GRILLE ASSY-RADIATOR	Not Necessary	328.00 FL	*- FL
53	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 FL	*- FL
54	1		*MOULDING-FRONT BUMPER, RH	Broken	216.00 FL	*216.00 FL
55	1		*LAMP ASSY-SIDE REPEATER, RH	Cut	143.00 FL	*143.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*AIR DUCT-FR BUMPER, RH	Crushed	14.00 FL	*14.00 FL
57	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
58	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
59	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
60	1		*WIRING ASSY-BUMPER EXTENSION	Torn	207.00 FL	*207.00 FL
61	4		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	652.00 FL	*- FL
62	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
63	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
64	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 FL	*- FL
65	1		*WHEEL ASSY-ALUMINIUM RH	Cut	926.00 FL	*926.00 FL
66	1		*MIRROR ASSY-OUTSIDE RR VIEW, RH	Cut	559.00 FL	*559.00 FL
67	1		*PANEL ASSY-FRONT DOOR, RH	Dented	1,277.00 FL	*1,277.00 FL
68	1		*HANDLE ASSY-DOOR OUTSIDE, RH	Cut	164.00 FL	*164.00 FL
69	1		*COVER-FR DR O/S HDL RH	Repair	14.00 FL	*- FL
70	1		*PAD-FR DR O/S HDL HINGE, RH	Not Necessary	5.00 FL	*- FL
71	1		*PAD-FR DR O/S HDL COVER, RH	Not Necessary	5.00 FL	*- FL
72	1		*MOULDING ASSY-FRT DR FRAME, RH	Necessary	72.00 FL	*72.00 FL
73	1		*W/STRIP ASSY-FR DR BELT O/S RH	Not Necessary	80.00 FL	*- FL
74	1		*BLACK TAPE-FR DR RR, RH	Necessary	13.00 FL	*13.00 FL
75	1		*PANEL ASSY-REAR DOOR, RH	Dented	1,377.00 FL	*1,377.00 FL
76	1		*BLACK TAPE-RR DR FR, RH	Necessary	13.00 FL	*13.00 FL
77	1		*BLACK TAPE-RR DR FRAME RR OTR	Necessary	8.00 FL	*8.00 FL
78	1		*MOULDING ASSY-RR DR FRAME, RH	Necessary	50.00 FL	*50.00 FL
79	1		*W/STRIP ASSY-RR DR BELT O/S RH	Not Necessary	75.00 FL	*- FL
80	1		*MOULDING ASSY-SIDE SILL, RH	Not Necessary	279.00 FL	*- FL
81	1		*COOLANT (4L)	Not Necessary	26.00 FN	*- FN
82	1		*PANEL ASSY-REAR FLOOR, RR (Supplementary)	Dented	219.00 FL	*219.00 FL
83	1		*BRACKET ASSY-SPARE TIRE MTG (Supplementary)	Necessary	15.00 FL	*15.00 FL
84	1		*REINF--RR SPARE TIRE WELL CROSS (Supplementary)	Necessary	41.00 FL	*41.00 FL
85	1		*REINF-TOWING HOOK (Supplementary)	Necessary	14.00 FL	*14.00 FL
86	1		*HOOK-TOWING (Supplementary)	Necessary	16.00 FL	*16.00 FL
87	20		*CLIP (Supplementary)	Necessary	40.00 FL	*40.00 FL
88	5		*FASTENER (Supplementary)	Necessary	5.00 FL	*5.00 FL
89	1		*MUFFLER COMPLETE-CENTER (Supplementary)	Bent	907.00 FL	*907.00 FL
90	1		*COVER-RR BUMPER UNDER, LH (Supplementary)	Broken	33.00 FL	*33.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	24,193.00	17,729.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,829.40	3,541.80
- Nett Item Discount on N Items 23.00/23.00% (\$\$)	5.98	0.00
Total Parts (\$\$)	19,357.62	14,187.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW (FRT) FRT BUMPER, BONNET, FRT SUPPORT, RHF FENDER,RHF DOOR & RHR DOOR. REPAIR / ALIGN LHF FENDER	New	3,200.00	1,800.00
2	RENEW (RR) RR BUMPER, RR END PNL & BOOTLID. REPAIR / ALIGN RR FLR PNL, LHR FENDER & RHR FENDER	New	3,200.00	2,000.00
3	RESPRAY FRT BUMPER, BONNET, LHF FENDER, RHF FENDER, RHF DOOR, RHR DOOR, RH SIDE SILL GARNISH - RR BUMPER, RR END PNL, RR FLR PNL, BOOTLID, LHR FENDER, - RHR FENDER & BOOTLID SPOILER	New	4,900.00	3,500.00
4	REMOVE & REFIT AIRCON CONDENSER & RADIATOR	New	100.00	0.00
5	TOP UP AIRCON GAS	New	80.00	0.00
6	REMOVE & REFIT RHF DOOR COMPONENT	New	120.00	120.00
7	REMOVE & REFIT RHR DOOR COMPONENT	New	120.00	120.00
8	RENEW RHF SPORT RIM & TRANSFER TYRE	New	30.00	30.00
9	TO RENEW RR EXHAUST MUFFLER ASSY	New	400.00	400.00
10	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO FACILITATE REPAIR	New	120.00	120.00
11	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
12	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
13	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
14	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	0.00
15	SUPPLY RR NUMBER PLATE WITH CASING	New	50.00	0.00
16	REMOVE & REFIT FRT PARKING ASSIST SENSOR	New	60.00	60.00
17	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
18	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	40.00
19	SUPPLY BODY PNL SEALANT	New	80.00	80.00
20	SUPPLY C&C BADGE	New	40.00	40.00
21	REPLACE REAR FLOOR PANEL (Supplementary)	New	800.00	800.00
22	REMOVE & REFIT FUEL TANK ASSY (Supplementary)	New	200.00	200.00
23	SPRAY PAINT REAR FLOOR PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			14,350.00	9,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >