

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info					
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Engine No	/YANG SEE JAY SEAN SMR232Z / 16/12/201				

Account No	Terms	Date/Time Printed	CSE	Operator	Andrew Committee (Inc.)	WIP No			
LAX00000	Credit	10/02/2021/ 18:26		261 / Edwin Caina		28874	Dicco/	Δ	nount
		Description of Goods	s / Services	and Mary Market and Comment of the C	Qty	Unit Price	DISC %		3200.00
RHF DOOR REPAIR / E PNT88000 RENEW (RI REPAIR / E PNT98000 RESPRAY F RHR DOOR -RR BUMPE	& RHR ¹ DO ALIGN LH R) RR ¹ BUM ALIGN RR FRT ¹ BUMPE , RH SIC ER , RR ¹ E	BUMPER , BONNET , FRT	SUPPORT, OOTLID //2 R & RHR /FEI	NDER SX 400 FENDER , RHF DOOR ,	x 4º0	350)		1800 2010 350	3200.00
REMOVE &	REFIT AI	RCON CONDENSER & RAD	IATOR L			7		191 198	80.0
TOP UP AI	RCON GAS							-	120.0
	REFIT RH	DOOR COMPONENT							120.0
	REFIT RH	R DOOR COMPONENT							30.0
	SPORT R	M & TRANSFER TYRE							400.00
15900099 TO RENEW PNT88000	RR EXHU	AST MUFFLER ASSY	70 5	ACTUATE DEDAID	ohoto)		en en	e :	120.00
REMOVE &	REFIT RR	FLR BOARD , TRIM & C	CARPET TO F	ACILITATE REPAIR (1"		8 8		30.00
CHECK WIR	ING ELEC	TRICAL SYSTEM & ADJUS	ST HEADLAMP	AIM					120.00
USING HI-	SCAN PRO	NOSTIC CHECK USING HI TEST erize Full Wheel Alig		IESI			, ,	20 10 10 10	120.00
Confirm & ac					ala honsa	and the	7	2 1 - W	
		and company stamp		LKK Auto Consultar the Repairer of the To resurvey before/afte To display damaged po Parts prices are subject Third party survey is one No literal modifications	following: or spray pain art(s) during of the confirmation of a "Without"	ting resurvey ition Prejudice" basis	(Identification) (Compared Linguistics) (Compared to the Compared to the Compa		

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimated is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen line.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



Co Reg No : 199405410K

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Date In/Mileage

Colour/Trim

ESTIMATE

GST Reg No : MR-8500111-X

Owner Name & Vehicle Info

Cust No/Name /YANG SEE JAY SEAN

Reg No/Reg Date SMR232Z / 16/12/201

MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000

Invoice Name & Address

AIG Asia Pacific Insurance Pte.

Chassis No KNAF5416ML5060000
Engine No G4FGKH739365
Make/Model KIA/CERATO 1.6 A GT LINE H171

SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account N	o Terms	Date/Time Prin	ted	CSE	Operator			WIP No			
AX00000	Credit	10/02/2021/ 1	8:26		261 / Edw	in Caina		28874			
		Description of	Good	s / Services			Qty	Unit Price	Disc%	Ar	nount
M SUNDRY								-			50.0
SUPPLY	FRT NUMBE	R PLATE WITH CA	SING								
M SUNDRY											50.
SUPPLY	RR NUMBER	PLATE WITH CAS	ING								
E PNT8800	•										60.
REMOVE	& REFIT F	RT PARKING ASSI	ST SE	ISOR						1	
E PNT8800	0										60.
	& REFIT RE	EVERSE SENSOR								40	120
SUNDRY										40	120
	ANTI CORROS	SION ON AFFECTE	D AREA	15	A 1	93					80
SUNDRY	1 2000000 - 0000000			_ 几!]		L ~				00
	BODY PNL S	SEALANT L	$\supset C$	\bigcirc 2771		4917	7/0)			40
SUNDRY				2011		011	110	.) 7		1	40
	C&C BADGE		コし	9001							20
SUNDRY											
Sundrie		/ BR					1.00	651.00	20.00	/	520
	R BUMPER .	- 12 R					1.00	241.00			192
COVER-R	R BUMPER L		MM				1.00		20.00		15
			cut	r			1.00		20.00		15
COVER-R	R BUMPER F	OG LAMP, RH	NAI				1.00	181.00			144
LAMP AS	21-21DE 1/	SIGNAL, LH X	CUT				1.00	181.00			144.
LAMP AS	21-21DE 1	SIGNAL, RH	CMI				1.00	207.00			165.
	BUMPER /	BWS 1 X NN					1.00	318.00	20.00	(254.
	BUMPER LH						1.00	65.00	20.00	4	52.
	BUMPER RH	- 07					1.00	65.00		/	52.
DONCKET	-RR BEAM U		(NN				1.00		20.00		7.
	-RR BEAM U	OD MTC DU	X M	N)			1.00	9.00			7.
DOLONET	OD OCAM I	up cto 1 /	W				1.00	6.00			4.
BRACKET	-RR BEAM L	UD MTC ! A /	~I				1.00	6.00			36.8
ANTENNA	ASSY-SMAR	TKEN IN Y VOIN					1.00	46.00			26.4
4 COVER-F	R BUMPER U	NDER,RH : 入					1.00	33.00 25.00			20.0
A BOACKE	ASSY-RR B	PR SIDE UPR,L	K NI	U			1.00	25.00	20.00		20.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

KIV

Co Reg No : 199405410K

ESTIMATE

	Invoice Name & Address	COTIVIATE	GST Reg No : MR-8500111-X
	AIG Asia D		Owner Name & Vehicle Info
2	AIG Asia Pacific Insurance Pte.	Cust No/Name	/YANG SEE JAY SEAN
** * **	MOTOR CLAIM DEPARTMENT	Reg No/Reg Date	SMR232Z / 16/12/201
,	78 SHENTON WAY #09-16	Date In/Mileage	/ 0
	AIG BUILDING	Chassis No	KNAF5416ML5060000
	SINGAPORE 079120	Engine No	G4FGKH739365
	Contact No 64191000	Make/Mode1	KIA/CERATO 1.6 A GT LINE H171
		Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

AVAAAA	Terms	Date/Time Print		Upe	erator		va in a second	WIP No)		
-AX00000	Credit	10/02/2021/ 18			/ Edwi	n Caina		28874	- 33 . 0		
M DD40455		Description of	Goods / Service	S			Qty	Unit Price	e Disc%		Amount
M BRACKET-	ASSY RR B	PR SIDE UPR,R	- BR				1.00	31.0	0 20.00	1	24.8
M ULTRASON	IC SENSOR	ASSY-BWS -	Short			11	A.00	163.0	0 20.00	/	521.6
M PANEL AS	SY-TRUNK	LID / 00	• 1			500 E	1.00	1297.0	20.00	/	1037.6
M HINGE AS	SY-TRUNK	LID, LH					1.00	97.0	20.00		77.6
M HINGE AS	SY-TRUNK	LID,RH					1.00	97.0	20.00	1	77.6
	Y-TRUNK L						1.00	202.00	20.00	1	161.6
	TRUNK LID		, s,				1.00	100.00	20.00	/	80.0
	SY-TRUNK						1.00	112.00	20.00	/	89.6
	ASSY-TRUNI						1.00	40.00	20.00		32.0
	Y-KIA SUB						1.00	32.00	20.00	/	25.6
	ERATO /		— —				1.00	28.00	20.00	/	22.4
	LINE /	THE NO L	- OSE	II I'	3	(0)5	7.90	45.00	20.00	/	36.0
PANEL ASS		VERSE OR		1111	1111	211	1.00		20.00		259.2
	-RR TRANS		ist	ЦЦ	υШ	(21)	(4.60)		20.00		32.8
1 LAMP ASSY							1.00		20.00		552.0
		B INSIDE, LH					1.00		20.00		486.4
		B INSIDE,RH ?					1.00		20.00		486.4
LAMP ASSY	-REAR COM	B OUTSIDE, LH 🗸					1.00		20.00	/	540.0
LAMP ASSY	-REAR COM	B OUTSIDE, RH	/ OR				1.00		20.00		540.0
MUFFLER A							1.00		20.00	/	605.6
GASKET-EX							1.00	14.00		/	11.2
LAMP ASSY	-HEAD,RH	- BR					1.00	2210.00	A-03 10040-00 A-0000-1 1	/	1768.00
PANEL ASS							1.00	1502.00		/	1201.60
HINGE ASS							1.00		20.00		34.40
HINGE ASS							1.00		20.00		34.40
CLIP-HOOD	INSULATI	NG PAD MTG /	P C				13.00		20.00	/	10.40
LATCH ASS	Y-HOOD X						1.00	103.00			82.40
PANEL-FEN	DER,RH	< 00					1.00	430.00		/	344.00
GUARD ASS	Y-FRONT W	HEEL,RH /	RY				1.00		20.00		76.00
KESEKVOIR	& PUMP A	SSY-WASHER 1	/ CR4				1.00	146.00	20.00		116.80
COVER-FR							1.00	633.00			506.40
<pre>1 GRILLE-FR 1 CAP-FRONT</pre>	ONI ROWDE	R / RR					1.00	485.00		/	388.00
CAP-FRUNT	HOOK X	2					1.00		20.00		7.20

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000		/YANG SEE JAY SEAN
7.23.200	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No Terms Date/Time Printed CSE Operator		WIP No		
AX00000 Credit 10/02/2021/ 18:26 261 / Edwin Caina		28874		
Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GRILLE ASSY-RADIATOR ! A X AM	1.00	328.00		262.4
M GARNISH-RADIATOR GRILLE	1.00	38.00	20.00	30.4
M MOULDING-FRONT BUMPER, RH / GR	1.00	216.00	20.00	172.8
M LAMP ASSY-SIDE REPEATER, RH / CMT	1.00	143.00	20.00	114.4
A A D DICT_ED RIMDED RH / CRU	1.00		20.00	11.2
ABSORBER-FRONT BUMPER ENERGY X MM	1.00		20.00	67.2
· ************************************	1.00	114.00	20.00	91.2
BRACKET-FR BUMPER UPR SIDE MTG 1 X AMI	1.00	22.00	20.00	17.6
WIRING ASSY-BUMPER EXTENSION * TH	1.00		20.00	165.6
ULTRASONIC SENSOR ASSY-P.A.S ? & MM	4.00	163.00	20.00	521.6
ORNAMENT-KIA NO.115 / MY	1.00		20.00	25.6
DEAM COMPLETE FR RUMPER Y WELL SET TO	7.90	497.00	20.00	397.6
CARRIER ASSY-FRONT END MODULE	1.00	675.00	20.00	540.0
WHEEL ASSY-ALUMINIUM RHF	4.60	926.00	20.00	740.8
MIRROR ASSY-OUTSIDE RR VIEW, RH	1.00		20.00	447.2
PANEL ASSY-FRONT DOOR, RH / DO	1.00	1277.00	20.00	1021.
HANDLE ASSY-DOOR OUTSIDE, RH X NW CUT	1.00		20.00 /	131.
COVER-FR DR O/S HDL RH X K	1.00		20.00	11.3
	1.00	5.00	20.00	4.0
PAD-FR DR O/S HDL HINGE, RH X MM	1.00		20.00	4.0
PAD-FR DR O/S HDL COVER, RH X A/AI	1.00	72.00	20.00	57.6
MOULDING ASST-REI DE FRANCISKI	1.00	80.00	20.00	64.0
	1.00	13.00	20.00 /	10.4
BLACK TAPE-FR DR RR, RH / APC	1.00	1377.00		1101.6
PANEL ASSY-REAR DOOR, RH / 00	1.00		20.00 /	10.4
BLACK TAPE-RR DR FR, RH / 1/80	1.00		20.00	6.4
BLACK TAPE-RR DR FRAME RR OTR, - ME	1.00		20.00	40.0
MOULDING ASSY-RR DR FRAME, RH / 180	1.00	75.00		60.0
W/STRIP ASSY-RR DR BELT O/S RH ? X MM	1.00	279.00		223.2
MOULDING ASSY-SIDE SILL, RH X MAI	1.00	26.00		20.0
COOLANT (4L) X NM SURVEYOR NAME: Stere (LKK)		20100		
SURVEYOR SIGNATURE: 15/2/21, 1.00pm)			
Confirm & accepted by DATE:				1 3
REMARKS: MY GC SM 7%	GST on	Net:		31,325.6 2192.7
REMARKS: MY OF L SM 72 OD- NM AML EXCISS-1, 18 days	Tota	l Payable	e	33,518.4
Authorized signatory and company stamp 20				

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.