

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21002106/UTF3Q2

Date: 02/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00017222106
Claimant Vehicle No :	SMJ1822G	Insured Vehicle No :	SKH9213X
Date of Loss:	11/02/2021	Nature of Claim:	TP
		Claim No:	SNM21D200870/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ1822G	Engine No:	A25A0143587
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	AXVH701028035
Reg. Date:	25/02/2019 (Man. Year: 2018)	Odometer:	24332 km
Colour:	White		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,635.20	2,541.70	6,093.50	70.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,570.00	1,460.00	3,110.00	68.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,205.20	4,001.70	9,203.50	69.70
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	13,205.20	3,200.00	10,005.20	75.77

INSPECTION

Date of Assignment:	15/02/2021	
Date Inspected:	16/02/2021 Inspected At:	Nineteen Autowerks Pte Ltd (HQ) BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE Singapore 417808
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2021)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ1822G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Dented/Bent	1,798.60 FL	*1,455.10 FL
2	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	280.70 FL	*- FL
3	1		*REAR DOOR INNER LOCK LH	Not Necessary	667.40 FL	*- FL
4	1		*REAR DOOR BLACK TAPE LH	Necessary	105.40 FL	*105.40 FL
5	1		*REAR FENDER LH	Repair	1,027.70 FL	*- FL
6	1		*REAR WINDSCREEN MOULDING	Not Necessary	218.70 FL	*- FL
7	1		*REAR SHOCK ABSORBER LH	Not Necessary	372.00 FL	*- FL
8	1		*REAR LOWER ARM LH	Not Necessary	486.80 FL	*- FL
9	1		*REAR KNUCKLE ARM LH	Not Necessary	808.50 FL	*- FL
10	1		*REAR KNUCKLE ARM BEARING LH	Not Necessary	701.10 FL	*- FL
11	1		*REAR ABS SENSOR LH	Not Necessary	286.50 FL	*- FL
12	1		*ROCKER PANEL GARNISH LH	Deformed/Torn	1,079.20 FL	*855.10 FL
13	2		*REAR BUMPER SIDE RETAINER	Not Necessary	341.00 FL	*- FL
14	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
15	1		*SET REAR DOOR TRIMBOARD CLIPS LH	Not Necessary	60.00 FS	*- FS
16	1		*REAR DOOR SEALANT LH	Not Necessary	80.00 FS	*- FS
17	1		*SET FRONT FENDER INNER SHIELD CLIPS LH	Not Necessary	45.00 FS	*- FS
18	1		*SET FRONT FENDER INNER TRIM CLIPS LH	Not Necessary	80.00 FS	*- FS
19	1		*REAR WINDSCREEN PRIMER AND CLEANER	Not Necessary	100.00 FS	*- FS
20	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
21	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
22	1		*REAR TYRE LH	Not Necessary	550.00 FS	*- FS
23	1		*REAR ALLOY RIM LH	Cut	1,250.00 FS	*680.00 FS
24	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,678.60 3,145.60
- List Item Discount on L Items 25.00/25.00% (\$\$) 2,043.40 603.90

Total Parts (\$\$) 8,635.20 2,541.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND STRENGTHEN PARTS ON ACCIDENT AREA	New	1,600.00	500.00
2	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	80.00	20.00
3	R&R LH REAR DOOR COMPONENT	New	480.00	50.00
4	R&R REAR WINDSCREEN	New	480.00	0.00
5	R&R LH REAR TYRE AND BALANCING	New	100.00	0.00
6	R&R LH REAR UNDERCARRIAGE	New	480.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
8	TO APPLY UNDERCOATING FOR RUST PROOFING	New	200.00	30.00
9	SPRAY PAINTING ON ACCIDENT AREA	New	1,000.00	800.00
Gross Labour Cost (\$\$)			4,570.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >