

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21002109/QGS3Q2
Date: 05/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800090538
Claimant Vehicle No :	SHC4730P	Insured Vehicle No :	SMD570X
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	4624356157SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4730P	Engine No:	2ZR6555936
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKN36U605766792
Reg. Date:	15/01/2016 (Man. Year: 2015)	Odometer:	732016 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,853.70	3,768.00	17,085.70	81.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,161.00	1,490.00	2,671.00	64.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,014.70	5,258.00	19,756.70	78.98
Approved Total (Overridden) (S\$)		4,500.00		

Nett Amount (S\$)	25,014.70	4,500.00	20,514.70	82.01
+ Loss of Use (5.5 x S\$60.00/day) (S\$)		330.00		
+ Car Rental (5.5 x S\$104.33/day) (S\$)		573.82		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		5,410.82		

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 08/02/2021

Estimated Period of Repair: 4.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
2	1		*FENDER LINER PAD ,FR WHEEL ,RH (DISC 25%)	Necessary	49.30 F	*36.98 F
3	1		*FENDER LINER FRT/RH (DISC 25%)	Cut	171.70 F	*128.78 F
4	1		*BUMPER LIP FRT (DISC 25%)	Crumpled	139.60 F	*104.70 F
5	1		*EMBLEM FRONT (DISC 25%)	Necessary	86.50 F	*64.88 F
6	1		*BUMPER GRILLE SUB-ASSY ,LOWER (DISC 25%)	Crumpled	311.10 F	*233.33 F
7	1		*COVER ,FR BUMPER HOLE RH (DISC 25%)	Crumpled	18.50 F	*13.88 F
8	1		*COVER ,FR BUMPER HOLE LH (DISC 25%)	Crumpled	18.50 F	*13.88 F
9	1		*BRACKET ,FR BUMPER (DISC 25%)	Crumpled	110.40 F	*82.80 F
10	1		*BUMPER SUPPORT F/LH (DISC 25%)	Broken	76.40 F	*57.30 F
11	1		*BUMPER SUPPORT F/RH (DISC 25%)	Broken	76.40 F	*57.30 F
12	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
13	1		*BUMPER FRT (DISC 25%)	Crumpled	482.00 F	*361.50 F
14	1		*BUMPER ENERGY ABSORBER FRT (DISC 25%)	Crumpled	78.80 F	*59.10 F
15	1		*BUMPER REINFORCEMENT FRT (DISC 25%)	Bent	498.40 F	*373.80 F
16	1		*BUMPER FRT ABSORBER LOWER (DISC 25%)	Crumpled	127.70 F	*95.78 F
17	1		*SUPPORT SUB-ASSY (DISC 25%)	Crumpled	1,460.40 F	*1,095.30 F
18	1		*HEAD LAMP LH (DISC 10%)	Scratched	945.20 F	*850.68 F
19	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
20	1		*NUMBER PLATE (SN)	Crumpled	15.00 F	*15.00 F
21	1		*NUMBER PLATE FRAME (SN)	Crumpled	12.00 F	*12.00 F
22	1		*FENDER LINER PAD ,FR WHEEL ,LH	Serviceable	49.30 F	*- F
23	1		*FENDER LINER FRT/LH	Serviceable	171.70 F	*- F
24	1		*CHECK ASSY ,FR DOOR	Serviceable	150.30 F	*- F
25	1		*HINGE UPPER LHF ,DOOR	Serviceable	80.50 F	*- F
26	1		*HINGE LOWER LHF ,DOOR	Serviceable	90.10 F	*- F
27	1		*FENDER FRT/RH	Serviceable	723.40 F	*- F
28	1		*FAN MOTOR NO.2	Serviceable	538.30 F	*- F
29	1		*FAN MOTOR NO.1	Serviceable	538.30 F	*- F
30	1		*FAN BLADE NO.2	Serviceable	204.20 F	*- F
31	1		*FAN BLADE	Serviceable	158.60 F	*- F
32	1		*FAN SHROUD TOP	Serviceable	99.60 F	*- F
33	1		*FAN SHROUD	Serviceable	244.50 F	*- F
34	1		*RADIATOR LOWER SUPPORT	Serviceable	876.30 F	*- F
35	1		*SUPPORT RADIATOR	Serviceable	18.50 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SUPPORT RADIATOR RH	Serviceable	54.50 F	*- F
37	1		*SUPPORT RADIATOR LH	Serviceable	17.70 F	*- F
38	1		*RADIATOR ASSY	Serviceable	1,496.90 F	*- F
39	1		*A/C CONDENSER	Serviceable	1,181.90 F	*- F
40	1		*HEAD LAMP RH	Serviceable	945.20 F	*- F
41	1		*SUPPORT SUB-ASSY	Serviceable	1,460.40 F	*- F
42	1		*HOOD HINGE RH	Serviceable	55.90 F	*- F
43	1		*HOOD HINGE LH	Serviceable	55.90 F	*- F
44	1		*UNDER COVER CENTER	Serviceable	448.30 F	*- F
45	1		*BUMPER FRT ABSORBER LOWER	Serviceable	127.70 F	*- F
46	1		*GRILLE ,RADIATOR LOWER NO.2	Serviceable	94.60 F	*- F
47	1		*GRILLE ,RADIATOR	Serviceable	310.60 F	*- F
48	1		*COVER ,RADIATOR	Serviceable	122.80 F	*- F
49	1		*HOOD END PANEL SEAL	Serviceable	35.50 F	*- F
50	1		*BRACKET ,FR TURN LOWER LH	Serviceable	26.00 F	*- F
51	1		*BRACKET ,FR TURN CENTER LH	Serviceable	58.20 F	*- F
52	1		*BRACKET ,FR TURN UPPER LH	Serviceable	24.40 F	*- F
53	1		*LENS & BODY ,FR TURN RH	Serviceable	511.80 F	*- F
54	1		*LENS & BODY ,FR TURN LH	Serviceable	511.80 F	*- F
55	1		*BRACKET ,FR TURN LOWER RH	Serviceable	26.00 F	*- F
56	1		*BRAKE ,FR TURN	Serviceable	58.20 F	*- F
57	1		*BRAKE ,FR TURN UPPER RH	Serviceable	58.20 F	*- F
58	1		*FOG LAMP LH	Serviceable	280.10 F	*- F
59	1		*FOG LAMP RH	Serviceable	295.20 F	*- F
60	1		*WIRE ,ENGINE ROOM ,NO.3	Serviceable	242.00 F	*- F
61	1		*DEFLECTOR ,RADIATOR LH	Serviceable	77.00 F	*- F
62	1		*DEFLECTOR ,RADIATOR RH	Serviceable	83.50 F	*- F
63	1		*ARM SUB-ASSY ,FR BUMPER RH	Serviceable	250.40 F	*- F
64	1		*ARM SUB-ASSY ,FR BUMPER LH	Serviceable	250.40 F	*- F
65	1		*BUMPER REINFORCEMENT FRT	Serviceable	498.40 F	*- F
66	1		*BUMPER ENERGY ABSORBER FRT	Serviceable	78.80 F	*- F
67	1		*FENDER FRT/LH	Repair	723.40 F	*- F
68	1		*DOOR FRT/LH	Repair	894.40 F	*- F
69	1		*HOOD PANEL	Repair	748.10 F	*- F
					Total Parts (\$\$)	20,853.70
						3,768.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	1,095.00	500.00
2	SPRAY PAINT	New	2,430.00	900.00
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
4	TO TRANSFER DOOR MECHANISM	New	120.00	0.00
5	TO REPLACE SUNDRY PARTS	New	100.00	0.00
6	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
7	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
9	TOWING CHARGE	New	56.00	40.00
Gross Labour Cost (\$\$)			4,161.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >