

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002117/T1GS3Q2
Date: 30/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800032721-02
Claimant Vehicle No :	SHA1313R	Insured Vehicle No :	SLX5376P
Date of Loss:	15/02/2021	Nature of Claim:	TP
		Claim No:	1947811132SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1313R		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU667376
Reg. Date:	12/05/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU090095
Colour:	Blue	Odometer:	634581 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,193.80	2,135.08	58.72	2.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	530.00	470.00	47.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,193.80	2,665.08	528.72	16.55
Approved Total (Overridden) (S\$)		2,100.00		

(S\$)	3,193.80	2,100.00	1,093.80	34.25
+ GST 7.00/7.00% (S\$)	223.57	147.00	76.57	34.25
Nett Amount (S\$)	3,417.37	2,247.00	1,170.37	34.25
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$110.67/day) (S\$)		332.01		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,731.01		

INSPECTION

Date of Assignment: 15/02/2021

Date Inspected: 15/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,052.20 FL	*1,052.20 FL
2	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	*1,480.00 FL
3	1		*RADIATOR EMBLEM	Necessary	45.90 FL	*45.90 FL
4	10		*BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
5	1		*FRONT BUMPER BRACKET TOP LH	Not Necessary	44.80 FL	*- FL
6	1		*FRONT BUMPER BRACKET SIDE LH	Not Necessary	28.60 FL	*- FL
7	1		*FRONT NUMBER PLATE W/HOLDER	Necessary	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,728.50	2,655.10
- List Item Discount on L Items 20.00/20.00% (\$)	534.70	520.02
Total Parts (\$)	2,193.80	2,135.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	280.00
2	SPRAY PAINTING	New	300.00	250.00
3	TUFF COAT	New	50.00	0.00
4	CHECK LIGHTING	New	50.00	0.00
Gross Labour Cost (\$)			1,000.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >