

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21002125/UBS3Q2

Date:

17/05/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MPC0003809

Claimant Vehicle No : SLT6837R**Insured Vehicle No :**

SMN5515X

Date of Loss: 10/02/2021

Nature of Claim:

TP

Claim No:

MPC2021D0000689

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLT6837R**

Make & Model: MITSUBISHI SPACE STAR, 1.2 CVT (A)

Engine No:

3A92UGJ9340

Reg. Date: 07/11/2017 (Man. Year: 2017)

Chassis No:

MMCXTA03AJH001640

Colour: Blue

Odometer:

47734 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/55 R15

Rear Tyre Size:

175/55 R15

Front Left Side: Yokohama 4 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 4 mm

Rear Right Side:

Yokohama 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,740.08	5,350.40	7,389.68	58.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	1,550.00	2,730.00	63.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,020.08	6,900.40	10,119.68	59.46
Approved Total (Overridden) (S\$)		5,500.00		

Nett Amount (S\$)	17,020.08	5,500.00	11,520.08	67.69
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,207.45		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment: 15/02/2021

Date Inspected: 15/02/2021

Estimated Period of Repair: 5.0 days

Inspected At: Zoom Autowerks Pte Ltd
832 SIMS AVENUE #12-884 EUNOSVILLE
Singapore 400832

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2021)
Parts:	144	mitsubishi space star 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT6837R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	825.40 FL	*751.00 FL
2	1		*FRONT BUMPER BRACKET	Not Necessary	137.80 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER	N/S Cracked	151.60 FL	*35.00 FL
4	1		*FRONT BUMPER CENTRE GARNISH	Not Necessary	295.80 FL	*- FL
5	1		*FRONT BUMPER SIDE GARNISH	N/S Twisted	351.20 FL	*115.00 FL
6	1		*FRONT BUMPER CENTRE CHROME GARNISH	Not Necessary	245.80 FL	*- FL
7	1		*FRONT BUMPER SIDE CHROME GARNISH	N/S Scratched	391.40 FL	*125.00 FL
8	1		*FRONT BUMPER FOG LAMP	N/S Cracked	656.80 FL	*311.00 FL
9	1		*FRONT BUMPER NUMBER PLATE BASED GARNISH	Not fitted	105.60 FL	*- FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
11	1		*RADIATOR GRILLE CHROME GARNISH	Not Necessary	195.80 FL	*- FL
12	1		*RADIATOR GRILLE BASED GARNISH	Not Necessary	325.80 FL	*- FL
13	1		*SET RADIATOR GRILLE CLIPS	Not Necessary	60.00 FL	*- FL
14	1		*FRONT HEADLAMP ASSY N/S	Cracked	2,213.60 FL	*1,842.00 FL
15	2		*FRONT HEADLAMP BRACKET	No such part	197.00 FL	*- FL
16	1		*FRONT FENDER	N/S Distorted	1,559.20 FL	*435.00 FL
17	2		*FRONT FENDER QUARTER GARNISH	Not Necessary	144.80 FL	*- FL
18	1		*FRONT FENDER EMBLEM	N/S Necessary	178.40 FL	*62.00 FL
19	2		*FRONT FENDER BRACKET	Not Necessary	190.80 FL	*- FL
20	1		*FRONT FENDER INNER SHIELD	N/S Distorted	429.00 FL	*103.00 FL
21	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*50.00 FL
22	1		*WING MIRROR ASSY LH	Not Necessary	479.10 FL	*- FL
23	1		*FRONT DOOR LH	Repair	984.20 FL	*- FL
24	1		*FRONT DOOR INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
25	1		*FRONT DOOR OUTER GLASS MOULDING LH	Not Necessary	175.80 FL	*- FL
26	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	198.40 FL	*- FL
27	1		*FRONT DOOR TOP HINGE LH	Not Necessary	78.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT DOOR BOTTOM HINGE LH	Not Necessary	67.20 FL	*- FL
29	1		*FRONT DOOR CHECKER LH	Not Necessary	59.40 FL	*- FL
30	1		*FRONT RIM LH (ORI)	Dented / Bent	910.08 FS	*580.00 FS
31	1		*FRONT KNUCKLE ARM LH	Bent	420.00 FL	*367.00 FL
32	1		*FRONT KNUCKLE HUB ,WHEEL BEARING LH	Bent	320.00 FL	*245.00 FL
33	1		*FRONT LOWER ARM LH	Buckled	392.00 FL	*280.00 FL
34	1		*FRONT STEERING ROCKEND	Bent	245.00 FL	*165.00 FL
35	1		*FRONT SHOCK ABSORBER LH	Bent	395.00 FL	*320.00 FL
36	1		*FRONT NUMBER PLATE W/GARNISH	Missing	65.00 FS	*40.00 FS
37	1		*FRONT TYRE RH 15INCH	Serviceable	380.00 FS	*- FS
					Sub Total (\$\$)	14,005.08
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,265.00
					Total Parts (\$\$)	12,740.08

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,200.00	600.00
2	TO PUTTY ,SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS	New	1,600.00	600.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL FRONT LEFT UNDERCARRIAGE COMPONENTS	New	250.00	150.00
5	TO CONDUCT ALL WHEEL ALIGNMENT	New	250.00	100.00
6	TO TRANSFER ,REPLACE & BALANCE FRONT RIM & TYRE	New	100.00	0.00
7	TO REMOVE & INSTALL FRONT DOOR LH COMPONENTS	New	180.00	0.00
8	TO DIAGNOSTIC & RESET TO SPECIFICATION	New	450.00	50.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	30.00
Gross Labour Cost (\$\$)			4,280.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >