



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 3608C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT BUMPER (CONSISTENT) | DEEP CUT | 824.30 | 474.80 |
| 1 | FRONT BUMPER SIDE RETAINER O/S (CONSISTENT) | NOT NECESSARY | 48.50 | - |
| 1 | FRONT BUMPER BEAM (CONSISTENT) | TO REPAIR SEE LABOUR | 322.20 | - |
| 1 | SET FRONT BUMPER CLIPS (CONSISTENT) | NECESSARY | 50.00 | 50.00 |
| 1 | FRONT FOG LAMP O/S (CONSISTENT) | CRACKED | 650.50 | 350.20 |
| 1 | FRONT FOG LAMP GARNISH O/S (CONSISTENT) | TWISTED | 211.20 | 142.60 |
| 1 | HEADLAMP O/S (CONSISTENT) | CRACKED | 2,850.00 | 1,756.40 |
| | LESS 20% DISCOUNT | | - | -554.80 |
| | | | 4,956.70 | 2,219.20 |
| | <u>LABOUR</u> | | | |
| | TO CHECK WIRING . | | 50.00 | 20.00 |
| | TO RESET & REPROGRAMME SYSTEM. | NOT NECESSARY | 100.00 | - |
| | TO CONDUCT WHEEL ALIGNMENT . | NOT NECESSARY | 100.00 | - |
| | LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER BEAM . | | 420.00 | 280.00 |
| | TO PUTTY & SPRAY PAINTING . | | 480.00 | 300.00 |
| | | | 1,150.00 | 600.00 |
| GRAND TOTAL | | | 6,106.70 | 2,819.20 |
| RECOMMENDED COST OF REPAIRS | | | | 2,819.20 |

Report Ref No. CC4/ASM21002126/Uba3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.