

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21002135/ABA3Q2
Date: 25/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700064333
Claimant Vehicle No :	SLQ2381E	Insured Vehicle No :	SLT6290S
Date of Loss:	10/02/2021	Nature of Claim:	TP
		Claim No:	5680956720SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ2381E		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20YA31590
Reg. Date:	30/06/2017 (Man. Year: 2017)	Chassis No:	JF1SJ5KC5HG092435
Colour:	Grey	Odometer:	68449 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,339.70	1,874.08	10,465.62	84.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,620.00	1,700.00	3,920.00	69.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,959.70	3,574.08	14,385.62	80.10
Approved Total (Overridden) (S\$)		2,800.00		

(S\$)	17,959.70	2,800.00	15,159.70	84.41
+ GST 7.00/7.00% (S\$)	1,257.18	196.00	1,061.18	84.41
Nett Amount (S\$)	19,216.88	2,996.00	16,220.88	84.41
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,498.00		
Global Sum Settlement (S\$)		3,490.00		

INSPECTION

Date of Assignment: 22/02/2021

Date Inspected: 22/02/2021

Inspected At:

Cn Motors Pte Ltd (HQ)

1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	1,192.30 F	*- FL
2	2		*REAR BOOT LID HINGE	Not Necessary	110.00 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	308.00 F	*- FL
4	1		*REAR BOOT LID EMBLEM LOGO	Not Necessary	65.00 F	*- FL
5	1		*REAR BOOT LID SUBARU LOGO	Not Necessary	68.00 F	*- FL
6	1		*REAR BOOT LID FORESTER LOGO	Not Necessary	68.00 F	*- FL
7	1		*REAR BOOT LID AWD LOGO	Not Necessary	65.00 F	*- FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	1		*REAR BOOT LID INNER LOCK	Not Necessary	560.30 F	*- FL
10	1		*REAR BOOT LID WEATHERSTRIP	Not Necessary	160.30 F	*- FL
11	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	220.30 F	*- FL
12	10		*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	65.00 F	*- FL
13	1		*REAR BOOT LID WINDSCREEN SEAL	Not Necessary	85.00 F	*- FL
14	2		*REAR BOOT LID WINDSCREEN SIDE SEAL	Not Necessary	150.00 F	*- FL
15	1		*REAR BOOT LID REVERSE CAMERA	Not Necessary	850.00 F	*- FL
16	2		*REAR TAIL LAMP	Not Necessary	874.60 F	*- FL
17	2		*REAR TAIL LAMP CLIP	Not Necessary	16.00 F	*- FL
18	1		*REAR L/H TAIL LAMP PANEL	Not Necessary	105.80 F	*- FL
19	1		*REAR L/H TAIL LAMP LOWER BRACKET	Not Necessary	38.00 F	*- FL
20	1		*REAR BUMPER	Deformed	980.30 F	*600.30 FL
21	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
22	1		*REAR L/H BUMPER SIDE RETAINER	Necessary	38.00 F	*38.00 FL
23	1		*REAR L/H BUMPER SIDE REFLECTOR	Not Necessary	42.00 F	*- FL
24	1		*REAR BUMPER TOWING COVER	Deformed	22.00 F	*22.00 FL
25	1		*REAR L/H BUMPER EXHAUST COVER	Deformed	76.80 F	*76.80 FL
26	1		*REAR BUMPER REINFORCEMENT	Bent	320.80 F	*320.80 FL
27	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	57.20 F	*- FL
28	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
29	1		*REAR L/H FENDER	Not Necessary	1,060.40 F	*- FL
30	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	972.60 F	*- FL
31	8		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
32	1		*REAR END PANEL	Dented	332.00 F	*332.00 FL
33	1		*REAR END PANEL TOP GARNISH	Deformed	90.00 F	*90.00 FL
34	1		*REAR SPARE TYRE PANEL	Repair	632.40 F	*- FL
35	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	336.00 F	*336.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*- FL
37	1		*REAR SPARE TYRE PANEL SIDE FOAM TOOL BOX	N/S Cracked	171.00 F	*85.50 FL
38	1		*REAR SPARE TYRE PANEL FOAM TOOL BOX	Cracked	161.20 F	*161.20 FL
39	1		*REAR CENTRE EXHAUST	Not Necessary	1,048.40 F	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					12,339.70	2,292.60
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	418.52
Total Parts (S\$)					12,339.70	1,874.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	60.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	0.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	150.00	0.00
5	TO REMOVE & REFIT REAR EXHAUST	New	200.00	0.00
6	GUM	New	60.00	0.00
7	TO CHECK WIRING	New	100.00	30.00
8	TUFF KOTE	New	150.00	60.00
9	PANEL BEATING	New	2,400.00	800.00
10	SPRAY PAINTING	New	2,000.00	700.00
Gross Labour Cost (\$)			5,620.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >