

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21002136/ABS3Q2
Date: 28/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100423088-05
Claimant Vehicle No :	SLJ6637D	Insured Vehicle No :	SKT7350H
Date of Loss:	11/02/2021	Nature of Claim:	TP
		Claim No:	4926622216SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ6637D		
Make & Model:	TOYOTA HARRIER, 2.0 Elegance (A)	Engine No:	3ZRB860047
Reg. Date:	20/12/2016 (Man. Year: 2016)	Chassis No:	ZSU600086817
Colour:	White	Odometer:	99388 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Champiro 6 mm	Rear Left Side:	Champiro 6 mm
Front Right Side:	Champiro 6 mm	Rear Right Side:	Champiro 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,365.92	7,717.95	8,647.97	52.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	2,280.00	2,370.00	50.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,015.92	9,997.95	11,017.97	52.43
Approved Total (Overridden) (S\$)		8,000.00		

Nett Amount (S\$)	21,015.92	8,000.00	13,015.92	61.93
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,607.45		
Global Sum Settlement (S\$)		8,550.00		

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021

Estimated Period of Repair: 6.0 days

Inspected At: Kt Motorwerk (HQ)
Blk 3012 Bedok Industrial Park E, #01-2020
Singapore 489978

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,379.80 FL	*1,712.00 FL
2	1		*TAILGATE INNER TRIM BOTTOM	Torn	651.10 FL	*651.10 FL
3	2		*TAILGATE INNER TRIM SIDE	Not Necessary	597.00 FL	*- FL
4	1		*TAILGATE INNER TRIM TOP	Not Necessary	326.80 FL	*- FL
5	2		*TAILGATE POCKETS	Not Necessary	204.60 FL	*- FL
6	1		*TAILGATE INNER LOCK	Damaged	475.30 FL	*475.30 FL
7	1		*TAILGATE INNER LOCK COVER	Not Necessary	85.20 FL	*- FL
8	1		*TAILGATE LOCK CATCH	Not Necessary	98.70 FL	*- FL
9	1		*TAILGATE LOGO	Necessary	97.60 FL	*97.60 FL
10	1		*TAILGATE HARRIER EMBLEM	Necessary	117.50 FL	*117.50 FL
11	1		*TAILGATE OUTER GARNISH	Not Necessary	495.30 FL	*- FL
12	2		*TAILGATE ABSORBER	Not Necessary	779.20 FL	*- FL
13	1		*TAILGATE LAMP	O/S Cut	991.20 FL	*495.60 FL
14	2		*TAILGATE LAMP INNER SEALER	Not Necessary	84.00 FL	*- FL
15	1		*WINDSCREEN MOLDING	Necessary	198.80 FL	*198.80 FL
16	1		*WINDSCREEN INNER SEAL	Necessary	60.00 FL	*60.00 FL
17	1		*TAILGATE WEATHERSTRIP	Cut	256.80 FL	*256.80 FL
18	2		*TAILGATE STOPPERS	Not Necessary	90.00 FL	*- FL
19	1		*REAR BUMPER	Deformed	1,450.60 FL	*1,450.60 FL
20	2		*REAR BUMPER RETAINERS	Necessary	197.20 FL	*197.20 FL
21	1		*REAR BUMPER ANTENNA	Cracked	245.60 FL	*245.60 FL
22	1		*REAR BUMPER SPONGE	Cracked	325.20 FL	*138.00 FL
23	1		*REAR BUMPER LOWER	Deformed	455.10 FL	*455.10 FL
24	2		*REAR BUMPER REFLECTORS	Not Necessary	170.40 FL	*- FL
25	1		*TAILAMPS	O/S Cut	997.40 FL	*498.70 FL
26	1		*TAILAMPS LOWER BRACKETS	O/S Cracked	197.00 FL	*98.50 FL
27	2		*TAILAMPS INNER SEALER	Not Necessary	85.00 FL	*- FL
28	2		*REAR FENDERS INNER TRIM	Not Necessary	1,516.40 FL	*- FL
29	1		*REAR FENDER AIR DUCT	Not Necessary	185.70 FL	*- FL
30	2		*REAR FENDERS INNER COWLING	Not Necessary	397.20 FL	*- FL
31	1		*REAR END PANEL	Dented	799.10 FL	*799.10 FL
32	1		*REAR END PANEL TOP GARNISH	Deformed	466.10 FL	*466.10 FL
33	1		*SPARE TYRE PANEL	Repair	972.50 FL	*- FL
34	1		*SPARE TYRE TOP BOARD OUTER	Deformed	895.70 FL	*541.00 FL
35	1		*SPARE TYRE TOP BOARD INNER	Not Necessary	575.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*SPARE TYRE SIDE TRAY (OUTER)	Deformed	1,585.00 FL	*776.00 FL
37	2		*SPARE TYRE SIDE TRAY (INNER)	Not Necessary	950.20 FL	*- FL
38	1		*SPARE TYRE BOTTOM SPONGE	Not Necessary	311.80 FL	*- FL
39	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
40	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
41	1		*REAR SEAT HEADREST	Not Necessary	30.00 FS	*- FS
42	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
43	2		*SET TAILGATE LAMP CLIPS	Necessary	60.00 FS	*20.00 FS
44	2		*SET TAILAMP CLIPS	Necessary	60.00 FS	*20.00 FS
45	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
46	1		*SET REVERSE SENSORS	Damaged	250.00 FS	*200.00 FS
47	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
48	2		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
49	1		*SET REAR BUMPER LOWER CLIP	Necessary	30.00 FS	*30.00 FS
50	2		*WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	21,557.90	10,150.60
- List Item Discount on L Items 25.00/25.00% (S\$)	5,191.98	2,432.65
Total Parts (S\$)	16,365.92	7,717.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	1,800.00	900.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	900.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
4	TO REMOVE/REFIT INTERIOR UPHOLSTERY	New	150.00	80.00
5	TO APPLY SEALANT TO THE AFFECTED AREAS	New	150.00	60.00
6	TO REMOVE/REFIT WIRING CHECKS ON TAILAMPS	New	150.00	30.00
7	TO REMOVE /REFIT REAR WINDSCREEN	New	150.00	120.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO REMOVE /REPLACE REVERSE SENSORS AND DISTANCE SETTING	New	150.00	50.00
10	TO REMOVE /REFIT AND REPLACE TAILGATE MECHANISM	New	150.00	80.00
Gross Labour Cost (S\$)			4,650.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >