

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21002137/KQF3E2

Date: 23/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100504589
Claimant Vehicle No :	SMX706S	Insured Vehicle No :	SLM1366C
Date of Loss:	07/02/2021	Nature of Claim:	TP
		Claim No:	2962046477SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX706S	Engine No:	2NRX566281
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	MHFZ28H3100068987
Reg. Date:	24/12/2020 (Man. Year: 2020)	Odometer:	4616 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/02/2021		
Date Inspected:	16/02/2021	Inspected At:	Lim Motor Pte Ltd (HQ) 160 Sin Ming Drive, #05-20 Autocity Singapore 575722
Estimated Period of Repair:	14.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	* Check	0.00 F	*- F
2	1		*REAR NUMBER PLATE GARNISH	* Check	0.00 F	*- F
3	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F
4	1		*REAR BUMPER	Bent	0.00 F	*- F
5	1		*REAR BUMPER CTR LAMP	Cracked	0.00 F	*- F
6	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
7	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
8	1		*REAR BUMPER PROTECTOR CTR	Bent	0.00 F	*- F
9	2		*REAR BUMPER PROTECTOR LH & RH	Cut	0.00 F	*- F
10	2		*REAR BUMPER REFLECTOR LH & RH	Cracked	0.00 F	*- F
11	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
12	1		*REAR END PANEL	Buckled	0.00 F	*- F
13	1		*REAR END PANEL TOP GARNISH	Bent	0.00 F	*- F
14	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
15	1		*REAR LH TAILLAMP PANEL	Repair	0.00 F	*- F
16	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
17	1		*REAR RH TAILLAMP PANEL	Repair	0.00 F	*- F
18	1		*TAILGATE	Buckled	0.00 F	*- F
19	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
20	1		*TAILGATE MOULDING	Cracked	0.00 F	*- F
21	2		*TAILGATE LAMP	Cracked	0.00 F	*- F
22	1		*TAILGATE WIPER MOTOR	* Check	0.00 F	*- F
23	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
24	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
25	1		*TAILGATE RUBBER	Bent	0.00 F	*- F
26	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
27	1		*SPARE TYRE BOARD	* Check	0.00 F	*- F
28	1		*SPARE TYRE PANEL	Buckled	0.00 F	*- F
29	1		*SPARE TYRE LOCK SCREW	* Check	0.00 F	*- F
30	1		*SPARE TYRE COVER	* Check	0.00 F	*- F
31	1		*REAR LH FENDER INNER TRIM	* Check	0.00 F	*- F
32	1		*REAR RH FENDER INNER TRIM	Cracked	0.00 F	*- F
33	1		*TOOLS HOLDER	Dented	0.00 F	*- F
34	1		*FRT NUMBER PLATE	Dented	0.00 F	*- F
35	1		*FRT NUMBER PLATE GARNISH	Distorted	0.00 F	*- F
36	1		*FRT BUMPER	Dented	0.00 F	*- F
37	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
38	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
39	1		*FRT BUMPER REINFORCEMENT	* Check	0.00 F	*- F
40	2		*FRT BUMPER PROTECTOR LH & RH	Distorted	0.00 F	*- F
41	1		*FRT BUMPER EMBLEM	Necessary	0.00 F	*- F
42	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
43	1		*FRT BUMPER MOULDING	Cracked	0.00 F	*- F
44	1		*FRT LH BUMPER FOG LAMP COVER	* Check	0.00 F	*- F
45	1		*FRT RH BUMPER FOG LAMP COVER	* Check	0.00 F	*- F
46	1		*FRT LH BUMPER FOG LAMP	* Check	0.00 F	*- F
47	1		*FRT RH BUMPER FOG LAMP	* Check	0.00 F	*- F
48	1		*FRT GRILLE	Cut	0.00 F	*- F
49	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
50	1		*FRT SUPPORT PANEL TOP GARNISH COVER	* Check	0.00 F	*- F
51	1		*FRT BRACE PANEL	* Check	0.00 F	*- F
52	1		*FRT LH HEADLAMP ASSY	* Check	0.00 F	*- F
53	1		*FRT RH HEADLAMP ASSY	* Check	0.00 F	*- F
54	1		*BONNET	Dented	0.00 F	*- F
55	1		*BONNET LOCK	* Check	0.00 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*AIR CON CONDENSER	* Check	0.00 F	*- F
57	1		*RADIATOR	* Check	0.00 F	*- F
58	1		*RADIATOR FAN ASSY	* Check	0.00 F	*- F
59	1		*FRT LH FENDER INNER SHIELD	* Check	0.00 F	*- F
60	1		*FRT RH FENDER INNER SHIELD	* Check	0.00 F	*- F
61	1		*REAR FENDER AIR GRILLE	* Check	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >