

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21002144/BA3Q2

Date:

10/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900243204

Claimant Vehicle No : SHA2011E**Insured Vehicle No :**

SJG699D

Date of Loss: 11/02/2021

Nature of Claim:

TP

Claim No:

1623177594SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA2011E**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No:

D4FDGU671694

Reg. Date: 29/09/2016 (Man. Year: 2016)

Chassis No:

KMHLB41UMGU093607

Colour: Blue

Odometer:

498261 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: West Lake 5 mm

Rear Left Side:

West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side:

West Lake 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	21,347.16	10,365.76	10,981.40	51.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,770.00	1,600.00	3,170.00	66.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,117.16	11,965.76	14,151.40	54.18
Approved Total (Overridden) (S\$)		9,500.00		

(S\$)	26,117.16	9,500.00	16,617.16	63.63
+ GST 7.00/7.00% (S\$)	1,828.20	665.00	1,163.20	63.63
Nett Amount (S\$)	27,945.36	10,165.00	17,780.36	63.63
+ Loss of Use (9.0 x S\$50.00/day) (S\$)		450.00		
+ Car Rental (9.0 x S\$110.67/day) (S\$)		996.03		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		11,698.48		
Global Sum Settlement (S\$)		11,600.00		

INSPECTION

Date of Assignment: 15/02/2021

Date Inspected: 16/02/2021

Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
 Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
 Singapore 575644

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent / Dented	2,265.90 FL	*2,265.90 FL
2	1		*BONNET RUBBER (LH)	Not Necessary	35.70 FL	*- FL
3	1		*BONNET RUBBER (RH)	Not Necessary	35.70 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	142.40 FL	*- FL
5	1		*BONNET ABSORBER (LH ONLY)	Not Necessary	61.60 FL	*- FL
6	1		*BONNET INSULATOR	Not Necessary	202.50 FL	*- FL
7	10		*BONNET INSULATOR CLIP	Not Necessary	36.80 FL	*- FL
8	1		*BONNET SEAL	Not Necessary	31.90 FL	*- FL
9	1		*RADIATOR GRILLE H EMBLEM	Necessary	129.50 FL	*129.50 FL
10	1		*RADIATOR GRILLE	Cracked / Mtg Cracked	1,480.00 FL	*1,110.10 FL
11	1		*FRONT BUMPER COVER	Dented / Torn	1,052.20 FL	*1,052.20 FL
12	1		*FRONT BUMPER SPONGE	Torn	379.20 FL	*119.50 FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent / Dented	588.40 FL	*588.40 FL
14	1		*FRONT BUMPER GRILLE (LH)	Deformed / Distorted	149.20 FL	*149.20 FL
15	1		*FRONT BUMPER LIP	Not Necessary	152.00 FL	*- FL
16	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	44.80 FL	*- FL
17	1		*FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40)	Not Necessary	80.00 FL	*- FL
18	1		*FRONT BUMPER BRACKET (LH)	Broken	49.20 FL	*49.20 FL
19	1		*FRONT BUMPER SIDE BRACKET (LH)	Not Necessary	28.60 FL	*- FL
20	1		*FRONT BUMPER PROTECTOR (LH)	No such part	25.40 FL	*- FL
21	1		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	76.20 FL	*- FL
22	1		*FRONT BUMPER GRILLE AIR DUCT (LH)	Not Necessary	126.20 FL	*- FL
23	1		*HEADLAMP SUPPORT PANEL ASSY	Broken / Bent	907.40 FL	*907.40 FL
24	1		*HEADLAMP (LH)	Broken	2,776.00 FL	*1,388.00 FL
25	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
26	1		*RADIATOR	Bent	1,637.20 FL	*708.50 FL
27	1		*RADIATOR GUARD (LH)	Not Necessary	76.50 FL	*- FL
28	1		*RADIATOR BRACKET (LH)	Not Necessary	13.00 FL	*- FL
29	1		*COOLANT	Not Necessary	45.00 FL	*- FL
30	1		*RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY	Not Necessary	1,194.20 FL	*- FL
31	1		*AIR CLEANER ASSY	Not Necessary	118.60 FL	*- FL
32	1		*AIR FILTER	Not Necessary	63.70 FL	*- FL
33	1		*AIR CLEANER COVER	Cracked	228.60 FL	*228.60 FL
34	1		*AIR CLEANER BOTTOM ASSY	Mtg Broken	325.00 FL	*325.00 FL
35	1		*AIR CLEANER HOSE	Not Necessary	432.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*AIR CLEANER HOUSING	Not Necessary	88.50 FL	*- FL
37	1		*AIR DUCT	Not Necessary	171.70 FL	*- FL
38	1		*FRONT FENDER (LH)	Dented	663.00 FL	*663.00 FL
39	1		*FRONT FENDER APRON PANEL(LH)	Dented	637.00 FL	*637.00 FL
40	1		*FRONT FENDER SHIELD (LH)	Deformed	174.90 FL	*174.90 FL
41	1		*FRONT FENDER MUDFLAP (LH)	Not Necessary	16.20 FL	*- FL
42	1		*FRONT FENDER RETAINER	Not Necessary	24.60 FL	*- FL
43	1		*FRONT FENDER GUARD	Not Necessary	120.00 FL	*- FL
44	1		*FRONT FENDER ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
45	1		*AIRCON CONDENSER	Bent	947.80 FL	*947.80 FL
46	1		*AIRCON SUCTION & LIQUID HOSE	Not Necessary	624.00 FL	*- FL
47	1		*INTER COOLER	Serviceable	1,032.50 FL	*- FL
48	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL
49	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	*- FL
50	1		*WIRING -ENGINE W/FUSE BOX	Not Necessary	3,326.00 FL	*- FL
51	1		*FRONT DOOR COMFORT LOGO (LH)	Not Necessary	75.00 FS	*- FS
52	1		*FRONT DOOR ADVERTISEMENT LOGO	Not Necessary	100.00 FS	*- FS
53	1		*HEADLAMP RH	Mtg Cracked	2,776.00 FL	*1,388.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,615.20	12,932.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,268.04	2,566.44
Total Parts (\$\$)	21,347.16	10,365.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,800.00	700.00
2	SPRAY PAINTING CHARGE	New	1,200.00	700.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX RADIATOR	New	90.00	50.00
7	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	80.00
8	REMOVE /REFIX FUSE BOX	New	120.00	0.00
9	REMOVE/REFIX ENGINE	New	600.00	0.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (S\$)			4,770.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >