

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002145/KPA3Q2
Date: 18/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100472478
Claimant Vehicle No :	SMF9625C	Insured Vehicle No :	GBF1295D
Date of Loss:	09/02/2021	Nature of Claim:	TP
		Claim No:	7639877477SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF9625C		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Engine No:	G4FGGU158318
Reg. Date:	04/04/2016 (Man. Year: 2016)	Chassis No:	KMHD841CMHU143719
Colour:	Metallic Grey	Odometer:	81432 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,428.16	877.44	1,550.72	63.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	530.00	880.00	62.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,838.16	1,407.44	2,430.72	63.33
+ GST 7.00/7.00% (S\$)	268.67	98.52	170.15	63.33

Nett Amount (\$\$)	4,106.83	1,505.96	2,600.87	63.33
+ Loss of Use (3.0 x S\$50.00/day) (\$\$)		150.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		1,657.96		

INSPECTION

Date of Assignment: 15/02/2021

Date Inspected: 18/02/2021

Estimated Period of Repair: 2.0 days

Inspected At: Kgc Workshop Pte Ltd (AMK)
14 Ang Mo Kio Street 63, Blk B
Singapore 569116

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	845.70 FL	*459.40 FL
2	1		*REAR LOWER BUMPER	Dented	412.00 FL	*280.10 FL
3	2		*REAR BUMPER RETAINER	Serviceable	65.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR RHS	Serviceable	85.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR LHS	Serviceable	85.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Buckled	480.00 FL	*294.80 FL
7	1		*REAR END PANEL	Repair	525.00 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
9	1		*SET REVERSE SENSOR	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,927.70	1,084.30
- List Item Discount on L Items 20.00/20.00% (S\$)	499.54	206.86
Total Parts (S\$)	2,428.16	877.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS	New	600.00	250.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	New	600.00	220.00
3	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	80.00	10.00
4	TO REMOVE AND REFIT REVERSE SENSOR AND CONDUCT SAFE DISTANCE SETTING	New	80.00	50.00
5	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	0.00
Gross Labour Cost (S\$)			1,410.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >