

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21002159/EQD3E2

Date: 12/04/2021

REFERENCE

Insured/Claimant:	LYNETTE CHEAH	Policy No:	
Date of Loss:	10/02/2021	Nature of Claim:	OD Claim No: 1301249427SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK2755E	Engine No:	D4HBJH205598
Make & Model:	KIA SORENTO, 2.2 (A)	Chassis No:	KNAPH81BMK5523936
Reg. Date:	02/04/2019 (Man. Year: 2018)	Odometer:	38101 km
Colour:	Black		
Engine Capacity:	2199 cc		
Market Value/New Car Price:	S\$116,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Ventus 5 mm	Rear Left Side:	Ventus 5 mm
Front Right Side:	Ventus 5 mm	Rear Right Side:	Ventus 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,797.62	9,787.20	4,010.42	29.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,336.40	3,890.00	3,446.40	46.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,134.02	13,677.20	7,456.82	35.28
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	20,834.02	13,377.20	7,456.82	35.79
+ GST 7.00/7.00% (S\$)	1,458.38	936.40	521.98	35.79
Nett Amount (S\$)	22,292.40	14,313.60	7,978.80	35.79

INSPECTION

Date of Assignment:	16/02/2021	
Date Inspected:	16/02/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, LH	Broken	2,743.00 FL	*2,743.00 FL
3	1		*LAMP ASSY-HEAD, RH	Broken	2,743.00 FL	*2,743.00 FL
4	1		*COVER-FR BUMPER UPR	Broken	561.00 FL	*561.00 FL
5	1		*MOULDING-FRT BPR LICENSE PLATE	Broken	20.00 FL	*20.00 FL
6	1		*LIP-FRONT BUMPER	Not Necessary	56.00 FL	*- FL
7	1		*SKID PLATE-FR BUMPER	Not Necessary	111.00 FL	*- FL
8	1		*MOULDING-FRONT BUMPER LWR, LH	Not Necessary	89.00 FL	*- FL
9	1		*MOULDING-FRONT BUMPER LWR, RH	Not Necessary	89.00 FL	*- FL
10	1		*GRILLE ASSY-RADIATOR	Broken	673.00 FL	*673.00 FL
11	1		*COVER ASSY-RADIATOR GRILLE UPR	Broken	186.00 FL	*186.00 FL
12	1		*GRILLE-FRONT BUMPER	Broken	191.00 FL	*191.00 FL
13	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	117.00 FL	*117.00 FL
14	1		*STIFFENER ASSY-FR BUMPER LWR	Not Necessary	117.00 FL	*- FL
15	1		*BRACKET-FR BUMPER SIDE, LH	Broken	17.00 FL	*17.00 FL
16	1		*BRACKET-FR BUMPER SIDE, RH	Broken	17.00 FL	*17.00 FL
17	1		*GRILLE-FRONT BUMPER FOG LAMP, L	Not Necessary	81.00 FL	*- FL
18	1		*GRILLE-FRONT BUMPER FOG LAMP, R	Not Necessary	81.00 FL	*- FL
19	1		*WIRING HARNESS-F.P.A.S	Torn	257.00 FL	*257.00 FL
20	4		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	748.00 FL	*- FL
21	1		*PANEL ASSY-HOOD	Dented	1,654.00 FL	*1,654.00 FL
22	1		*HINGE ASSY-HOOD, LH	Bent	87.00 FL	*87.00 FL
23	1		*HINGE ASSY-HOOD, RH	Bent	87.00 FL	*87.00 FL
24	1		*PAD-HOOD INSULATING	Crushed	320.00 FL	*320.00 FL
25	1		*STRIP ASSY FR-HOOD	Torn	27.00 FL	*27.00 FL
26	1		*BRACKET-HOOD RELEASE CABLE MTG	Not Necessary	8.00 FL	*- FL
27	1		*LATCH ASSY-HOOD	Bent	104.00 FL	*104.00 FL
28	1		*CARRIER ASSY-FRONT END MODULE	Broken	760.00 FL	*760.00 FL
29	1		*BEAM COMPLETE-FR BUMPER	Bent	551.00 FL	*551.00 FL
30	1		*PANEL-FENDER, LH	Bent	502.00 FL	*502.00 FL
31	1		*PANEL-FENDER, RH	Repair	502.00 FL	*- FL
32	1		*GUARD ASSY-FRONT WHEEL, LH	Not Necessary	64.00 FL	*- FL
33	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	64.00 FL	*- FL
34	1		*GARNISH ASSY-FNDR SIDE, LH	Cut	88.00 FL	*88.00 FL
35	1		*GARNISH ASSY-FNDR SIDE, RH	Cut	88.00 FL	*88.00 FL
36	1		*COOLER ASSY-OIL	Not Necessary	316.00 FL	*- FL
37	1		*RADIATOR ASSY	Not Necessary	743.00 FL	*- FL
38	1		*BLOWER ASSY	Not Necessary	1,063.00 FL	*- FL
39	1		*AIR GUIDE	Broken	77.00 FL	*77.00 FL
40	1		*GUARD-AIR	Not Necessary	43.00 FL	*- FL
41	1		*DAM-AIR	Not Necessary	29.00 FL	*- FL
42	1		*COOLANT (4L)	Not Necessary	26.00 FN	*- FN
43	13		*CLIP-HOOD INSULATING PAD MTG	Necessary	13.00 FL	*13.00 FL
44	1		*CONDENSER ASSY-COOLER	Not Necessary	784.00 FL	*- FL
45	1		*COVER-COWL TOP, LH (Supplementary)	Crushed	21.00 FL	*21.00 FL
46	1		*COVER-COWL TOP, RH (Supplementary)	Crushed	24.00 FL	*24.00 FL
47	15		*CLIP (Supplementary)	Necessary	15.00 FL	*15.00 FL
48	1		*COVER ASSY-ENGINE (Supplementary)	Broken	241.00 FL	*241.00 FL
49	1		*COVER-FENDER APRON UPR, LH (Supplementary)	Crushed	25.00 FL	*25.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	17,243.00	12,229.00
- List Item Discount on L Items 20.00/20.00% (S\$)	3,439.40	2,441.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ULTRASONIC SENSOR S.P.A.S. SIDE (NPA)	New	0.00	0.00
2	RENEW FRT BUMPER, FRT SUPPORT, BONNET, LHF FENDER & RHF FENDER. REPAIR LHF DOOR, RHF DOOR & FRT A PILLAR LH / RH	New	3,200.00	1,400.00
3	RESPRAY FRT BUMPER, BONNET, LHF FENDER, RHF FENDER, LHF DOOR, RHF DOOR & FRT A PILLAR LH / RH	New	2,800.00	1,400.00
4	REMOVE & REFIT AIRCON CONDENSER & RADIATOR	New	100.00	0.00
5	TOP UP AIRCON GAS	New	80.00	0.00
6	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
9	REMOVE & REFIT FRT PARKING ASSIST SENSOR	New	60.00	60.00
10	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
11	SUPPLY BODY PNL SEALANT	New	60.00	40.00
12	APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS	New	6.40	0.00
13	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	400.00	400.00
14	SPRAY PAINT LH FRONT DOOR (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			7,336.40	3,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >