



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name | /CHEAH RUI'EN, LYNETTE (XIE RUI' |
| | Reg No/Reg Date | SMK2755E / 02/04/201 |
| | Date In/Mileage | / 0 |
| | Chassis No | KNAPH81BMK5523936 |
| | Engine No | D4HBH205598 |
| | Make/Model | KIA/SORENTO 2.2 A SR D EGD |
| | Colour/Trim | ABP AURORA BLACK / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | |
|--|--------|-------------------|-----|-------------------|------------|----------------------------|--------------|
| LAX00000 | Credit | 15/02/2021/ 19:23 | BLE | 261 / Edwin Caina | 28971 | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount |
| M SUNDRY ULTRASONIC SENSOR S.P.A.S. SIDE (TBA) KS96891C1000ABP | | | | 1 | | | 1299 3200.00 |
| E PNT88000 RENEW FRT BUMPER, FRT SUPPORT, BONNET, LHF FENDER & RH FENDER REPAIR LHF DOOR, RH DOOR & FRT A PILLAR LH/RH | | | | 3 X 490 | | | 1499 2800.00 |
| E PNT98000 RESPRAY FRT BUMPER, BONNET, LHF FENDER, RH FENDER, LHF DOOR, RH DOOR & FRT A PILLAR LH/RH | | | | 4 X 350 | | | 100.00 |
| E PNT88000 REMOVE & REFIT AIRCON CONDENSER & RADIATOR | | | | | | | 80.00 |
| M SUNDRY TOP UP AIRCON GAS | | | | | | | 30.00 |
| A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM | | | | | | | 120.00 |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | | | | | | | 50.00 |
| M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING | | | | | | | 60.00 |
| E PNT88000 REMOVE & REFIT FRT PARKING ASSIST SENSOR | | | | | | | 49 80.00 |
| M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS | | | | | | | 49 60.00 |
| M SUNDRY SUPPLY BODY PNL SEALANT | | | | | | | 6.40 |
| M SUNDRY APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS | | | | 80 X 4 = 320 | | (Provide Saller Agreement) | 20.00 |
| M SUNDRY Sundries | | | | 1.00 | 2743.00 | 20.00 | 2194.40 |
| M LAMP ASSY-HEAD, LH | | | | 1.00 | 2743.00 | 20.00 | 2194.40 |
| M LAMP ASSY-HEAD, RH | | | | 1.00 | 561.00 | 20.00 | 448.80 |
| M COVER-FR BUMPER UPR | | | | | | | |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | | | | | | | | | | | | | | |
|---|---|--------------|----------------------------------|-----------------|----------------------|-----------------|-----|------------|-------------------|-----------|--------------|------------|----------------------------|-------------|------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | <table> <tr> <td>Cust No/Name</td><td>/CHEAH RUI'EN, LYNETTE (XIE RUI'</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMK2755E / 02/04/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAPH81BMK5523936</td></tr> <tr> <td>Engine No</td><td>D4HBJH205598</td></tr> <tr> <td>Make/Model</td><td>KIA/SORENTO 2.2 A SR D EGD</td></tr> <tr> <td>Colour/Trim</td><td>ABP AURORA BLACK / WK SATURN BLACK</td></tr> </table> | Cust No/Name | /CHEAH RUI'EN, LYNETTE (XIE RUI' | Reg No/Reg Date | SMK2755E / 02/04/201 | Date In/Mileage | / 0 | Chassis No | KNAPH81BMK5523936 | Engine No | D4HBJH205598 | Make/Model | KIA/SORENTO 2.2 A SR D EGD | Colour/Trim | ABP AURORA BLACK / WK SATURN BLACK |
| Cust No/Name | /CHEAH RUI'EN, LYNETTE (XIE RUI' | | | | | | | | | | | | | | |
| Reg No/Reg Date | SMK2755E / 02/04/201 | | | | | | | | | | | | | | |
| Date In/Mileage | / 0 | | | | | | | | | | | | | | |
| Chassis No | KNAPH81BMK5523936 | | | | | | | | | | | | | | |
| Engine No | D4HBJH205598 | | | | | | | | | | | | | | |
| Make/Model | KIA/SORENTO 2.2 A SR D EGD | | | | | | | | | | | | | | |
| Colour/Trim | ABP AURORA BLACK / WK SATURN BLACK | | | | | | | | | | | | | | |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|----------------------------------|--------|-------------------|------------|-------------------|---------|
| LAX00000 | Credit | 15/02/2021/ 19:23 | BLE | 261 / Edwin Caina | 28971 |
| Description of Goods / Services | | Qty | Unit Price | Disc% | Amount |
| M MOULDING-FRT BPR LICENSE PLATE | ✓ BR | 1.00 | 20.00 | 20.00 | 16.00 |
| M LIP-FRONT BUMPER | ? | 1.00 | 56.00 | 20.00 | 44.80 |
| M SKID PLATE-FR BUMPER | ? | 1.00 | 111.00 | 20.00 | 88.80 |
| M MOULDING-FRONT BUMPER LWR,LH | ✓ | 1.00 | 89.00 | 20.00 | 71.20 |
| M MOULDING-FRONT BUMPER LWR,RH | ✓ | 1.00 | 89.00 | 20.00 | 71.20 |
| M GRILLE ASSY-RADIATOR | ✓ BR | 1.00 | 673.00 | 20.00 | 538.40 |
| M COVER ASSY-RADIATOR GRILLE UP | ✓ BR | 1.00 | 186.00 | 20.00 | 148.80 |
| M GRILLE-FRONT BUMPER | ? | 1.00 | 191.00 | 20.00 | 152.80 |
| M ABSORBER-FRONT BUMPER ENERGY | ? | 1.00 | 117.00 | 20.00 | 93.60 |
| M STIFFENER ASSY-FR BUMPER LWR | ✓ | 1.00 | 117.00 | 20.00 | 93.60 |
| M BRACKET-FR BUMPER SIDE,LH | ✓ | 1.00 | 17.00 | 20.00 | 13.60 |
| M BRACKET-FR BUMPER SIDE,RH | ✓ | 1.00 | 17.00 | 20.00 | 13.60 |
| M GRILLE-FRONT BUMPER FOG LAMP,L | ✓ | 1.00 | 81.00 | 20.00 | 64.80 |
| M GRILLE-FRONT BUMPER FOG LAMP,R | ✓ | 1.00 | 81.00 | 20.00 | 64.80 |
| M WIRING HARNESS-F.P.A.S | ? | 1.00 | 257.00 | 20.00 | 205.60 |
| M ULTRASONIC SENSOR ASSY-BWS | ? | 4.00 | 187.00 | 20.00 | 598.40 |
| M PANEL ASSY-HOOD | ✓ | 1.00 | 1654.00 | 20.00 | 1323.20 |
| M HINGE ASSY-HOOD,LH | ? | 1.00 | 87.00 | 20.00 | 69.60 |
| M HINGE ASSY-HOOD,RH | ? | 1.00 | 87.00 | 20.00 | 69.60 |
| M PAD-HOOD INSULATING | ✓ CRU | 1.00 | 320.00 | 20.00 | 256.00 |
| M STRIP ASSY FR-HOOD | ? | 1.00 | 27.00 | 20.00 | 21.60 |
| M BRACKET-HOOD RELEASE CABLE MTG | ✓ | 1.00 | 8.00 | 20.00 | 6.40 |
| M LATCH ASSY-HOOD | ? | 1.00 | 104.00 | 20.00 | 83.20 |
| M CLIP-HOOD INSULATING PAD MTG | ✓ APC | 13.00 | 1.00 | 20.00 | 10.40 |
| M CARRIER ASSY-FRONT END MODULE | ? | 1.00 | 760.00 | 20.00 | 608.00 |
| M BEAM COMPLETE-FR BUMPER | ? | 1.00 | 551.00 | 20.00 | 440.80 |
| R PANEL-FENDER,LH | ✓ R | 1.00 | 502.00 | 20.00 | 401.60 |
| R PANEL-FENDER,RH | ✓ R | 1.00 | 502.00 | 20.00 | 401.60 |
| M GUARD ASSY-FRONT WHEEL,LH | ✓ | 1.00 | 64.00 | 20.00 | 51.20 |
| M GUARD ASSY-FRONT WHEEL,RH | ✓ | 1.00 | 64.00 | 20.00 | 51.20 |
| M GARNISH ASSY-FNDR SIDE,LH | ✓ CUT | 1.00 | 88.00 | 20.00 | 70.40 |
| M GARNISH ASSY-FNDR SIDE,RH | ✓ CUT | 1.00 | 88.00 | 20.00 | 70.40 |
| M COOLER ASSY-OIL | ? | 1.00 | 316.00 | 20.00 | 252.80 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address | Owner Name & Vehicle Info | |
|--|---------------------------|------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name | /CHEAH RUI'EN, LYNETTE (XIE RUI') |
| | Reg No/Reg Date | SMK2755E / 02/04/201 |
| | Date In/Mileage | / 0 |
| | Chassis No | KNAPH81BMK5523936 |
| | Engine No | D4HBJH205598 |
| | Make/Model | KIA/SORENTO 2.2 A SR D EGD |
| | Colour/Trim | ABP AURORA BLACK / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|--------|-------------------|-----|-------------------|--------|------------|-------|--------|
| LAX00000 | Credit | 15/02/2021/ 19:23 | BLE | 261 / Edwin Caina | 28971 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| M CONDENSER ASSY-COOLER | | | | | 1.00 | 784.00 | 20.00 | 627.20 |
| M RADIATOR ASSY | | | | | 1.00 | 743.00 | 20.00 | 594.40 |
| M BLOWER ASSY | | | | | 1.00 | 1063.00 | 20.00 | 850.40 |
| M AIR GUIDE | | | | | 1.00 | 77.00 | 20.00 | 61.60 |
| M GUARD-AIR | | | | | 1.00 | 43.00 | 20.00 | 34.40 |
| M DAM-AIR | | | | | 1.00 | 29.00 | 20.00 | 23.20 |
| M COOLANT (4L) | | | | | 1.00 | 26.00 | 23.00 | 20.02 |

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Steve (LKK)
 SURVEYOR SIGNATURE: 16/2/21, 19:30 am
 DATE: 00-NM AL
 REMARKS: Excess - ?
P/P
By Bel SM
5 days

Confirm & accepted by

| | |
|----------------------|------------------|
| Nett | 20,123.22 |
| 7% GST on | 20123.22 |
| Total Payable | 21,531.85 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.