

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel. 65684555 Fax: 65651240

Co Reg No : 199405410K

GST Reg No : MR-8500111-X **ESTIMATE** Owner Name & Vehicle Info Invoice Name & Address /CHEAH RUI'EN, LYNETTE (XIE RUI' AIG Asia Pacific Insurance Pte. Cust No/Name / 02/04/201 Reg No/Reg Date SMK2755E Ltd. MOTOR CLAIM DEPARTMENT Date In/Mileage 78 SHENTON WAY #09-16 KNAPH818MK5523936 Chassis No AIG RUILDING D4HBJH205598 Engine No SINGAPORE 079120 KIA/SORENTO 2.2 A SR D EGD Make/Model Contact No 64191000 ABP AURORA BLACK / WK SATURN BLACK Colour/Trim

A a a a sum a Ata			CCE	Operator		WIP No			
Account No	Terms	Date/Time Printed	CSE	261 / Edwin Ca	ina	28971			
LAX00000	Credit	15/02/2021/ 19:23	BLE		Qty	Unit Price	Disc%	Amo	unt
		Description of Good	\$ / Service	3					
KS96891C E PNT88000 RENEW FR REPAIR L E PNT98000 RESPRAY LHF DOOR E PNT88000 REMOVE & M SUNDRY TOP UP A	TOOOABP TOUMPER HE DOOR FRTOUMPE REFIT A	R S.P.A.S. SIDE (TBA FRT SUPPORT, BON RHF DOOR & FRT A P ER, BONNET, LHF FE OOR & FRT A PILLAR L IRCON CONDENSER SIRA S CTRICAL SYSTEM & ADJ	INET , LHF FILLAR LH/I INDER , RHI IH/RH	f ¹ fender . 4			1498	1499 ²	200.00 800.00 100.00 80.00 30.00
A 10028901 TO CARRY USING HI	OUT DIAG	GNOSTIC CHECK USING						W and	50.00
F DNTOONIN		RT PARKING ASSIST SE	NSOR					42	80.00
	TI CORROS	SION ON AFFECTED ARE	AS					40	60.00
M SUNDRY SUPPLY B M SUNDRY APPLY ZE		SEALANT INT PROTECTION ON AF	FECTED AR	EAS 80 X 4	= 320 (Provide Salur	Agizand)		20.00
M SUNDRY Sundries M LAMP ASS M LAMP ASS M COVER-FI	SY-HEAD, L SY-HEAD, R				1.00 1.00 1.00	2743.0	0 20.00 0 20.00 0 20.00	<i>V</i> .	2194.40 2194.40 448.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen. Page 1 of 3



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

g No : 199405410K	ESTIMATE	GST Reg No : MR-850 Owner Name & Vehicle Info
Invoice Name & Address		/CHEAH RUI'EN, LYNETTE (XIE R
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Engine No	SMK2755E / 02/04/201

					A commence of the commence of	and the second of the second o	WIP No	The second secon	
	Terms	Date/Time Printed	CSE	Oper	ator		28971		
Account No		15/02/2021/ 19:23	BLE	261	/ Edwin Cai	Ohr	Unit Price	Disc%	Amount
_AX00000	Credit	Description of Goods	/ Services			the second section of	20.00	20.00	16.0
		LICENSE PLATE	0		HE .	1.00	56.00	20.00	44.8
M MOULDING-	FRT BPR	LICENSE PLATE	`			1.00 1.00	111.00	20.00	88.8
M I IP-FRONT	BUMPER	4 4 1 7 1				1.00	89.00	20.00	71.2
M SKID PLAT	E-FR BUI		,			1.00	89.00	20.00	71.2
M MOULDING-	FRONT B	UMPER LWK, LT / A/A	J			1.00	673.00	20.00	538.4
M MOULDING-	EKONI B	DMAEK FMY YOU				1.00	186.00	20.00	148.8
M GRILLE AS	SY-RADIA	TOP GRILLE UPR / BR				1.00	191.00	20.00	152.8
M COVER ASS	Y-RADIA	on direct of	~^			1.00	117.00	20.00	93.6
M GRILLE-FR	ONT BUMP	LN - 1 /	BR			1.00	117.00	20.00	93.6
M ABSORBER-	FRONI BU	IMPER ENERGY :	.I			-1.00	17.00	20.00 /	13.6
M STIFFENER	ASSY-FR	OUTILE THE	' п			_ 71.00	17.00	20.00 /	13.6
M BRACKET-F	K ROWLER			Π Γ	\sim)	81.00	20.00	64.8
M BRACKET-F	K ROWLER	SIDE, RH	DAY		Π		81.00		64.8
1 GRILLE-FR	ONI BUMP	ER FOG LAMP	ا کا سم	U U I		1 G. W	257.00	20.00	205.
4 GRILLE-FR	INI BUMP	PER FOG LAMPLE TO				1.00	187.00		598.
WIRING HA	(NE22-L.	r.n.s . /				1.00	1654.00		1323.2
ULTRASONI	, JENSON	7331 5110					87.00		69.
PANEL ASS	-HOOD 4					1.00	87.00		69.
HINGE ASS	HOOD D	1 / 67				1.00	320.00		256.
HINGE ASSY	ACHI ATT	NG / CRU				1.00	27.00	NAME AND DESCRIPTION OF THE PARTY OF THE PAR	21.
STRIP ASSI	LO HOU	1 / TN				1.00	8.00		6.4
SIKIP ASSI	OD DELE	ASE CABLE MTG X AM	1			1.00	104.00		83.3
	שאטט אננני	9 / 10				1.00	1.00		10.
LAICH ASSI	THIS HILL AT	ING PAD MTG				13.00	760.00		608.0
CADDIED AS	CY_FRON	T END MODULE ?	/ BR			1.00	551.00		440.8
BEAM COMPL	FTF_FR I	BUMPER 1 / OT				1.00	502.00	_	401.
		R V OT				1.00	502.00	STAND OF CAME OF PARTY PROPERTY.	401.
		ρ .				1.00	64.00		51.2
PANEL-FENL GUARD ASSI	-FRONT	wissi ili J MIN				1.00	64.00	20.00	51.2
GUARD ASSI	-FRONT	LILICCI DU Y				1.00	88.00	20.00	70.4
GARNISH AS	SY-FNDR	SIDE, LH / (U)				1.00	88.00	20.00	70.4
GARNISH AS	SY-FNDR	SIDE, RH / 147				1.00	316.00		252.8
1 COOLER ASS						1.00	310.00	20.00	252.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

- Walter and All Control of the Cont		3, 73, 73			
Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	/CHEAH RUI'EN, LYNETTE (XIE RUI'			
Ltd.	Reg No/Reg Date	SMK2755E / 02/04/201			
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0			
78 SHENTON WAY #09-16	Chassis No	KNAPH818MK5523936			
AIG BUILDING		D4HBJH205598			
SINGAPORE 079120 Contact No 64191000	Make/Mode1	KIA/SORENTO 2.2 A SR D EGD			
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	15/02/2021/ 19:23	BLE	261 / Edwin Caina		28971		
LAXUUUUU	Credit	Description of Goods			Qty	Unit Price	Disc%	Amount
M CONDENSER M RADIATOR M BLOWER AS M AIR GUIDE M GUARD-AIR	ASSY 1	the same of the sa	, Co. vices		1.00 1.00 1.00 1.00 1.00		20.00	627.20 594.40 850.40 61.60 34.40 23.20

Estimate

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis	SURVEYOR NAME: Steve (LKK) SURVEYOR SIGNATURE: 16/1/11, 19.30 am DATE: FX CCSS - 9
No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company	REMARKS: P/P BeL SM
Acknowledged by Repairer	7 W. day
Signature:	+ A ways
Cores	V

Confirm & accepted by

Nett 20123.22 7% GST on

20,123.22 1408.63

Total Payable

21,531.85

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.