

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21002161/KPA3Q2
Date: 05/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070121232
Claimant Vehicle No :	SHF665E	Insured Vehicle No :	SMU8803H
Date of Loss:	08/02/2021	Nature of Claim:	TP
		Claim No:	5599009744SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF665E	Engine No:	2ZR2G77536
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU903091301
Reg. Date:	14/08/2020 (Man. Year: 2020)	Odometer:	56906 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,449.50	1,825.70	7,623.80	80.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,930.00	1,660.00	46.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,039.50	3,755.70	9,283.80	71.20
+ GST 7.00/7.00% (S\$)	912.77	262.90	649.87	71.20

Nett Amount (S\$)	13,952.27	4,018.60	9,933.67	71.20
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$81.13/day) (S\$)		324.52		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,550.57		
Global Sum Settlement (S\$)		4,550.00		

INSPECTION

Date of Assignment: 15/02/2021

Date Inspected: 15/02/2021

Estimated Period of Repair: 5.0 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER SUB-ASSY ,FRONT LH	Repair	977.80 FL	*- FL
2	1		*EMBLEM ,SIDE PANEL	Necessary	54.60 FL	*54.60 FL
3	1		*PANEL SUB-ASSY ,FRONT DOOR ,LH	Bent / Warped	1,300.70 FL	*1,300.70 FL
4	1		*WEATHERSTRIP ,FRONT DOOR ,LH	Serviceable	231.30 FL	*- FL
5	1		*HINGE ASSY ,FRONT DOOR ,LOWER LH	Repair	110.60 FL	*- FL
6	1		*HINGE ASSY ,FRONT DOOR ,UPPER LH	Repair	97.50 FL	*- FL
7	1		*TAPE ,BLACK OUT ,NO.1 FRT LH	Necessary	13.30 FL	*13.30 FL
8	1		*TAPE ,BLACK OUT ,NO.2 FRT LH	Necessary	43.50 FL	*43.50 FL
9	1		*TAPE ,BLACK OUT ,NO.3 FRT LH	Necessary	26.30 FL	*26.30 FL
10	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,FRT LH	Serviceable	926.00 FL	*- FL
11	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,LH	Serviceable	238.30 FL	*- FL
12	1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Repair	1,294.90 FL	*- FL
13	1		*WEATHERSTRIP ,REAR DOOR OPENING TRIM LH	Serviceable	293.00 FL	*- FL
14	1		*HINGE ASSY ,REAR DOOR ,LOWER LH	Repair	87.10 FL	*- FL
15	1		*HINGE ASSY ,REAR DOOR ,UPPER LH	Repair	98.90 FL	*- FL
16	1		*TAPE ,BLACK OUT ,NO.1 REAR LH	Not Necessary	21.90 FL	*- FL
17	1		*TAPE ,BLACK OUT ,NO.2 REAR LH	Not Necessary	34.90 FL	*- FL
18	1		*TAPE ,BLACK OUT ,NO.3 REAR LH	Not Necessary	15.40 FL	*- FL
19	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,LH	Serviceable	926.00 FL	*- FL
20	1		*REGULATOR SUB-ASSY ,REAR DOOR WINDOW ,LH	Serviceable	206.70 FL	*- FL
21	1		*PANEL SUB-ASSY ,QUARTER ,LH	Repair	871.50 FL	*- FL
22	1		*LINER ,REAR WHEEL HOUSE ,LH	Serviceable	139.80 FL	*- FL
23	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Dented / Distorted	594.80 FL	*594.80 FL
24	2		*FENDER CLIP	Not Necessary	130.00 FS	*- FS
25	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
26	1		*FRT BUMPER CLIP	Not Necessary	65.00 FS	*- FS
27	2		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	130.00 FS	*- FS
28	1		*FRT DOOR STICKER TRANSCAB	Necessary	100.00 FS	*60.00 FS
29	1		*TYRE	Serviceable	350.00 FS	*- FS
30	1		*RIM	Serviceable	1,879.40 FS	*- FS
31	1		*HUB CAP	Dented	211.50 FS	*175.80 FS
32	1		*SET CLIP ,ROCKER PANEL MOULDING	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,600.70	2,334.00
- List Item Discount on L Items 25.00/25.00% (\$)	2,151.20	508.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (\$)	9,449.50	1,825.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	500.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	1,320.00
4	TO RUST-PROOFING OF APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
			Gross Labour Cost (S\$)	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >