

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002165/EQF3Q2
Date: 18/03/2021

REFERENCE

Insured/Claimant:	ONG JOO LEONG	Policy No:	2100409544	
Date of Loss:	12/02/2021	Nature of Claim:	OD	Claim No: 7419341581SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS4896A		
Make & Model:	MITSUBISHI LANCER, 1.3 (A)	Engine No:	4A92BT6268
Reg. Date:	20/04/2015 (Man. Year: 2015)	Chassis No:	JMYSRCY1AFU004153
Colour:	Red	Odometer:	88252 km
Engine Capacity:	1590 cc		
Market Value/New Car Price:	S\$43,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,510.00	1,945.77	1,564.23	44.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,760.00	3,205.00	2,555.00	44.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,270.00	5,150.77	4,119.23	44.44
+ GST 7.00/7.00% (S\$)	648.90	360.55	288.35	44.44
Nett Amount (S\$)	9,918.90	5,511.32	4,407.58	44.44

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
2	1		*MARK LANCER	Necessary	58.00 F	*58.00 FL
3	1		*LED TAILLAMP, BOOT-LH	Cut	214.00 F	*214.00 FL
4	1		*LED TAILLAMP, FENDER-LH	Broken	280.00 F	*280.00 FL
5	1		*BRKT, R/BMPR FACE SUPT, RH	Not Necessary	17.00 F	*- FL
6	1		*BRKT, R/BMPR FACE SUPT, LH	Broken	17.00 F	*17.00 FL
7	1		*FACE, RR BUMPER	Broken	865.00 F	*865.00 FL
8	1		*REINFORCEMENT, RR BUMPER	Not Necessary	233.00 F	*- FL
9	1		*HINGE, TRUNK LID, RH	Not Necessary	93.00 F	*- FL
10	1		*HINGE, TRUNK LID, LH	Not Necessary	93.00 F	*- FL
11	1		*WEATHERSTRIP, TRUNK LID	Crushed	184.00 F	*184.00 FL
12	1		*STRIKER, TRUNK LID LATCH	Not Necessary	24.00 F	*- FL
13	1		*LATCH, TRUNK LID	Not Necessary	74.00 F	*- FL
14	1		*PANEL, TRUNK LID	Dented	772.00 F	*772.00 FL
15	1		*MARK, THREE-DIA	Necessary	70.00 F	*70.00 FL
16	1		*MARK, EX	Necessary	41.00 F	*41.00 FL
17	1		*REFLECTOR	Not Necessary	37.00 F	*- FL
18	1		*LAMP ASSY, LICENSE PLATE	Not Necessary	35.00 F	*- FL
19	1		*LAMP AS, HIGH MOUNTED STOP	Not Necessary	373.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,510.00	2,521.00
- List Item Discount on L Items 0.00/23.00% (\$)	0.00	575.23
Total Parts (\$)	3,510.00	1,945.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESPRAY ACCIDENT DAMAGED PORTION REAR BUMPER, REAR END PANEL, BOOT LID LH REAR FENDER	New	1,750.00	1,050.00
2	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	60.00	30.00
3	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
4	SUPPLY ANTI CORROSION	New	160.00	0.00
5	SUPPLY BODY SEALANT	New	80.00	40.00
6	RENEW ACCIDENT DAMAGED PORTION ON REAR BUMPER, REAR END PANEL, BOOT LID, REPAIR LHR FENDER	New	2,250.00	900.00
7	REMOVE AND INSTALL REAR COMPARTMENT TRIM TO FACILITATE REPAIRS	New	225.00	0.00
8	TRANSFER BOOT LID TRIM, MECHANISM, ELECTRONICS TO NEW BOOT LID	New	225.00	225.00
9	SUPPLY C&C EMBLEM	New	40.00	40.00
10	SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	0.00
11	REPAIR LH UPPER TAIL LAMP HOUSING PANEL	New	450.00	450.00
12	SPRAY PAINT LH TAIL LAMP HOUSING	New	350.00	350.00
Gross Labour Cost (\$\$)			5,760.00	3,205.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >