

CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Ong Joo Leong Blk 604 Senja Road #17-21 Singapore 670604 Contact No Mobile: 90938093	Cust No/Name / Ong Joo Leong Reg No/Reg Date SKS4896A / 20/04/201 Date In/Mileage / 88252 Chassis No JMYSRCYIAFU004153 Engine No 4A92BT6268 Make/Model MIT/LANCER EX 1.6 GLS 4A/T (F05) Colour/Trim P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	15/02/2021/ 11:24	QUA	265 / AndreChow	62907


Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT9S000 RESPRAY ACCIDENT DAMAGED PORTION REAR BUMPER, REAR END PANEL, BOOT LID LH REAR FENDER	350 X 3			1750.00 1050
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30 60.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUPPLY ANTI CORROSION				? 160.00
M SUNDRY SUNDRIES				20 30.00
M SUNDRY SUPPLY BODY SEALANT				40 80.00
E PNT88000 RENEW ACCIDENT DAMAGED PORTION ON REAR BUMPER, REAR END PANEL, BOOT LID, REPAIR LHR FENDER	450 X 2			900 2250.00
E PNT88000 REMOVE AND INSTALL REAR COMPARTMENT TRIM TO FACILITATE REPAIRS	(photo)			? 225.00
E PNT88000 TRANSFER BOOT LID TRIM, MECHANISM, ELECTRONICS TO NEW BOOT LID				40.00
M SUNDRY SUPPLY C&C EMBLEM				50.00
M SUNDRY SUPPLY REAR NUMBER PLATE WITH FRAME	1.00	58.00	00.00	58.00
M MARK, LANCER	1.00	214.00	00.00	214.00
M LED TAILLAMP, BOOT-LH	1.00	280.00	00.00	280.00
M LED TAILLAMP, FENDER-LH	1.00	17.00	00.00	17.00
M BRKT, R/BMPR FACE SUPT, RH	1.00	17.00	00.00	17.00
M BRKT, R/BMPR FACE SUPT, LH	1.00	861.00	00.00	861.00
M FACE, RR BUMPER	1.00	233.00	00.00	233.00
M REINFORCEMENT, RR BUMPER	1.00	93.00	00.00	93.00
M HINGE, TRUNK LID, RH				

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ong Joo Leong	Cust No/Name /Ong Joo Leong
Blk 604 Senja Road	Reg No/Reg Date SKS4896A / 20/04/201
#17-21	Date In/Mileage / 88252
Singapore 670604	Chassis No JMYSRCYIAFU004153
Contact No Mobile: 90938093	Engine No 4A92BT6268
	Make/Model MIT/LANCER EX 1.6 GLS 4A/T (F05)
	Colour/Trim P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	15/02/2021/ 11:24	QUA	265 / AndreChow	62907

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M HINGE, TRUNK LID, LH ?	1.00	93.00	00.00	93.00
M WEATHERSTRIP, TRUNK LID ✓ CR4	1.00	184.00	00.00	184.00
M STRIKER, TRUNK LID LATCH X	1.00	24.00	00.00	24.00
M LATCH, TRUNK LID ?	1.00	74.00	00.00	74.00
M PANEL, TRUNK LID / DD	1.00	768.00	00.00	768.00
M MARK, THREE-DIA - MC	1.00	69.00	00.00	69.00
M MARK, EX - MC	1.00	41.00	00.00	41.00
M REFLECTOR ?	1.00	37.00	00.00	37.00
M LAMP ASSY, LICENSE PLATE X	1.00	35.00	00.00	35.00
M LAMP AS, HIGH MOUNTED STOP X	1.00	373.00	00.00	373.00

Estimate

SURVEYOR NAME : Steve (LKK)
 SURVEYOR SIGNATURE : DD-MY AL
 DATE : EXCISI -!
 REMARKS : PIP
My BL say
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Confirm & accepted by _____
- Subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

As Endorsed by Repairer

Authorized signatory and company stamp

	Nett	8,461.00
7% GST on	8461.00	592.27
	Total Payable	9,053.27

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.