

CYCLE & CARRIAGE

AIG-OD (REVERT)
SURVEY: 15/02/21
LKK - STEVE

VEHICLE NO : SKS 4896A

MODEL : MIT/LANCER EX 1.6 GLS 4A/T

WIP : 62907

Material	:	\$	<u>1,925.77</u>
Labour	:	\$	<u>3,225.00</u>
Sub-Total	:	\$	<u>5,150.77</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>5,150.77</u>
GST 7%	:	\$	<u>360.55</u>
Grand Total	:	\$	<u>5,511.32</u>
Finalise By/Date	:	<u>LARRY ON 25/02/21</u>	

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 06 WORKING DAYS + 2 days (wk end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for a Mitsubishi Lancer EX 1.6 GLS 4A/T (F05).

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: KAX0008, Credit, 25/02/2021/ 09:06, BLA, 884 / Lauro Songcuan, 62907

Main invoice table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various services like 'SPRAY PAINT DAMAGED PORTIONS REAR BUMPER' and 'CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM'.

Pro Forma watermark

* - change price

This is not an official tax invoice. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-


Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 15/02/2021	Cust No/Name	/Ong Joo Leong
	Reg No/Reg Date	SKS4896A / 20/04/2015
	Date In/Mileage	16/02/2021/ 88252
	Chassis/Package	JMYSRCY1AFU004153
	Engine No	4A92BT6268
	Make/Model	MIT/LANCER EX 1.6 GLS 4A/T (F05)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	25/02/2021/ 09:06	BLA	884 / Lauro Songcuan	62907

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
DOA: 12.02.2021 SURVEY: STEVE (LKK) 15.02.2021 06 DAYS				
Pro Forma				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	1,925.77			
Labour	3,125.00			
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	100.00			
Total(w/o GST)	5,150.77			
		7% GST on	5150.77	360.55
			Total Payable	5,511.32

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SKS 4896 A**

	<u>Labour</u>	<u>Cost \$</u>
1	Repair LH Upper Tail Lamp Housing Panel	450.00 ✓
2	Spray Paint LH Tail Lamp Housing	350.00 ✓
		<u>800.00</u>
	7% GST	56.00
	Total	<u>856.00</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SKS4896B

WIP: 62907

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	<i>Trench / od</i>	? / SUPP		<i>OP</i>	<i>Store 16/2/21</i>
2	REPAIR LH UPP TAILAMP HOUSING PANEL	? / SUPP	\$450	<i>✓</i>	
3	PANTRYORK LH TAILAMP PANEL	? / SUPP	\$350	<i>✓</i>	<i>Store 18/2/21</i>
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14	<i>Additional 01 Days LHS = 6 Days</i>	? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	<i>18/2/21</i>	<i>Steve</i>
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Lanner Ex

SURVEYOR: Steve

All DTCS

Item	Setting Information
M.U.T.-3 Version V.C.I. Version	SEW20091-00 B178
Vehicle Information	CY1A 2015MY

SK24896A
Please use Profix NA unit to check all the bands.

2021.02.24

All DTCS

2021.02.24

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCS	
AT/CVT/A-MTTC-SST	AT4_10801005		No DTCS	
ABS/ASC/ASTC/WSS	ABS_4088000E		No DTCS	
SRS-AIR BAG	ORC_81087196		No DTCS	
Air Conditioner	AC_80080006		No DTCS	
ETACS (Can't see P/N on ECU body)	ETACS_83040900	B16A4 B16A2	Turn signal(RH) bulb outage Turn signal(LH) bulb outage	Stored Stored
Meter	MTR_84084000		No DTCS	
Steering Angle Sensor	GS_SAS_47000100		Non-equipped System or Communication Error	
LIN (Can't see P/N on ECU body)	ETACS_83040900		Non-target System	
KOS/iMMO/Keyless/TPMS (iMMOBI & KOS)	KOS_WCM_8A880001_08MY	B240C B1A11	Tail gate antenna(outdoor) open Keyless/KOS key 2 low battery	Stored Active
AFS/ACL/Leveling	AFS_90080000		Non-equipped System or Communication Error	

All DTCS

Item	Setting	Information
M.U.T.-3 Version		SEW20091-00
V.C.I. Version		B178
Vehicle Information		CY1A 2015MY

SKS489GA
After you MORT-3x Not inst to Base all the good
to Job Done

2021.02.24

All DTCS

2021.02.24

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCS	
AT/CVT/A-MTTC-SST	AT4_10801005		No DTCS	
ABS/ASC/ASTC/WSS	ABS_4088000E		No DTCS	
SRS-AIR BAG	ORC_81087196		No DTCS	
Air Conditioner	AC_80080006		No DTCS	
ETACS (Can't see P/N on ECU body)	ETACS_83040900		No DTCS	
Meter	MTR_84084000		No DTCS	
Steering Angle Sensor	GS_SAS_47000100		Non-equipped System or Communication Error	
LIN (Can't see P/N on ECU body)	ETACS_83040900		Non-target System	
KOS/IMMO/Keyless/TPMS (IMMOBI & KOS)	KOS_WCM_8A880001_08MY	B1A11	Keyless/KOS key 2 low battery	Active
AFS/ACL/Leveling	AFS_90080000		Non-equipped System or Communication Error	