

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG21002166/EQF3Q2
Date: 18/03/2021**REFERENCE**Insured/Claimant: SIA TZE YIN (XIE ZHIYUN) Policy No: 1800029180
Date of Loss: 14/02/2021 Nature of Claim: OD Claim No: 7057997707SG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLX4466U**
Make & Model: MITSUBISHI SPACE STAR, 1.2 CVT (A) Engine No: 3A92UGT8993
Reg. Date: 28/03/2018 (Man. Year: 2018) Chassis No: MMCXTA03AJH020666
Colour: Black Odometer: 28943 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$51,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size: 175/55 R15 Rear Tyre Size: 175/55 R15
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,777.00	4,119.48	2,657.52	39.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,120.00	3,150.00	1,970.00	38.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,897.00	7,269.48	4,627.52	38.90
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	11,597.00	6,969.48	4,627.52	39.90
+ GST 7.00/7.00% (S\$)	811.79	487.86	323.93	39.90
Nett Amount (S\$)	12,408.79	7,457.34	4,951.45	39.90

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FACE ,FR BUMPER	Dented	751.00 F	*751.00 FL
3	1		*AIR DAM SIDE,FR RH	Not Necessary	18.00 F	*- FL
4	1		*BRACKET ,FR BUMPER SIDE ,RH	Not Necessary	7.00 F	*- FL
5	1		*BRACKET ,FR BUMPER SIDE ,LH	Not Necessary	7.00 F	*- FL
6	1		*AIR DAM ,SIDE ,FR LH	Not Necessary	18.00 F	*- FL
7	1		*COVER,FR BUMPER GRILLE	Broken	161.00 F	*161.00 FL
8	1		*GRILLE ,ASSY ,RADIATOR	Broken	406.00 F	*406.00 FL
9	1		*GARNISH ,FR BUMPER ,RH	Not Necessary	53.00 F	*- FL
10	1		*GARNISH ,FR BUMPER ,LH	Not Necessary	53.00 F	*- FL
11	1		*GARNISH ,FR BUMPER SIDE ,RH	Not Necessary	173.00 F	*- FL
12	1		*GARNISH ,FR BUMPER SIDE ,LH	Not Necessary	173.00 F	*- FL
13	1		*GARNISH ,FR BUMPER ,CTR	Not Necessary	190.00 F	*- FL
14	1		*MARK ,THREE ,DIA	Necessary	70.00 F	*70.00 FL
15	1		*HOOD	Repair	615.00 F	*- FL
16	1		*LATCH HOOD	Not Necessary	118.00 F	*- FL
17	1		*FENDER ,FR RH	Dented	435.00 F	*435.00 FL
18	1		*PANEL ASSY ,FR END	Dented	797.00 F	*797.00 FL
19	1		*PANEL ,AIR GUIDE SIDE ,RH	Not Necessary	8.00 F	*- FL
20	1		*HEADLAMP ASSY ,RH	Crushed	1,842.00 F	*1,842.00 FL
21	1		*CONDENSER ASSY,A/C REFRIGE	Bent	762.00 F	*762.00 FL
			Supplementary			
22	1		*PANEL,AIR GUIDE	Broken	100.00 F	*100.00 FL
			Supplementary			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,777.00	5,344.00
- List Item Discount on L Items 0.00/23.00% (\$\$)	0.00	1,224.52
Total Parts (\$\$)	6,777.00	4,119.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER ,FRT FENDER RH ,BONNET ,REPAIR FRT FENDER LH FRT AIRDAM ,FRT SUPPORT PANEL	New	1,800.00	900.00
2	REMOVE & INSTALL FRT AIRDAM	New	100.00	80.00
3	SPRAY PAINT FOR FRT AIRDAM ,FRT BUMPER ,BONNET ,FRT FENDER RH& LH FRT SUPPORT PANEL	New	2,100.00	1,050.00
4	FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	RENEW FRT SUPOORT Supplementary	New	450.00	450.00
8	SPRAY FRT SUPOORT Supplementary	New	350.00	350.00
9	TOPUP A/C GAS Supplementary	New	120.00	120.00
Gross Labour Cost (S\$)			5,120.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >