

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 6662E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CRUMPLED	1,885.80	928.50
1	FRONT BUMPER SIDE RETAINER	SERVICEABLE	85.00	-
1	FRONT BUMPER BRACKET	SERVICEABLE	48.00	-
10	FRONT BUMPER CLIPS	SERVICEABLE	80.00	-
1	HEADLAMP ASSEMBLY	CRACKED	3,125.00	2,465.70
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	625.00	-
1	FRONT FOG LAMP COVER	CRUMPLED	150.00	150.00
	LESS 25% DISCOUNT		-1,499.70	-886.05
			4,499.10	2,658.15
	SPECIAL NETT ITEMS			
1	FRONT FOG LAMP (SN)	CRACKED	180.00	180.00
1	FRONT HEADLAMP WASHER (SN)	CRUMPLED	215.00	215.00
1	FRONT HEADLAMP WASHER BRACKET (SN)	NECESSARY	85.00	85.00
			480.00	480.00
	<u>LABOUR</u>			
	TO CHECK AND RECONNECT SNAP WIRING.		180.00	30.00
	TO TUFF COAT AFFECTED AREAS.		180.00	30.00
	TO RESPRAY AFFECTED AREAS.		1,400.00	200.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR FRONT CHASSIS MEMBER AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,600.00	250.00
	TO POLISH AND PROTECTION COATING FOR NEW PAINT.	NOT NECESSARY	1,000.00	-
			4,360.00	510.00
	GRAND TOTAL		9,339.10	3,648.15



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,900.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/III20010618/Qqf3e2-1

Ja

OI SUN PIN

Asst. Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.