

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP20090034

Date: 15 Jan 2021

Don Teo Aeng Soon
c/o Sheng Khoon Motor Service
Blk 4 Yew Tee Ind Est 393
Woodlands Road
Singapore 677972

THIRD PARTY SURVEY ACCIDENT OCCURED ON 16 Sept 2020

Workshop Name and Address

Sheng Khoon Motor Service
Blk 4 Yew Tee Ind Est 393
Woodlands Road
Singapore 677972

As per your instruction dated 05 OCT 2020
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SMC6662E

1. VEHICLE PARTICULARS

Registration No : SMC6662E
Model : TOYOTA LEXUS RX350
Year / Capacity : Mar 2010/ 1496 cc
Chassis No : JTJBK11AX02423153

Engine No : 2GRJ214673
Mileage : 194 597 km
Colour : Metallic Blue

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	235/60/R18	Prelli	9.00 mm	Sport
REAR O/S :	235/60/R18	Prelli	9.00 mm	Sport
FRONT N/S :	235/60/R18	Prelli	9.00 mm	Sport
REAR N/S :	235/60/R18	Prelli	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **front side** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 10 working days to complete
5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SMC6662E

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>List Items</u>				
1 pc	Front bumper / CR4	bent	\$ 1,885.80	\$ 1,885.80 782.1
1 pc	Front bumper side retainer XSV	reuse	\$ 85.00	\$ 85.00 X
1 pc	Front bumper bracket XVL	reuse	\$ 48.00	\$ 48.00 X
10 pcs	Front bumper clips XSV	reuse	\$ 80.00	\$ 80.00 X
1 pc	Headlamp assembly / CnA	electronically shocked	\$ 3,125.00	\$ 3,125.00 1,654
1 pc	Front support panel X R	bent - repair	\$ 625.00	\$ -
1 pc	Front fog lamp cover / CRU	grazed	\$ 150.00	\$ 150.00 /
Parts Sub-Total			\$ 5,998.80	\$ 5,373.80 2,586.10
Discount 25.00%			\$ 1,499.70	\$ 1,343.45 -25%
			\$ 4,499.10	\$ 4,030.35 1,919.58

Vehicle Number : SMC6662E

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Nett Items</u>				
1 pc	Front fog lamp / CR4	electronically shocked	\$ 180.00	\$ 180.00 /
1 pc	Front headlamp washer CRU	broken	\$ 215.00	\$ 215.00 /
1 pc	Front headlamp washer bracket / Nec	broken	\$ 85.00	\$ 85.00 /
Special Nett Sub-Total			\$ 480.00	\$ 480.00 480
Spare Parts Total			\$ 4,979.10	\$ 4,510.35

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
------	------------------	---------------------------	------------------------------

	Spare PartsTotal c/f	\$ 4,979.10	\$ 4,510.35
1	To check and reconnect snap wiring	\$ 180.00	\$ 150.00 30
2	To tuff coat affected areas	\$ 180.00	\$ 150.00 30
3	To respray affected areas	\$ 1,400.00	\$ 1,200.00 200
4	To renew damaged parts, straighten and repair front chassis member and aligned all parts.	\$ 1,600.00	\$ 1,400.00 250
5	To polish and protection coating for new paint	\$ 1,000.00	\$ 1,000.00X
	Total	\$ 9,339.10	\$ 8,410.35 510

The repairer has agreed to undertake the repair under lump Sum Basis. We have further adjusted the amount to a lump Sum Repair of :

\$ 7,150.00


Fong Kok Heng
Qualified Appraiser



1,939.58
480
510

2,929.58
- 20%

2,343.66

L/S
\$ 2,350
3 days