



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 2708X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT MUDGUARD	CRUMPLED	75.00	75.00
1	FRONT WHEEL	BENT	350.00	350.00
1	FRONT WHEEL BEARING	JAMMED	50.00	50.00
1	FRONT WHEEL AXLE	BENT	60.00	60.00
1	BRAKE DISC	SERVICEABLE	165.00	-
2	FRONT FORK ASSY LH & RH @\$240.00	BENT	480.00	480.00
1	STEM STEERING	BENT	165.00	90.00
1	HANDLEBAR	BENT	80.00	80.00
1	CLUTCH LEVER	SCRATCHED	40.00	40.00
1	BRAKE LEVER	SCRATCHED	40.00	40.00
1	BRAKE MASTER CYLINDER (NPA)	SERVICEABLE	-	-
2	BALANCER @\$25.00	CRUMPLED	50.00	50.00
2	SIDE MIRROR @\$30.00	MISSING	60.00	60.00
1	FRONT HEADLIGHT COVER	CRUMPLED	60.00	60.00
1	REAR HEADLIGHT COVER	SERVICEABLE	60.00	-
1	HEADLIGHT ASSY	SCRATCHED	160.00	160.00
1	FRONT MASK	CRUMPLED	90.00	90.00
1	FRONT MASK COVERING	CRUMPLED	120.00	90.00
1	FRONT LH SIGNAL LAMP	SCRATCHED	65.00	65.00
1	FRONT RH SIGNAL LAMP	CRUMPLED	65.00	65.00
1	PILOT LIGHT	SERVICEABLE	250.00	-
1	BELLY SHIELD COVERING	SERVICEABLE	90.00	-
1	FRONT SIDE FAIRING LH	SCRATCHED	105.00	105.00
1	FRONT SIDE FAIRING RH	SCRATCHED	105.00	105.00
1	REAR SIDE FAIRING LH	SERVICEABLE	95.00	-
1	REAR SIDE FAIRING RH	SCRATCHED	95.00	95.00
1	REAR LH SIGNAL LAMP	SERVICEABLE	55.00	-
1	REAR RH SIGNAL LAMP	CRUMPLED	55.00	55.00
1	REAR CENTRE COVERING	CRUMPLED	40.00	40.00
1	FRONT FOOTREST BAR	BENT	75.00	75.00
1	FRONT FOOTREST RUBBER	CRUMPLED	45.00	45.00

Report Ref No. CS3/III20010028/Qvf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GEAR PEDAL	SERVICEABLE	50.00	-
1	GEAR PEDAL RUBBER	SERVICEABLE	20.00	-
1	BRAKE PEDAL	SCRATCHED	85.00	85.00
1	EXHAUST PIPE	SERVICEABLE	380.00	-
1	EXHAUST PIPE COVER	SCRATCHED	38.00	38.00
1	REAR FOOTREST RH	SERVICEABLE	75.00	-
	LESS 10% DISCOUNT		-389.30	-254.80
			3,503.70	2,293.20
	<u>SPECIAL NETT ITEMS</u>			
1	NO PLATE (FRONT)(SN)	NECESSARY	35.00	35.00
1	NO PLATE (REAR)(SN)	BENT	35.00	35.00
1	SET CONE BEARING (SN)	NECESSARY	100.00	80.00
1	FRONT CENTRE BASKET (SN)	SERVICEABLE	150.00	-
1	SET STICKER (SN)	NECESSARY	350.00	150.00
			670.00	300.00
	<u>LABOUR</u>			
	TOWING.		120.00	80.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO REALIGN BODY FRAME.		350.00	150.00
	TO R&R FRONT SUSPENSION,HANDLE BAR,HEADLAMP,SIDE FAIRING AND ATTACHMENTS.		400.00	210.00
	TO RESPRAY ON FRONT FENDER,HEADLAMP COWLING,SIDE FAIRING AND ACCIDENT AFFECTED AREA.		500.00	150.00
			1,420.00	620.00
	GRAND TOTAL		5,593.70	3,213.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00

Report Ref No. CS3/III20010028/Qvf3e2-1

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.