

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002173/UGA3Q2
Date: 05/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070122967
Claimant Vehicle No :	GBB8312M	Insured Vehicle No :	GBB7816H
Date of Loss:	09/02/2021	Nature of Claim:	TP
		Claim No:	0117815707SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB8312M		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD Turbo (A)	Engine No:	ZD30213653K
Reg. Date:	26/04/2010 (Man. Year: 2010)	Chassis No:	JN1SC2F24Z0801417
Colour:	Red/White	Odometer:	0 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,448.42	16,613.46	22,834.96	57.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,940.00	4,540.00	2,400.00	34.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,388.42	21,153.46	25,234.96	54.40
Approved Total (Overridden) (S\$)		13,800.00		

(S\$)	46,388.42	13,800.00	32,588.42	70.25
+ GST 7.00/7.00% (S\$)	3,247.19	966.00	2,281.19	70.25
Nett Amount (S\$)	49,635.61	14,766.00	34,869.61	70.25
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021

Estimated Period of Repair: 14.0 days

Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WIPER GARNISH	Distorted	520.00 FN	*441.00 FN
2	1		*SET WIPER GARNISH CLIPS	Necessary	48.00 FN	*32.00 FN
3	1		*FRONT BODY PANEL	Badly Dented	1,100.00 FN	*1,100.00 FN
4	1		*FRONT CENTRE GRILLE	Broken / Missing	500.00 FN	*438.40 FN
5	1		*FRONT CENTRE GRILLE EMBLEM BADGE	Missing	98.00 FN	*48.10 FN
6	1		*SET FRONT CENTRE GRILLE CLIP HOLDER	Missing	48.00 FN	*32.00 FN
7	1		*FRONT CENTRE GRILLE BRACE PANEL	No such part	180.00 FN	*- FN
8	6		*FRONT CENTRE GRILLE CLIPS	Not Necessary	48.00 FN	*- FN
9	2		*HEADLAMP	Cracked	1,370.00 FN	*946.00 FN
10	1		*FRONT BUMPER	Dented	680.00 FN	*680.00 FN
11	1		*DASHBOARD INSTRUMENT REINFORCEMENT	Bent	1,050.00 FN	*675.00 FN
12	1		*RADIATOR ASSY	Punctured	980.00 FN	*980.00 FN
13	1		*RADIATOR FAN COWLING	Cracked	120.00 FN	*120.00 FN
14	1		*RADIATOR FAN BLADE	Broken	160.00 FN	*105.00 FN
15	1		*RADIATOR FAN CLUTCH	Jammed	400.00 FN	*305.00 FN
16	1		*RADIATOR TOP HOSE	Not Necessary	48.00 FN	*- FN
17	1		*RADIATOR BOTTOM HOSE	Not Necessary	48.00 FN	*- FN
18	3		*FRONT BRAKE HOSE	Not Necessary	144.00 FN	*- FN
19	3		*FRONT BRAKE PIPE	Twisted (2 PCS ONLY)	144.00 FN	*96.00 FN
20	1		*FRONT BRAKE PIPE BRACKET	Bent	65.00 FN	*65.00 FN
21	3		*ENGINE MOUNTING	Not Necessary	720.00 FN	*- FN
22	1		*GEARBOX MOUNTING	Not Necessary	240.00 FN	*- FN
23	1		*AIRCON BLOWER ASSY	Cracked	1,050.00 FN	*1,050.00 FN
24	1		*AIRCON HEATER UNIT	Cracked	1,980.00 FN	*1,980.00 FN
25	1		*AIRCON EVAPORATOR	No such part	1,500.00 FN	*- FN
26	1		*AIRCON CONDENSER	Not Necessary	1,050.00 FN	*- FN
27	1		*AIRCON DISCHARGE HOSE	Twisted	320.00 FN	*320.00 FN
28	1		*WIPER PANEL SIDE	N/S Cracked	260.00 FN	*90.00 FN
29	1		*WIPER BLADE (N/S)	Twisted	250.00 FN	*68.00 FN
30	2		*HEATER HOSE (INNER AND OUTER)	Not Necessary	700.00 FN	*- FN
31	2		*WIPER ARM	Not Necessary	380.00 FN	*- FN
32	1		*FRONT CABIN TILE BAR	Bent	550.00 FN	*550.00 FN
33	2		*FRONT CABIN TILE BAR MOUNTING	Twisted	500.00 FN	*500.00 FN
34	2		*FRONT CABIN TILE BAR SIDE COVER	Not Necessary	210.00 FN	*- FN
35	1		*WIPER MOTOR	Not Necessary	650.00 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*WIPER REGULATOR	Not Necessary	190.00 FN	*- FN
37	1		*FRONT WINDSCREEN GLASS	Broken	1,200.00 FN	*991.00 FN
38	1		*FRONT WINDSCREEN GLASS TOP MOULDING	Necessary	170.00 FN	*142.00 FN
39	2		*FRONT WINDSCREEN GLASS SIDE MOULDING	Necessary	210.00 FN	*180.00 FN
40	1		*FRONT WINDSCREEN GLASS LOWER MOULDING	Necessary	140.00 FN	*95.00 FN
41	2		*FRONT CORNER PANEL	Repair	760.00 FN	*- FN
42	1		*HEADLAMP LOWER GARNISH	N/S Cracked	500.00 FN	*35.00 FN
43	1		*N/S SIDE MIRROR SHIELD ASSY	Not Necessary	850.00 FN	*- FN
44	1		*AIRCON CONDENSER BRACKET	Not Necessary	130.00 FN	*- FN
45	1		*AIRCON CONDENSER FAN MOTOR ASSY	Not Necessary	680.00 FN	*- FN
46	1		*O/S A PILLAR -INNER	Repair	180.00 FN	*- FN
47	1		*O/S A PILLAR -OUTER	Repair	180.00 FN	*- FN
48	1		*N/S A PILLAR -INNER	Repair	490.00 FN	*- FN
49	1		*N/S A PILLAR -OUTER	Badly Dented	1,400.00 FN	*1,400.00 FN
50	1		*N/S FRONT DOOR	Repair	1,600.00 FN	*- FN
51	1		*N/S WINDSCREEN PILLAR INNER GARNISH	Not Necessary	180.00 FN	*- FN
52	1		*O/S WINDSCREEN PILLAR INNER GARNISH	Not Necessary	180.00 FN	*- FN
53	1		*DASHBOARD INSTRUMENT CENTRE OUTER PANEL }	Distorted	1,250.00 FN	*1,250.00 FN
54	3		*DASHBOARD CONSOLE BOX }		2,250.00 FN	*- FN
55	1		*AIRCON COOLING COIL	No such part	1,800.00 FN	*- FN
56	1		*AIRCON COOLING COIL CASING	No such part	420.00 FN	*- FN
57	1		*MAIN FUSE BOX	Repair	200.00 FN	*- FN
58	1		*MAIN FUSE BOX OUTER COVER	Not Necessary	105.00 FN	*- FN
59	1		*SUB FUSE BOX CASING (OUTER)	Not Necessary	105.00 FN	*- FN
60	1		*MAIN FUSE WIRE HARNESS	Repair	800.00 FN	*- FN
61	2		*AIRCON CONDENSER BRACKET (INNER)	Not Necessary	300.00 FN	*- FN
62	1		*FLOOR PANEL	Repair	1,600.00 FN	*- FN
63	1		*REAR VIEW MIRROR	Cracked	280.00 FN	*190.00 FN
64	2		*FRONT CABIN REAR B PILLAR	Repair	1,100.00 FN	*- FN
65	1		*FRONT CABIN REAR PANEL	Repair	980.00 FN	*- FN
66	1		*TAILGATE LID	Dented	1,688.00 FN	*1,395.70 FN
67	1		*REAR CARGO CHECK END PANEL	Bent	886.40 FN	*445.00 FN
68	1		*N/S REAR LAMP	Cracked	497.20 FN	*265.00 FN
69	1		*REAR LAMP PANEL	N/S Bent	460.00 FN	*108.00 FN
70	1		*SIDE GATE LID LOCK HANDLE (N/S)	Bent	163.40 FN	*163.40 FN
71	2		*SIDE GATE LID RUBBER STOPPER	Torn	51.60 FN	*51.60 FN
72	1		*N/S CHASSIS FRAME (NPA)	Repair	0.00 FN	*- FN
73	1		*REAR WATER PIPE	Bent	166.20 FN	*166.20 FN
74	2		*FRONT BOTH DOOR COMPANY STICKER	Necessary	100.00 FS	*60.00 FS
75	1		*FRONT LICENCE PLATE	Bent	50.00 FS	*14.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*BLT BRAKE FLUID	Not Necessary	50.00 FS	*- FS
77	1		*BLT RADIATOR COOLANT	Not fitted	30.00 FS	*- FS
78	1		*FRONT WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
79	1		*FRONT WINDSCREEN SEAL	Necessary	120.00 FS	*30.00 FS
80	1		*TAILGATE LID 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
81	1		*SET REVERSE SENSOR	Cracked	250.00 FS	*200.00 FS
82	1		*TAILGATE LID 13 PAX STICKER	Necessary	20.00 FS	*10.00 FS
83	1		*TAILGATE LID COMPANY STICKER	Necessary	250.00 FS	*200.00 FS
84	1		*TAILGATE LID STEP BAR	Bent	450.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	43,673.80	18,363.40
- Nett Item Discount on N Items 10.00/10.00% (S\$)	4,225.38	1,749.94
Total Parts (S\$)	39,448.42	16,613.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	120.00	100.00
2	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PAEALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	300.00	0.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	160.00	20.00
4	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	120.00	0.00
5	TO DISMANTLE AND REFIT INSTRUMENT DASHBOARD ,CHECK ELECTRICAL LIGHTINGS AND RE-RUN ,RE-ROUTE WIRE HARNESS	New	350.00	200.00
6	TO REMOVE AND RENEW ENGINE AND BEARBOX MOUNTINGS	New	150.00	0.00
7	TO DISMANTLE AIR-CON ASSY ,REMOVE AND RENEWAL OF PARTS ,VACUUM AND CHARGE-IN GAS	New	180.00	100.00
8	TOWING CHARGES	New	150.00	50.00
9	TO CONDUCT BRAKE BLEED SYSTEM TEST	New	60.00	0.00
10	TO RUST-PROOFING OF THE AFFECTED AREAS	New	250.00	120.00
11	TO REMOVE AND REFIT FRONT CABIN	New	500.00	250.00
12	TO REMOVE AND REFIT REAR CABIN	New	300.00	300.00
13	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,800.00	2,000.00
14	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,500.00	1,400.00
Gross Labour Cost (\$\$)			6,940.00	4,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >