

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002174/EVD3Q2

Date: 18/03/2021

REFERENCE

Insured/Claimant:	WONG MUI CAN	Policy No:	1800147050	
Date of Loss:	11/02/2021	Nature of Claim:	OD	Claim No: 5367885278SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG9591K		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGJH711501
Reg. Date:	07/01/2019 (Man. Year: 2018)	Chassis No:	KNAF1416MK5021372
Colour:	Grey	Odometer:	22153 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$69,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	NFERA 4 mm	Rear Left Side:	NFERA 4 mm
Front Right Side:	NFERA 4 mm	Rear Right Side:	NFERA 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,020.00	2,626.40	1,393.60	34.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	1,430.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,450.00	4,056.40	1,393.60	25.57
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	4,850.00	3,456.40	1,393.60	28.73
+ GST 7.00/7.00% (S\$)	339.50	241.95	97.55	28.73
Nett Amount (S\$)	5,189.50	3,698.35	1,491.15	28.73

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*COVER -FR BUMPER	Broken	633.00 F	*633.00 FL
3	1		*GRILLE ,FRONT BUMPER	Broken	262.00 F	*262.00 FL
4	1		*GRILLE ASSY- RADIATOR	Not Necessary	223.00 F	*- FL
5	1		*MOULDING -FRONT BUMPER ,RH	Cut	36.00 F	*36.00 FL
6	1		*LAMP ASSY -SIDE REPEATED ,RH	Cut	143.00 F	*143.00 FL
7	1		*AIR DUCT -FR BUMPER ,RH	Necessary	14.00 F	*14.00 FL
8	1		*ABSORBER -FRONT BUMPER ENERGY	Broken	84.00 F	*84.00 FL
9	1		*STIFFNER -FR BPR LWR	Broken	114.00 F	*114.00 FL
10	1		*BRACKET -FR BUMPER UPR SIDE MTG	Not Necessary	22.00 F	*- FL
11	1		*LAMP ASSY -HEAD ,RH	Cut	1,040.00 F	*1,040.00 FL
12	1		*BEAM COMPLETE -FR BUMPER	Not Necessary	497.00 F	*- FL
13	1		*CARRIER ASSY -FRONT END MODULE	Broken	675.00 F	*675.00 FL
14	1		*LAMP ASSY -DAY RUNNING LIGHT ,RH	Cut	203.00 F	*203.00 FL
15	1		*COVER-DAYTIME TUNNING LIGHT,RH (Supplementary)	Cut	12.00 F	*12.00 FL
16	1		*OMAMENT-KIA NO 115 (Supplementary)	Necessary	32.00 F	*32.00 FL
17	10		*CLIPS (Supplementary)	Necessary	10.00 F	*10.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,020.00	3,278.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	651.60
Total Parts (S\$)	4,020.00	2,626.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FRT BUMPER	New	400.00	400.00
2	SPRAY PAINT FOR FRT BUMPER	New	350.00	350.00
3	APPLY RESEAL FRT NUMBER PLATE FROM LTA	New	80.00	80.00
4	FRT NUMBER PLATE	New	50.00	50.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			1,430.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >