



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## General Details

Involving	TPVD Toyota (SLC5920D)
Date of Loss	13 February 2021
Time of Loss	17.20
Loss Description	chain collision: SLL6383A > SHA3180T (INSD) > SLC5920D (TP)
Comment	

## Workshop Details

Total Rebate Amount	31483
Nett Loss Amount	\$24,517.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details



Vehicle Registration#	SLC5920D	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>19/05/2016</div> <div></div>
Mileage	<div>82651</div>	Age of Vehicle	4

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2015</div>
Make	TPVD	<div>TOYOTA</div>
		<div></div>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	TBC	<div></div>
Date of Birth		<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	Toyota POLICY INFORMATION	SIENTA 1.5G A ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="NSP1707013149"/>
Engine No		<input type="text" value="2NR8554447"/>
Engine Capacity		<input type="text" value="1496"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="56000"/>

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

17/02/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="25"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save







SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts













Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		TAILGATE	Dented	0	1600	No		25			1200	Reviewing
<input type="checkbox"/>		0	1		TAILGATE OUTER GARNISH	Damaged	0	385	No		25			288.75	Reviewing
<input type="checkbox"/>		0	1		TAILGATE LOGO	Necessary	0	50	No		25			37.5	Reviewing
<input type="checkbox"/>		0	1		TAILGATE WEATHERSTRIP	Deformed	0	372.3	No		25			279.23	Reviewing
<input type="checkbox"/>		0	2		TAILGATE LAMP	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		ANTENNA BUZZER	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	2		TAILGATE HINGE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	2		TAILGATE DAMPER	Serviceable	0	0	No		25			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		TAILGATE WINDSCREEN MOULDING	Necessary	0	194	No		25			145.5	Reviewing
<input type="checkbox"/>		0	1		TAILLAMP N/S	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TAILLAMP O/S	Cracked	0	689	No		25			516.75	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER SIDE COVER N/S	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER SIDE COVER O/S	Deformed	0	287	No		25			215.25	Reviewing
<input type="checkbox"/>		0	2		REAR BUMPER SIDE REFLECTOR	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	2		REAR BUMPER COVER RETAINER	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER CENTRE PROTECTOR	Deformed	0	400	No		25			300	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER	Cracked	0	1050	No		25			787.5	Reviewing
<input type="checkbox"/>		0	2		REAR BUMPER RETAINER	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	2		REAR BUMPER BRACKET	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		END PANEL	Dented	0	685	No		25			513.75	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		END PANEL TOP GARNISH	Deformed	0	284	No		25			213	Reviewing






Labour


Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	0	800	0	0	Reviewing	
<input type="checkbox"/>		0		TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE, REFIT TAILGATE COMPONENTS TO REPLACE TAILGATE, CHECK AND RE-ADJUST CLOSE GAP, ALIGNMENT AND WATER SEEPAGE	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR WORK	0	120	0	0	Reviewing	
<input type="checkbox"/>		0		SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO AFFECTED AREA / PANEL	0	800	0	0	Reviewing	

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	0	80	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary















Add




Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
<input type="checkbox"/>		0	TAILGATE WINDSCREEN INNER SEAL	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	TAILGATE WINDSCREEN SEALANT	Reviewing		80	NECESSARY	
			TAILGATE					

<input type="checkbox"/>	 EDIT	SR NO	OUTER GARNISH CLIPS (6PCS)	Reviewing ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	NECESSARY COMMENT	 REMOVE
<input type="checkbox"/>		0	TAILGATE LAMP CLIPS (6PCS)	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	TAILGATE TRIMBOARD CLIPS (10PCS)	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	TAILLAMP CLIPS (6PCS)	Reviewing		33	NECESSARY	
<input type="checkbox"/>		0	END PANEL TOP GARNISH CLIPS (6PCS)	Reviewing		33	NECESSARY	
<input type="checkbox"/>		0	END PANEL SEALANT	Reviewing		80	NECESSARY	
<input type="checkbox"/>		0	REAR LICENCE PLATE & FRAME	Reviewing		55	DEFORMED	

	EDIT	SR NO	FRAME NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	REVERSE SENSOR	Reviewing		220	NOT WORKING	
<input type="checkbox"/>		0	REAR BUMPER CLIPS (10PCS)	Reviewing		55	NECESSARY	
<input type="checkbox"/>		0	REAR BUMPER SIDE COVER CLIPS (12PCS)	Reviewing		33	NECESSARY (6PCS ONLY)	
<input type="checkbox"/>		0	SUNDRIES	Deny		0	NOT NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$6,999.23		
CATEGORY	ESTIMATE	ADJUSTED					
Spare Parts	\$0.00	\$4,497.23					
Labour	\$0.00	\$1,880.00					
Miscellaneous	\$0.00	\$622.00					

Submit for Review





SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	5600		

Submit for Review