



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFU 6416M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (CONSISTENT)	DEEP CUT	2,018.00	1,415.00
1	FRONT BUMPER PAD (CONSISTENT)	BROKEN	685.00	435.00
2	FRONT BUMPER CHROME MOULDINGS @\$320.00 (CONSISTENT)	NECESSARY	640.00	450.00
1	FRONT BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	188.00	166.00
1	SET FRONT BUMPER CLIPS & RIVET (CONSISTENT)	NECESSARY	60.00	60.00
1	HEADLAMP O/S (CONSISTENT)	NOT NECESSARY	1,850.00	-
1	FRONT FENDER O/S(CONSISTENT)	TO REPAIR SEE LABOUR	915.00	-
	LESS 10% DISCOUNT		-	-252.60
			6,356.00	2,273.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER PDC SENSOR (6 PCS) (SN) (CONSISTENT)	SHORTED	850.00	300.00
			850.00	300.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REPLACED FRT PDC SENSOR .		80.00	50.00
	TO SPRAY RUST PROOFING .	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S.		600.00	300.00
	TO PUTTY & SPRAY PAINTING .		600.00	580.00
			1,380.00	950.00
	<b>GRAND TOTAL</b>		<b>8,586.00</b>	<b>3,523.40</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,800.00</b>

Report Ref No. CC4/ASM21002179/Ups3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.